MIL-G-82241C
Amendment-2
10 July 1985
SUPERSEDING
Amendment-1
26 April 1983

MILITARY SPECIFICATION

GLOVE INSERTS, RADIOACTIVE CONTAMINANTS PROTECTIVE

This amendment forms a part of Military Specification MIL-G-82241C, dated 17 January 1979, and is approved for use by all Departments and Agencies of the Department of Defense.

Page 1

2.1 - Delete and add the following:

"2.1 Government documents.

2.1.1 Specifications, standards, and handbooks. Unless otherwise specified the following specifications standards and handbooks of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation form a part of this specification to the extent specified."

Under "Specifications, Federal" add the following document -
"NN-P-71 - Pallet, Material Handling, Wood, Stringer Construction 2 Way and 4 Way"

Under "Specifications, Military" add the following document -
"MIL-P-15011 - Pallet Material Handling, Wood Post Construction 4 Way Entry"

Page 2

Under "Standards, Military" - add new standard -
"MIL-STD-147 - Palletized unit loads"

Add new paragraph: "2.3 Order of Precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document shall take precedence."

Page 3

Add new paragraph. "3.3.3. Vulcanization. As an alternate the glove seams may be joined by an injection process using any commercially available latex material and vulcanized in accordance with the time and temperature requirements of the glove manufacturer."

FSC 8415

DISTRIBUTION STATEMENT A - Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:56Z
Check the source to verify that this is the current version before use.

3.4 - Delete paragraph in its entirety and substitute:

"3.4 Design. The gloves shall be a 5-finger silhouette, ambidextrous design, joined by either stitching or vulcanization, as shown in figure 1."

3.5 - At end of paragraph add:

"As an alternate, the contractor's working patterns may exclude the 1/8 inch cut or trim line marked on the Government patterns, but shall remain the same in all other respects."

Page 4

3.6.1 - At end of paragraph add: "(see 3.5)"

3.6.3 - Delete in its entirety and substitute:

"3.6.3 Thread breaks. Thread breaks (all stitch types) shall be secured by stitching back of break not less than 1/2 inch. Skipped stitches or thread breaks (401 stitch types) may be repaired using 301 stitch type."

Page 5

Table II, operation 1, line 4 - add: "(see 3.5)."

Operation 2, delete in its entirety and substitute the following:

"Assemble gloves.

a. Stitch two component parts 1/8 inch from outer edges, except at top opening.

301 or 401	SSa-1	8-12	70/2	70/2

OR

b. Inject latex material between two component parts, 1/8 inch from outer edges, except at top opening.

c. Vulcanize seams in accordance with the time and temperature requirements of the glove manufacturer.

d. There shall be no puckers, pleats or areas of poor adhesion.

NOTE: A 1/8 inch seam allowance shall be trimmed off either during or after joining operation. When contractor's working patterns do not use the cut or trim line, the gauge of joining shall be 1/8 inch from the outer edge."

Operation 4, delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:56Z
Check the source to verify that this is the current version before use.

Page 6

3.8 - At end of paragraph add "All measurements shall be made between stitch or vulcanization lines."

Page 8

4.4.2.1 - SEAMS AND STITCHINGS, delete defects a.2, a.3 and a.4 in their entirety.

Page 9

4.4.2.1 - SEAMS AND STITCHINGS defect a.6, line 1 - delete: "Inseam" and substitute "Seam."

Before "ASSEMBLY DETAIL" add the following: "VULCANIZED SEAMS

a	Any open seam (for any distance)	Major
b.	Pucker, pleat or area of poor adhesion	Major"

ASSEMBLY DETAIL, defect b - delete in its entirety.

Page 10

4.4.3 - At end of paragraph add:

Examine	Defect
Marking (exterior	Omitted, incorrect, illegible, of improper size, location, sequence, or method of application.
Materials	Any component missing, damaged or not as specified
Workmanship	Inadequate application of components such as improper taping, incomplete closure of container flaps, loose strapping, or inadequate stapling. Bulged or distorted container.
Content	Number of bundles per shipping container is more or less than required Number of pairs of gloves per bundle is more or less than specified. 1/

1/ For this defect, one bundle shall be examined from each shipping container in the sample.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:56Z
Check the source to verify that this is the current version before use.

Add new paragraph:

4.4.4 Palletization examination. An examination shall be made to determine that the palletization complies with the section 5 requirements. Defects shall be scored in accordance with the list below. The sample unit shall be one palletized unit load fully packaged. The lot size shall be the number of palletized unit loads in the end item inspection lot. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirements.
Palletization	Pallet pattern not as specified. Interlocking of loads not as specified. Load not bonded with required straps as specified
Weight	Exceeds maximum load limits.
Marking	Omitted, incorrect, illegible, of improper size location, sequence or method of application.

5.2.1, line 3 - Delete "grade V2s, size 1" and substitute "type CF, size 1A, variety DW, grade V15c".

line 4 - Following "MIL-B-17757." add "The liner will be type CF, class domestic in accordance with the requirements specified in MIL-B-17757."

5.2.2, line 3 - Delete "size 1" and substitute "size 1A, variety DW, type CF."

Following "MIL-B-17757." add "The liner will be type CF, class domestic. in accordance with the requirements specified in MIL-B-17757."

Add new paragraph

5.2.4 Palletization. When specified (see 6.2), glove inserts, packed as specified in 5.2 shall be palletized on a 4-way entry pallet in accordance with load type IA of MIL-STD-147. Each prepared load shall be banded with primary and secondary straps in accordance with the banding means (C, K and L) or O or P. Pallet patterns shall be in accordance with the appendix of MIL-STD-147. The pallet shall be 4-way, Type III. Class 1 Style A Size 2, wood group I, Grade A of NN-P-71, or 4-way, Style (1, 1A or 1B), Size A, Type I Class 1 of MIL-P-15011. Interlocking of loads shall be effected by reversing the pattern of each course. If the container is of a size which does not conform to any of the patterns specified in MIL-STD-147 the pallet pattern used shall first be approved by the contracting officer.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:56Z
Check the source to verify that this is the current version before use.

Page 11

5.2.2.1 - Delete in its entirety.

6.2 - Delete "d" in its entirety and add the following

"d. When first article inspection is required, the item will be tested and should be a first article sample. The Contracting Officer should include specific instructions in acquisition documents regarding arrangement for examinations, quantity and testing and approval

e When palletization is required (see 5.2.4)."

Page 12

Figure - delete and substitute new Figure 1.

Custodian:
Navy - NU
Air Force - 99

Review Activities:
Navy - SH, MC
Air Force - 82
DLA - CT

User Activities
Navy - AS, OS

Preparing Activity:
Navy - NU

Project No. 8415-0456

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:56Z
Check the source to verify that this is the current version before use.




FIGURE 1. Glove Inserts, Radioactive Contaminants Protective

U.S. GOVERNMENT PRINTING OFFICE: 1985 — 505-038/23257

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:56Z
Check the source to verify that this is the current version before use.