MILITARY SPECIFICATION

PROBE AND S&A ASSEMBLY, TOW-2/E6

This Amendment forms a part of Military Specification MIL-W-48698 (AR) dated 27 April 1987 and is approved for use within the US Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1.1 Between MIL-STD-105 and DOD-STD-2000, add the following:

"MIL-STD-1169 Packaging, Packing and Marking for Shipment of Inert Ammunition Components"

PAGE 3

3.6, Line 3: Delete "is".

PAGE 4

3.18, Lines 2 and 6: Delete "0.5 ohms" and substitute "1.0 ohms".

PAGE 6

4.3.2, Line 4: Delete "byu" and substitute "by".

PAGE 42

4.4.2.31, Minor 208: Delete "3.2" and substitute "3.23".

PAGE 50

4.4.2.35, Minor 211: Delete "3.2" and substitute "3.23".

PAGE 53

4.4.2.37, Minor 206: Delete "3.2" and substitute "3.23".

AMSC N/A FSC 1336

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.
Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.

PAGE 77

4.4.2.60:

Next Higher Assembly: Delete "9398046" and substitute "9388046".

Add new paragraph 4.4.2.61 included.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.61	Mechanism Assembly				9388005
					NEXT HIGHER ASSEMBLY 9387141
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined				
MAJOR					
101	Leaf spring in proper position		100%	3.2	Visual
102	Presence of shoulder washers		100%	3.2	Visual
103	Presence of piston actuator spacer		100%	3.2	Visual
MINOR					
201	Workmanship		1.00%	3.23	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.

PAGE 82

4.5.2, After last sentence add: "(See 6.8)."

4.5.3, After last sentence add: "(See 6.8)."

PAGE 90

4.5.14.2.a, After the first sentence add the following:

"This test shall be conducted prior to continuity circuit tests described 4.5.15 (Table V). The test circuit shall not exceed 40 microamperes."

TABLE IV Delete in its entirety and substitute the following:

"TABLE IV - Open circuit tests

TEST	Resistance ≥ 1.0 megohm FROM (+)	TO (-)
1. Detonator switch *	red cable	inner tip
2. Tip switch	inner tip	black cable
3. Ogive switch	base contact	ogive (or rivet)

* WARNING: If Test 1 fails STOP immediately. The S&A is unsafe and should be removed from the lot and disposed of."

4.5.15.2.a, Line 2: Delete "40 microamperes" and substitute "2 milliamperes".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.

Table V, Column 3: Delete "0.5 ohms" and substitute "1.0 ohms".

5. Delete in its entirety and substitute the following:

"5. PACKAGING

5.1 Preservation and packing. The probe and its associated components shall be preserved and packaged in accordance with MIL-STD-1169.

5.2 Packing. Packing of the probe and its associated components shall be in accordance with MIL-STD-1169.

5.3 Marking. Marking shall be in accordance with MIL-STD-1169.

5.4 Shipping. The probe and its associated components shall be shipped in the stowed condition in accordance with notes 16 and 17 of Dwg. 9387141."

PAGE 93

Add the following:

"6.8 Tip assembly. Upon insertion of the inert charge assembly, inner tip assembly, and crush ring, apply tip assembly to the probe with 30 ± 1 in-lb torque and cure at ambient for 24 hours before commencing first article or lot quality confirmation testing."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1336-A566)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:37Z
Check the source to verify that this is the current version before use.