INCH-POUND

MIL-S-63326 (AR)
AMENDMENT 6
27 December 1994
SUPERSEDING
AMENDMENT 5
17 April 1989

# MILITARY SPECIFICATION

## SAFETY AND ARMING ASSEMBLIES FOR MINES: BLU 91/B AND BLU 92/B

This amendment forms a part of MIL-S-63326 (AR), dated 11 August 1981, and is approved for use by the U.S. Army Armaments Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1, Specification, Federal: Delete "QQ-S-465" and substitute "QQ-S-365".

PAGE 2

2.1, Issues of documents:

Specifications, Military: Delete "MIL-S-63457 - Soldering, ...and Electronic Equipment" in its entirety.

Standards, Military: Add the following Military Standard:

"MIL-STD-2000 - Standard Requirements for Soldered Electrical and Electronic Assemblies".

PAGE 4

3.6.1, Under Temperature:

Delete "+70° + 10°F" and substitute "+70°F ± 10°F (Ambient)".

Delete "140° + 5°F" and substitute "+145°F + 5°F".



AMSC N/A FSC 1345

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 4 (Cont'd)

3.6.2:

Delete "partucular" and substitute "particular".

Under Temperature:

Delete "+70° + 10°F" and substitute "Ambient".

Delete "+140° + 5°F" and substitute "+145°F + 5°F".

3.8: Delete "... than 0.015 ohm." and substitute ". . than 0.15 ohm.".

PAGE 8

TABLE I: S&A Assembly and Components: Delete "Microminature" and substitute "Microminiature".

PAGE 11

TABLE I, S&A Assembly, Examination for Defects: Delete "4.4.2.45(a)" and substitute "4.4.2.47(a)".

Note (a): Delete "4.4.2.41, 4.4.2.43, been performed" and substitute "4.4.2.41, 4.4.2.43 and 4.4.2.45 have been performed".

Note (b): Delete "70° ± 10°F" and substitute "Ambient".

PAGE 12

Note (a): Delete "4.4.2.42 and 4.4.2.41 been performed" and substitute "4.4.2.41, 4.4.2.42 and 4.4.2.44 have been performed".

Note (b): Delete "70° ± 10°F" and substitute "Ambient".

PAGE 16

4.4.2.2, Borerider:

Add the following Major Category:

"122 Chamfer on tines missing ...0.40% ...3.2 ...Visual".

PAGE 17

4.4.2.3, Spring Borerider:

Minor 201: Delete "3.10" and substitute "3.2".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 18

4.4.2.4, Interlock, Assembly :

Major 101: Delete in its entirety.

Major 201: Delete “3.2” and substitute “3.10”.

PAGE 19

4.5.2.5, Pin, Interlock:

Minor 203: Delete in its entirety and substitute “Chamfers missing ...0.65% ...3.2 ...Visual".

PAGE 21

4.4.2.7, Cup, Interlock:

Ada the following Major Category:

“109 Hardness test ...0.40% ...3.2 ...ASTM E-18".

Minor 203: Delete “3.2” and substitute "3.1O".

PAGE 22

4.4.2.8, Slider Assembly:

Major 102: Delete “Gage” and substitute “Visual”.

Major 103: Delete “Gage” and substitute “Visual”.

Major 104: Delete in its entirety.

Major 106: After staked add “(-1 assy only)”.

PAGE 23

4.4.2.9, Cup Slider:

Major 114: Delete “Depth of notch” and substitute “Length from notch to tabs”.

PAGE 31

4.4.2.15, Flexible Cable Assembly:

* Major 106: Delete “Visual, MIL-S-45743" and substitute “Visual, MIL-STD-2000".

Major 107: Delete "Gage" and substitute "Visual".



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 32

4.4.2.16, Flexible Cable Assembly:

* Major 105: Delete "Visual, MIL-S-45743" and substitute "Visual, MIL-STD-2000".

Major 106: Delete "Gage" and substitute "Visual".

PAGE 33

4.4.2.17, Cable Flexible:

Major 107: Delete "Soldering poor or incorrect" and substitute "Solder coating poor or incorrect".

Add the following Major Category:

"115 Solderability ...10-0-1 ...3.2 ...Visual".

PAGE 34

4.4.2.16, Clip Ground:

Note a: Delete "Accept D" and substitute "Accept 0".

PAGE 35

4.4.2.19, Actuator, Microminiature Piston:

Piston actuator function test: Delete "-60°" and substitute "-65°F".

Major 103: Delete "4.5.6.3" and substitute "4.5.3.3".

Major 104: Delete "4.5.6.3" and substitute "4.5.3.3".

Major 105: Delete "4.5.6.3" and substitute "4.5.3.3".

Major 106: Delete "4.5.6.1" and substitute "4.5.3.1".

Major 108: Delete "4.5.6.2" and substitute "4.5.3.2".

Minor 201: Delete "3.2" and substitute "3.10".

PAGE 36

4.4.2.20, MDF Assembly:

Major 107: Delete "4.5.8.2" and substitute "4.5.4.2".

Minor 201: Delete "3.2" and substitute "3.10".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 39

4.4.2.23, MDF, PBXN-5 Lead Sheathead:

Major 102: Delete “4.5.10” and substitute “4.5.6”.

PAGE 40

4.4.2.24, Lower Housing Assembly:

Next Higher Assembly: Delete “932869,3/9328743” and substitute "9328692/9328743” .

Minor 201: Delete “3.2” and substitute "3.10".

PAGE 41

4.4.2.25, Housing, Lower, Sheet 1 of 4:

Major 106: Delete “(See E-E)” and substitute "(See G-G)".

Major 107: Delete "(See E-E)" and substitute "(See G-G)".

Number of sample units column: Delete “*”.

NOTE : Delete in its entirety.

PAGE 42

4.4.2.25, Housing, Lower, Sheet 2 of 4:

Major 120: Delete in its entirety.

Major 121: Delete in its entirety.

Major 125: Add “, 2 places” after “hole”.

Major 128: Add “, 2 places” after “hole”.

Major 129: Add “, 2 places” after “hole”.

Major 130: Delete "well" and substitute “wells (detonator and delay detonator)."

Major 131: Add “, 2 places” after “hole”.

Major 138: Delete “(a) - 3.2 4.5.4” and substitute "1/ ...3.2 ...4.5.1"

Add the following note:

"1/ Sampling and rejection shall be in accordance with MIL-P-12879".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 43

4.4.2.25, Housing, Lower, Sheet 3 of 4:

Note a: Delete in its entirety.

PAGE 44

4.4.2.25, Housing, Lower, Sheet 4 of 4:

Major 167: Delete in its entirety.

Add Major 175: "Location of interlock assembly notch ...0.40% ...3.2 ...Gage".

Add Major 176: "Width of interlock assembly notch ...0.40% ...3.2 ...Gage".

Minor 202: Delete in its entirety.

Minor 204: Delete "... notch incorrect" and substitute "...notch missing or incorrect".

PAGE 45

4.4.2.26, Upper Housing Assembly:

Minor 201: Delete "3.2" and substitute "3.10".

PAGE 46

4.4.2.27, Housing, Upper, Sheet 1 of 5:

Major 114: Delete "(Sec T-T, Sht. 3)" and substitute "(Sec T-T, Sht. 6)".

PAGE 47

4.4.2.27, Housing, Upper, Sheet 2 of 5:

Major 127: Delete "...cap counter bore, 2 places (Sht. 2)" and substitute "... cap flash hole, 2 places (Sht. 2)".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 48

4.4.2.27, Housing, Upper, Sheet 3 of 5:

Major 142: Delete "4.5 5.4" and substitute "4.5.1".

Major 143: Delete "(See S-3, Sht. 6)" and substitute "(See S-S, Sht. 6).

Major 144: Delete in its entirety.

Major 149: Delete "Distance . . section" and substitute "Distance from center of slider release pin cavity semicircular section to centerline of datum -A-".

PAGE 55

4.4.2.32, Pin, Shear Borerider:

Add the following Major Category:

"104 Head thickness ...0.40% ...3.2 ...Gage".

PAGE 58

4.4.2.35, Cup, Centrifugal Lock:

Drawing Number: Delete "9328819" and substitute "9329819".

PAGE 59

4.4.2.36, MDF Spacer:

Major 102: Delete "profile of side" and substitute "Profile incorrect".

Major 103: Delete in its entirety.

Major 104: Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 60

4.4.2.37, Spacer Actuator:

Major 106: Delete “Diameter of cavity (See A-A) “ and substitute “Depth of diameter located to DATUM A (See A-A)”.

Minor 202: Delete "3.10” and substitute “3.2”.

Minor 203: Delete in its entirety.

PAGE 61

4.4.2.38, Shield:

Minor 201: Delete “Gage” and substitute “Visual”.

PAGE 63a

* 4.4.2.40.1, Add new paragraph as follows:

“4.4.2.40.1: Classification of Defects and Tests for Packing and Marking for Box, Fiberboard for Safety and Arming Assembly, Drawing Number 12937950.”



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

# CLASSIFICATION OF CHARACTERISTICS

| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| . | Packing and Marking for Box, Fiberboard for Safety and Arming Assembly | 1 OF 1 | 12937990 |
| | | | NEXT HIGHER ASSEMBLY |

| CLASSIFICATION | EXAMINATION OR TEST | CONFORMANCE CRITERIA | REQUIREMENT PARAGRAPH | INSPECTION METHOD REFERENCE |
|---|---|---|---|---|
| Critical | None defined | | | |
| Major | | | | |
| 101 | S&A Cable, MDF are improperly secured in the tray | 0.40% | 3.2 | Visual |
| 102 | Desiccant missing or mislocated | 0.40% | 3.2 | Visual |
| 103 | Lid missing or improper | 0.40% | 3.2 | Visual |
| 104 | Barrier bag not properly sealed | 0.40% | 3.2 | Visual |
| 105 | Marking improper | 0.40% | 3.2 | Visual |
| Minor | | | | |
| 201 | Poor workmanship | 0.65% | 3.10 | Visual |

NOTES





Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 64

4.4.2.41, Safe & Arm Assembly (Prior to Assembling Borerider Shear Pin and Lock Plate):

Critical category:

Critical 1: Delete "1/ in its entirety.

Critical 2: Add "1/" after “binding”.

Major category:

Major 102: Delete “...missing ...0.40% ...3.2 ...Visual/ Manual” and substitute “...missing 1/ ...100% ...3-2 Visual/Manual”.

Notes:

Add the following note:

"1/ Major 102 shall be performed prior to critical 2".

PAGE 65

4.4.2.42, Safe & Arm Assembly:

Major 103: Delete "100%" and substitute “0.40%”.

PAGE 66

4.4.2.43, Safe & Arm Assembly (prior to Assembling Shield and Lock Plate).

Critical category: Delete "none defined" and add new Critical defect as follows:

"1 - Ball lock missing ...100% ...3.2 ...Gage".

Major 104: Delete “0.40%” and substitute "l00%".

PAGE 67

4.4.2.44, Critical 1: Delete "Eyelet ground open circuit, detonator..." and substitute “Ground circuit open, detonator...".

PAGE 68

4.4.2.45, Critical 1: Delete "Eyelet ground open circuit, detonators...” and substitute “Ground circuit open, detonators...”.



Source: https://assist.dla.mil -- Downloaded: 2026l0-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 69

4.4.2.46, Safe and Arm Assembly:

LAT of S&A ASSEMBLIES, NO. OF SAMPLE UNITS column: Delete "*".

Transportation vibration, INSPECTION METHOD column: Delete “4.5.15.3” and substitute “4.5.11.3”.

Continuity - Resistance checks, REQUIREMENT column: Delete “3.8” and substitute “3.2”.

Arming, INSPECTION METHOD column: Delete “4.5.17” and substitute “4.5.13” .

Main charge functioning: Add "2/" after “functioning”.

SAMPLE SIZE column: Add "1/" after “SIZE”.

+70° + 5°F column: Delete “+70° + 5°F” and substitute "AMBIENT".

PAGE 70

4.4.2.47, Safe & Arm Assembly:

LAT of S&A ASSEMBLIES, NO. OF SAMPLE UNITS column: Delete "*".

Transportation vibration, INSPECTION METHOD column: Delete "4.5.15.3" and substitute "4.5.11.3".

Continuity - Resistance checks, REQUIREMENT column: Delete "3.8" and substitute "3.2".

Main charge functioning: Add "2/" after “functioning” .

SAMPLE SIZE column: Add "1/" after "SIZE".

+70° + 5°F column: Delete "+70° + 5°F" and substitute "AMBIENT".

MDF functioning: Delete “4.5.14” and substitute “4.5.14.1”.

Delay detonator, delay time: Delete “4.5.14” and substitute “4.5.14.2”.

Main charge functioning: Delete “4.5.14” and substitute “4.5.14.2”.



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 73

4.5.9: Delete "Assemblies subjected to this test shall not be returned to the lot."

PAGE 74

4.5.14.2: Main charge lead explosive train functioning:

Delete "... The witness ring shall be 1-3/16 in I.D. x 1-1/2 in long x 3 in. O.D., cold drawn..." and substitute "...The witness ring shall be 1 3/16 in I.D. x 3/4 in. long minimum x 2 1/2 in O.D. minimum, cold drawn...".

PAGE 75

4.5.18: Delete “4.5.18” and substitute “4.5.17”.

PAGE 76

* 5.1 Preservation, packaging and marking:

Delete "...in accordance with drawing 9329606" and substitute "...in accordance with drawing 9329606 or alternate packing drawing 12937990".

5.2 Packing and marking:

Delete "...in accordance with drawing 9329607” and substitute "...in accordance with drawing 9329607 or alternate packing drawing 12937990”.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in this notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-0011)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.