MIL-T-60164(MU)
AMENDMENT 2
1 July 1969
SUPERSEDING
AMENDMENT 1
17 May 1968

MILITARY SPECIFICATION

TAPE, FAN FOLDED

This amendment forms a part of Military Specification MIL-T-60164(MU) dated 29 May 1967.

Paragraph 2.2: Add "Standard T456-OS-68 Tensile Strength Retention".

Paragraph 3.2.2 Lamination: Delete paragraph.

* Paragraph 3.3.2: Delete in its entirety and substitute new 3.3.2.

"3.3.2 Solubility.- The tape weight shall change no more than ±1.0 percent for carbon tetrachloride, ±2.0 percent for water, ±2.0 percent for ethyl alcohol, ±1.0 percent for gasoline and ±12.0 percent for motor oil."

* Paragraph 3.3.6 Opacity: Change "95%" to "98%".

Paragraph 3.3.7: Delete in its entirety and substitute new 3.3.7.

"3.3.7 Internal tear resistance.- Tape shall have a minimum internal tear resistance of 60 grams, machine direction; 65 grams cross direction."

* Paragraph 3.3.9 Tensile strength: Change "15 pounds" to "18 pounds".

* Add the following new paragraph 3.3.9.1.

"3.3.9.1 Tensile strength retention (wet).- The tape shall have a minimum tensile strength retention of 15% at the fold."

* Paragraph 3.3.10 Crease retention: Change "75%" to "85%".

* Paragraph 3.3.11 Tape width: Change tolerance "±.007" to "±.005".

* Paragraph 3.3.18 Weight: Change "1.4 pounds" to "1.6 pounds".

* Add new paragraph 3.3.19.

"3.3.19 Handling properties.- The tape shall exhibit no more than slight smudging following immersion for 30 seconds in any of the following reagents: Carbon Tetrachloride (Technical Grade), Water, Ethyl Alcohol (2B - 95%), Gasoline and Motor Oil (Slight smudging is defined as barely perceptible under normal lighting)."

FSC 1220

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:13Z
Check the source to verify that this is the current version before use.

* Paragraph 3.4: Delete in its entirety and substitute new 3.4.

"3.4 Moisture resistance.- The tape shall show no evidence of damage nor exceed the tape width and length by 2%, and thickness by 15% due to absorption or drying out of moisture after exposure to the RH conditions specified in 3.6.2. Absorbency shall not have potential of causing hardness when subjected to the low temperatures specified in 3.6.1."

* Paragraph 3.7.2 Folding endurance.- Change "1500 double folds" to "300 double folds".

Add the following paragraphs in proper sequence:

"4.1.1 First article (initial production) approval.- The requirement for first article approval and the responsibility (Government or contractor) for first article testing shall be as specified in the contract. The sample for first article approval tests shall consist of three (3) tapes manufactured in the same manner using the same materials, equipment, processes, and procedures as used in regular production. All parts and materials, including packaging and packing, shall be obtained from the same source of supply as used in regular production.

4.1.1.1 Government testing.- When the Government is responsible for conducting first article approval tests, the contractor, prior to submitting the sample to the Government, shall inspect the sample to insure that it conforms to all the requirements of the contract and submit a record of this inspection with the sample, including certificates of conformance for materials.

4.1.1.2 Contractor testing.- When the contractor is responsible for conducting first article approval tests, the sample shall be inspected by the contractor for all the requirements of the contract. The sample and a record of this inspection, including certificates of conformance for materials, shall be submitted to the Government for approval. The Government reserves the right to witness the contractor's inspection."

* In Table II: Delete:

"302.	Lamination	3.2.2	4.5.3(b), 4.5.5 & 4.5.6"

* Table IV: Add to the respective columns the following:

"319.	Tensile strength retention	3.3.9.1	4.5.2.8.1
320.	Handling properties	3.3.19	4.5.2.18

Paragraph 4.5.2.5, next to last line: Change "5%" to "10%".

Source: https://assist.dla.mil -- Downloaded: 202610-23T00:13Z
Check the source to verify that this is the current version before use.

* Add the following new paragraphs 4.5.2.8.1, 4.5.2.18 and 4.5.2.18(a).

"4.5.2.8.1 Tensile strength retention (wet).- The tape shall be immersed in water for one minute then tested as specified in Tappi, Procedure T-456-OS-68. The tensile strength retention shall be within the limit specified in 3.3.9.1.

4.5.2.18 Handling properties test procedures.- Place 200 ML of each reagent specified in 3.3.19 into the 5 separate beakers. Cut several strips of tape into 8" lengths. Place a paper towel in a manner that the folds are facing upward. Immerse one end of the strip into one of the reagents so that the strip touches the bottom of the beaker. Keep tape immersed for 30 seconds. Remove the strip and place between the folds of the paper towel so that a layer of towel will be in contact with both sides of the wet end of strip. Place 1KG weight on top of towel and withdraw strip from between the weighted towel layers. Visually inspect towel for evidence of smudging. Repeat test in each beakered reagent with new tape strip. Allowable smudging shall be as specified in 3.3.19.

4.5.2.18(a) Handling properties.- The following test equipment shall be utilized for handling properties tests of 4.5.2.18:

1. Five (5) 250 ML Glass Beakers
2. One (1) LKG Brass Balance Weight
3. One (1) suitable timer or stop watch capable of measuring seconds
4. Suitable cutting instrument
5. Scott "C-Fold" paper towels - brand 150
6. Reagents as specified in 3.3.19"

* Paragraph 4.5.8 Folding endurance.- Delete "1500" and substitute "300".

*The outside margins have been marked to indicate where changes to the previous amendment have been made. This has been done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in this notation. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content as written irrespective of the marginal notation and relationship to the last previous amendment.

Custodian:

Army - MU

Preparing activity:

Army - MU

Project No. 1220-A223

Source: https://assist.dla.mil -- Downloaded: 202640-23T00:13Z
Check the source to verify that this is the current version before use.