MIL-B-63094B(AR)
Amendment 3
18 March 1980
SUPERSEDING
Amendment 2
5 July 1979

MILITARY SPECIFICATION

BLASTING MACHINE, 50 CAP, M34

This Amendment forms a part of Military Specification MIL-B-63094B(AR), dated 24 July 1978.

PAGE 3

Delete paragraph 3.3 in its entirety and substitute with:

"3.3 Output capacity. The blasting machine shall produce a minimum output of one and five tenths (1.5) amperes Root Mean Square (RMS) for a period of zero (0) to one and five tenths (1.5) milliseconds when tested as specified in 4.5.1."

Delete paragraph 3.4 in its entirety and substitute with:

"3.4 Drop test. The blasting machine shall comply with the requirmments of 3.3 when subjected to a five (5) foot drop onto a concrete surface."

PAGE 6

Table I - First Article Inspection under Sleeve, Rotor delete, "(Dwg. 9232516)" and substitute with, "(Dwg. 9235516)".

PAGE 11

Table I - First Article Inspection under Tests delete,

"Drop test/10 (c)/3.4/4.5.2
Transportation vibration/20 (f)/3.6/4.5.4
Waterproofness/5 (f)/3.5/4.5.3.1
Service life cycle/5 (g)/3.7/4.5.5"

FSC: 1375

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:11Z
Check the source to verify that this is the current version before use.

and substitute with:

"Drop test/10 (e)/3.4/4.5.2
Transporation vibration/10 (f)/3.6/4.5.4
Humidity/10 (f)/3.11/4.5.9
Waterproofness/5 (f)/3.5/4.5.3.1"

PAGE 12

Table I - First Article Inspection delete, "Humidity/10 (f)/3.11/ 4.5.9" and substitute with, "Service life cycle/5 (g)/3.7/4.5.5".

Table I - First Article Inspection under Housing Electrical delete, "(Dwg. 9235541)" and substitute with, "(Dwg. 9328279)".

PAGE 16

Paragraph 4.4.2.1 - In Next Higher Assembly Block delete, "9235509" and substitute with, "9328276".

PAGE 17

Paragraph 4.4.2.2 - In Next Higher Assembly Block delete, "9235509" and substitute with, "9328276".

PAGE 24

Paragraph 4.4.2.9 - In Next Higher Assembly Block delete, "9235523" and substitute with, "9328725".

PAGE 33

Paragraph 4.4.2.18 - Delete this paragraph in its entirety.

PAGE 42

Paragraph 4.4.2.27 - In Next Higher Assembly Block delete, "9312773" and substitute with, "9328276".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:11Z
Check the source to verify that this is the current version before use.

PAGE 44

*"Major 110 Insulation resistance,"add "100%" to AQL column.

PAGE 45

Paragraph 4.4.2.30 - In Drawing Number Block delete, "9235541" and substitute with, "9328279". In Next Higher Assembly Block delete, "9235509" and substitute with, "9328276".

PAGE 49

Paragraph 4.4.2.33 - In Next Higher Assembly Block delete, "9235504" and substitute with, "9312773".

PAGE 55

Paragraph 4.4.5 - In the second line from the end of this page, delete the period between the words "selected" and "after" and change the "A" in "after" to "a".

PAGE 57

Delete paragraph 4.5.2 in its entirety and substitute with:

"4.5.2 Drop test. Five blasting machines shall be conditioned at minus forty-five degrees centigrate minus five degrees centigrade (-45° - 5°C) and another five at fifty-two degrees centigrade plus five degrees centigrade (52°C + 5°C) for a period of twenty-four hours plus one hour (24 hrs + 1 hr). The machine shall then be dropped once, a vertical distance of five feet (5 ft) onto a solid concrete surface, with the following orientations at each temperature:

Temp	Connector end down	Connector end up	Handle down	Handle up	Pivoted Handle corner down
-45°C	Unit #1	Unit #2	Unit #3	Unit #4	Unit #5
$+52^{\circ}$C	Unit #6	Unit #7	Unit #8	Unit #9	Unit #10

The blasting machine shall then be tested in accordance with the test methods of 4.5.1 for output capacity except that it shall indicate a successful firing three (3) sequential times. If the device fails to comply with all of the specified requirements it shall be classed defective. (Destructive Test)

Source: https://quest.ida.mil -- Downloaded: 2026-10-23T02:11Z
Check the source to verify that this is the current version before use.

PAGE 62

*a. Delete paragraph 5.1.2 in its entirety.

b. Delete paragraph 5.2.2 in its entirety and substitute with the following:

"5.2.2 Level B. 100 Blasting Machines shall be packed as in 5.2.1 except replace the wooden box with a fiberboard box, Type CF, Class Domestic, Grade 350, Spec PPP-B-631. Use commercial chipboard as fillers instead of MIL-F-50449. Close and seal the box in accordance with the requirements of the Appendix of PPP-B-636.

PAGE 63

Paragraph 5.3 delete "5.5.15.8.1 through 5.5.15.8.4" and substitute with "5.4.21 and 5.4.22".

The margins of this amendment are marked with an asterisk to indicate where changes from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationships to the last previous amendment.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No: 1385-A149

Source: https://assist.dla.mil - Downloaded: 2026-10-23T02:11Z
Check the source to verify that this is the current version before use.