MILITARY SPECIFICATION

CARTRIDGE, 105MM, HE, ROCKET ASSISTED, XM548, DELAY ASSEMBLY FOR

This amendment forms a part of Military Sepcification MIL-C-60458 (MU), dated 27 October 1967, and is approved for use by the US Army Armament Research and Development Command, Department of the Army and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Add the following preamble underneath the title:

"This specification is approved by the U.S. Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense."

Delete "XM548" and substitute "XM548E1" wherever referenced in specification.

2.1: Specifications

Military: Delete "MIL-C-13739 - Composition Delay."

Standards: Add "MIL-STD-1234" as follows: "MIL-STD-1234 - Pyrotechnics: Sampling, Inspection and Testing."

PAGE 2

3.3.3:

Line 1: Delete "Moisture Content" in both places and substitute "total volatiles."

Line 3: Delete "0.05 percent" and substitute "0.1 percent."

FSC: 1315

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:37Z
Check the source to verify that this is the current version before use.

PAGE 3

3.4.2.2: Delete last sentence and substitute the following:

"The average delay time shall be 19.5 seconds plus or minus 1.5 seconds and the standard deviation shall be no greater than 1.25 seconds."

PAGE 7

4.3.2.1: Major Category:

Major Defect 103: Delete in its entirety and substitute the following:

"103. Diameter of two holes at threaded end...Gage 01003."

Major Defect 106: Delete in its entirety and substitute as follows:

"106. Depth of two holes at threaded end...Gage 01006."

Minor Category:

Minor Defect 206: Delete in its entirety and substitute the following:

"206. True position of two holes at threaded end...Gage 01014."

Minor Defect 218: Delete in its entirety.

Minor Defect 221: Delete in its entirety and substitute the following:

"221. Surface finish of 2 holes at threaded end improper ...Gage 01029."

Add Minor Defects 223 and 224 as follows:

"223. Diameter of two pilot holes at end containing counterbore...Gage 01031."

"224. True position of two pilot holes at end containing counterbore...Gage 01032."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:37Z
Check the source to verify that this is the current version before use.

PAGE 8

4.3.2.3: Change Minor Defect 201 as follows:

"201. Flash composition not removed from sidewall ...Visual 03001."

PAGE 9

4.3.2.5: Delete Major Defect 102 in its entirety and substitute the following:

"Major 100% Inspection

102. Pyrotechnic Composition in evidence on surface "X" ...Visual 05004."

Add new paragraph 4.3.2.6 as follows:

"4.3.2.6 Sealed Barrier Bag (See Improvised Packing No. 57/69)

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major	AQL 0.40 percent		
101.	Seal improper or incomplete.	Visual	10001
102.	Bag, punctured, torn or cut.	Visual	10002
Minor: None defined."			

PAGE 10

4.3.3.4.2.1:

Line 1: Delete "Seven loaded delays" and substitute "Twenty loaded delays."

Add the following sentence:

"A minimum of fifteen (15) delay assemblies at this temperature shall be recorded on radar to be used in calculating the average and standard deviation of the lot."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:37Z
Check the source to verify that this is the current version before use.

4.3.3.4.2.2:

Line 1: Delete "Seven loaded delays" and substitute "Twenty loaded delays."

Add the following sentence:

"A minimum of fifteen (15) delay assemblies at this temperature shall be recorded on radar to be used in calculating the average and standard deviation of the lot."

PAGE 11

Add new paragraph 4.3.3.6 as follows:

"4.3.3.6 Determination of average particle size.

4.3.3.6.1 Molybdenum Trioxide-Major defect - Code No. 09002. - A sample shall be selected from each lot of molybdenum trioxide and tested in accordance with MIL-STD-1234. If the sample fails to meet the requirements of drawing 9212470 for particle size the lots shall be rejected. The tests shall be conducted in accordance with 4.4.4.1.

4.3.3.6.2 Chromium Oxide - Major defect - Code No. 09003 -A sample shall be selected from each lot of chromium oxide and tested in accordance with MIL-STD-1234. If the sample fails to meet the requirements of drawing 9212469 for particle size the lot shall be rejected. The test shall be conducted in accordance with 4.4.4.2."

PAGE 12

4.4.1.2.2, line 2: Delete "4.4.2.1" and substitute "4.4.1.2.1."

4.4.2: Delete first sentence and substitute the following:

"After conditioning at 140°F for 12 hours minimum, the delay assembly shall be assembled to the required test equipment specified on the applicable equipment list."

4.4.3: Delete in its entirety and substitute the following:

"4.4.3 Determination of Moisture. The moisture content of the flash, delay, and igniter composition shall be determined in accordance with Method 102.1 of MIL-STD-1234."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:37Z
Check the source to verify that this is the current version before use.

Add new paragraph 4.4.4 as follows:

"4.4.4 Particle size

4.4.4.1 Particle size (molybdenum trioxide). This test shall be conducted in accordance with MIL-STD-1234, method 202.1.

4.4.4.2 Particle size (Chromium oxide). This test shall be conducted in accordance with MIL-STD-1234, method 202.1."

Add new paragraph 6.7 as follows:

"6.7 Handling of Delay Assemblies. Precaution should be taken during loading, subsequent to loading and prior to packing to insure delay assemblies are not exposed to conditions which would adversely affect their moisture content."

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No. 1315-A440

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:37Z
Check the source to verify that this is the current version before use.