MILITARY SPECIFICATION
ADAPTION KIT, ATOMIC WARHEAD TO GUIDED MISSILE, TRAINING: M246 (TYPE W)

1. SCOPE

1.1 This specification covers requirements, quality assurance provisions, and the preparation for delivery criteria for one type of Adaption Kit, Atomic Warhead to Guided Missile Training M246 (Type W) used to train troops in the classroom.

2. APPLICABLE DOCUMENTS

2.1 The following documents, of the issue in effect on date of invitation for bids or request for proposals, form a part of this specification to the extent specified herein:

SPECIFICATIONS

MILITARY

MIL-C-48521	- Cable Assembly, Special Purpose, Electrical: W47U Through W55U and W65U and W72U.
MIL-S-48525	- Shipping and Storage Container, Warhead Section: M511.
MIL-T-48527	- Test Set, Atomic Weapon: T-4186.

STANDARDS

MILITARY

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-810	- Environmental Test Methods.

DRAWINGS

ORDNANCE CORPS

8879606 - Cable Subassembly.
8878895 - Arm Safe Device Training: M106.
8879347 - Thermal Battery Training: M21.
8879348 - Thermal Battery Training: M23.
8879349 - Acceleration Switch Training: M56.
8879887 - Quick Access Door Assembly.

FSC - 1135

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

8879990 - Parameter Setting Door Assembly.
9212631 - Impact Fuze, Training: M1144.
9293494 - Packing and Marking for Shipping and Storage Container for Lance, Adaption Kit, Training, Type W, M246.
9236944 - Combined Option Selector Switch Assembly, M171.
9236945 - Sequential Timer, Training: M43.
9236993 - Adaption Kit Atomic AW to Guided Missile, Training: M246.
9236994 - Adaption Kit Subassembly, AW Training: M247 (Type W).
9237031 - Control Adaption Kit Training.
9237035 - Housing "A" Section Modified.
9237036 - Case Assembly "A" Section.
9237037 - Fuze Impact Assembly.
9237038 - Plate.
9237042 - Mounting Plate Assembly.
9237044 - Case Assembly "C" Section Modified.
9237045 - Case Assembly "D" Section Modified.
9237046 - AK, AW to GM, Training: M246 (Marking).
9237060 - Housing Assembly, Training.
9237206 - Case Assembly, "C" Section Training.
9237223 - Base Assembly, Training (Arm-Safe Device: M106).
10988759 - Altitude Fuze Training: M1145 (Type W).
ET-9236993 - Equipment Tabulation.

(Copies of specifications, standards, drawings, and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Assembly. The adaption kit (type W) shall comply with all requirements specified on drawing (dwg) 9236993, with all requirements specified herein, and with the requirements of all applicable specifications to the extent specified on the drawing and herein.

3.2 First article testing. Requirements for the submission of first article samples by the supplier shall be as specified in the contract (see 4.2).

3.3 Serialization. The supplier shall assign serial numbers as required by drawings.

3.4 Continuity. The continuity loop of the assembled training adaption kit (Type W) shall be verified by utilizing the T4186 Test Set connected to the 1A1J1 Connector. Continuity checkout of major subassemblies shall be performed

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

by utilizing the test set connected to the 1J13 Connector. Testing is to be conducted in accordance with 4.4.1.

3.5 Quick access door assembly. The quick access door assembly (dwg 8879887) shall be tested in accordance with 4.4.2.

3.6 Parameter setting door assembly. The parameter setting door assembly (dwg 8879990) shall be tested in accordance with 4.4.3.

3.7 Weight. The total weight of the adaption kit (Type W) shall be 212.5 + 5.0/ -10.0 lbs when tested in accordance with 4.4.4.

3.8 Center of gravity. The center of gravity location for the adaption kit (Type W) shall be at station 61.05 ± 0.75 when tested in accordance with 4.4.4.

3.9 Components. For components to be used in the Adaption Kit Training (M246), objective evidence (see 6.2) indicating that the following components conform to their respective specifications and/or drawings shall be made available to the Government representative:

a. Cable Assembly, Special Purpose, Electrical: W47U Through W55U and W65U and W72U, MIL-C-48521.
b. Shipping and Storage Container Warhead Section M511, MIL-S-48525.
c. Test Set, Atomic Weapon: T4186, MIL-T-48527.

3.10 Workmanship.

3.10.1 Plastic and metal characteristics. All components shall be free from cracks, splits, cold flow, shrinkage, cold shuts, inclusions, porosity, or any similar characteristic.

3.10.2 Threads. Threads shall be full and undamaged for the entire minimum length or depth as required on the applicable drawing.

3.10.3 Burrs. Parts shall be free from burrs.

3.10.4 Foreign matter. Parts shall be free from chips, dirt, grease, rust, corrosion, or any embedded foreign material.

3.10.5 Cleaning. The cleaning method shall not be injurious to any of the parts, nor shall the parts be contaminated by the cleaning agent.

3.10.6 Electrical. Cable assemblies and wires shall be dressed in such a manner as to prevent pinching or chafing of the wire insulation. Ends of wires shall be free from burrs, sharp edges, or points. All parts shall be free from flux, chips, dirt, grease, rust or foreign material.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.2 First article inspection.

4.2.1 Quantity to be submitted. When the contract requires first article inspection, the contractor shall submit 1 complete assembly (see dwg 9236993) for first article testing to the testing facility designated in the invitation for bids or request for proposal.

4.2.2 Inspection and testing to be performed. The first article inspection sample shall be subjected to the inspections and tests specified in Table I. Tests shall be conducted in order specified in Table I.

Table I
First article inspection or tests

Inspection or Test	Dest	Non Dest
1. Classification of characteristics (see 4.3.2.1)		X
2. Quick access door assembly operating (see 3.5)		X
3. Parameter setting door assembly operation (see 3.6)		X
4. Continuity (see 3.4)		X
5. Weight (see 3.7)		X
6. Center of gravity (see 3.8)		X

4.2.3 Inspection equipment. The inspection and testing specified in 4.2.2 shall be accomplished by using the gages and test equipment specified in 4.3.4.1.

4.2.4 Rejection. If any item fails to comply with any of the applicable requirements, the first article sample shall be rejected.

4.3 Quality conformance inspection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

4.3.1 Inspection lot formation. All items in each inspection lot shall be from one production line, one shift, one batch of products, one manufacturer of raw material or components, one production method or manufacturing operation. The entire lot shall be submitted as a unit for inspection.

4.3.2 Product inspection examination. A sample shall be selected at random from each inspection lot in accordance with the applicable major or minor characteristic table (see Table II and Table III), and inspected for all characteristics in the applicable classification. Any characteristics in the sample found to be defective shall reject the inspection lot. Sequence for the inspection of characteristics in each classification need not be followed as long as all characteristic inspections are performed.

Table II
Major Characteristics

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-16	all	28-29	23	52-56	31	132-156	39
17	16	30-31	24	57-62	32	157-191	40
18	17	32-34	25	63-69	33	192-244	41
19-20	18	35-36	26	70-76	34	245-334	42
21	19	37-40	27	77-86	35	335-519	43
22-23	20	41-43	28	87-97	36	520-1120	44
24-25	21	44-47	29	98-112	37	over 1120	45
26-27	22	48-51	30	113-131	38		

Table III
Minor Characteristics

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-9	all	14-16	12	28-33	16	77-121	20
10	9	17-18	13	34-41	17	122-273	21
11	10	19-22	14	42-54	18	over 273	22
12-13	11	23-27	15	55-76	19		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

4.3.2.1 Classification of characteristics (see 3.1). Critical, major and minor characteristics are defined in MIL-STD-105. Inspection shall be conducted as follows:

4.3.2.1.1 Acceleration switch, training: M56 (see dwg 8879349).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Mounting holes (4) missing	Visual
	102. Solid rivet in place	Visual
	103. Alignment pin hole missing	Visual
	104. Correct connector for cable subassembly (see 8879606)	Visual
	105. Incorrect identification plate	Visual
	106. Improper color	Visual
	107. Workmanship (see 3.10)	Visual
Minor:	None defined.	

4.3.2.1.2 Arm safe device training: M106 (see dwg 8878895).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Mounting holes (4) missing	Visual
	102. Incorrect number of pins and keyway orientation for connector end (9237223)	Visual
	103. Incorrect identification plate	Visual
	104. Workmanship (see 3.10)	Visual
	105. Improper color	Visual
Minor:	None defined.	

4.3.2.1.3 Thermal battery training: M23 (see dwg 8879348).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Mounting holes missing	Visual
	102. Spring pin missing	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

103. Alignment hole missing.....Visual
104. Incorrect identification plate.....Visual
105. Workmanship (see 3.10).....Visual
106. Improper color.....Visual

Minor: None defined.

4.3.2.1.4 Thermal battery training: M21 (see dwg 8879347).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Mounting holes missing.....Visual
102. Spring pin missing.....Visual
103. Alignment hole missing.....Visual
104. Incorrect identification plate.....Visual
105. Workmanship (see 3.10).....Visual
106. Improper color.....Visual

Minor: None defined.

4.3.2.1.5 Impact fuze, training: M1144 (see dwg 9212631).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Inability to assemble threaded end with mating part.....Manual
102. Inability to assemble connector receptacle to its mating connector.....Manual
103. Incorrect identification plate.....Visual
104. Workmanship (see 3.10).....Visual
105. Improper color.....Visual

Minor: None defined.

4.3.2.1.6 Combined option selector switch assembly, training: M171 (see dwg 9236944).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

Major:
101. Mounting holes (4) missing.....Visual
102. Spring pin missing.....Visual
103. Alignment hole missing.....Visual
104. Failure of electrical receptacles (2) to fit with mating connector...Manual
105. Incorrect identification plate.....Visual
106. Workmanship (see 3.10).....Visual
107. Improper color.....Visual

Minor: None defined.

4.3.2.1.7 Sequential timer, training: M43 (see dwg 9236945).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Mounting holes (8) missing.....Visual
102. Spring pins (2) missing (see 9237060).....Visual
103. Alignment holes (2) missing (see 9237060).....Visual
104. Failure of electrical receptacle to fit with mating connector.....Manual
105. Workmanship (see 3.10).....Visual
106. Incorrect identification plate.....Visual
107. Improper color.....Visual

Minor: None defined.

4.3.2.1.8 Housing "A" section modified (see dwg 9237035).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Spring pin holes (2) missing.....Visual
102. Workmanship (see 3.10).....Visual
103. Improper color.....Visual

Minor: None defined.

4.3.2.1.9 Case assembly "A" section (see dwg 9237036).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

Major:
101. Spring pins (2) missing.....Visual
102. Workmanship (see 3.10).....Visual
103. Impact fuzes, missing or loose.....Visual/Manual

Minor: None defined.

4.3.2.1.10 Fuze, impact assembly (see dwg 9237037).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Bolt holes (4) missing.....Visual
102. Workmanship (see 3.10).....Visual
103. Lockwire missing.....Visual

Minor: None defined.

4.3.2.1.11 Plate (see dwg 9237038).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Alignment holes missing (2).....Visual
102. Bolt holes (4) missing.....Visual
103. Fuze mounting holes (2) missing....Visual
104. Workmanship (see 3.10).....Visual
105. Improper color.....Visual

Minor: None defined.

4.3.2.1.12 Control, adaption kit training (see dwg 9237031).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:
101. Component alignment holes (16) missing.....Visual
102. Improper mating of connectors.....Manual
103. Plate mounting holes(6) missing....Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

104. Any inserts missing (45) (see dwg 9237042).....Visual
105. Spring pins (8) missing (see dwg 9237042).....Visual
106. Protective caps on connectors missing.....Visual
107. Stenciling, improper, missing, or illegible.....Visual
108. Sealing disc missing.....Visual
109. Workmanship (see 3.10).....Visual
110. Improper color.....Visual

Minor: None defined.

4.3.2.1.13 Adaption kit subassembly, AW training: M247 (Type W) (see dwg 9236994).

Categories	Characteristics	Method of Inspection
Critical: None defined.		
Major:		
101.	Incorrect torques	Gage
102.	Components missing, damaged, loose or improper	Visual
103.	Incorrect identification plate	Visual
104.	Workmanship (see 3.10)	Visual
105.	Color improper	Visual
Minor: None defined.		

4.3.2.1.14 Case assembly "C" section modified (see dwg 9237044).

Categories	Characteristics	Method of Inspection
Critical: None defined.		
Major:		
101.	Forward alignment pin hole missing	Visual
102.	Forward spring pin missing	Visual
103.	Aft end spring pin missing	Visual
104.	Alignment pin hole, aft end, missing	Visual
105.	Mounting holes (18) at station 61.375 missing	Visual
106.	Alignment pin (1) at station 61.375 missing	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

107. Alignment pin hole at station 61.375 missing.....Visual
108. Existing spring pins removed (2) (see dwg 9237206).....Visual
109. Existing spring pin holes (2) missing (see dwg 9237206).....Visual
110. Markings missing, illegible, or improper.....Visual
111. Workmanship (see 3.10).....Visual
112. Improper color.....Visual

Minor: None defined.

4.3.2.1.15 Case assembly "D" section modified (see dwg 9237045).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Forward alignment pin missing	Visual
	102. Forward alignment pin hole missing	Visual
	103. Doors and covers in place	Visual
	104. "T" bolts (4) missing	Visual
	105. Station 100 alignment pins missing (2)	Visual
	106. Station 100 shear pins (6) missing	Visual
	107. Mounting holes at station 85 missing	Visual
	108. Workmanship (see 3.10)	Visual
Minor:	None defined.	

4.3.2.1.16 Altitude fuze training: M1145 (Type W) (see dwg 10988759).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
	101. Aft pin spring missing	Visual
	102. Aft alignment holes (2) missing	Visual
	103. Improper connectors	Manual
	104. Forward pin spring missing	Visual
	105. Forward alignment hole missing	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

106. Identification plate improper or missing.....Visual
107. Component missing, damaged, loose or improper.....Visual
108. Improper color.....Visual
109. Workmanship (see 3.10).....Visual

Minor: None defined.

4.3.2.1.17 Adaption kit, AW, to guided missile training: (Type W) M246 (see dwg 9236993).

Categories	Characteristics	Method of Inspection

Critical: None defined.

Major:

101. Any component missing, damaged, loose or improper.....Visual/Manual
102. Identification marking missing, incorrect or illegible (see 9237046).....Visual
103. Incorrect torque for AK subassembly (6 places).....Gage
104. Incorrect torque for strap assembly harness (11 places).....Gage
105. Incorrect torque, case assembly "C" section to case assembly "D" section (20 places).....Gage
106. Incorrect torque for impact fuze (2 places).....Gage
107. Incorrect torque altitude fuze to case assembly "C" section (8 places).....Gage
108. Incorrect torque "A" section to altitude fuze (6 places).....Gage
109. Any hardware missing or loose.....Visual
110. Protective finish missing, exposing base metal.....Visual
111. Workmanship (see 3.10).....Visual
112. Station 100 connector missing or loose.....Visual/Manual
113. Improper color.....Visual
114. Yellow flag and connector assemblies (2) loose or missing....Manual/Visual
115. Lettering on yellow flags (2) incorrect or illegible (both sides).....Visual
116. 1.00 inch dia. white emergency destruction dots (3) missing (see 9237046).....Visual

Minor: None defined.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

4.3.2.1.18 Packing for adaption kit assembly (Type W) in M511 shipping and storage container prior to closing cover (see dwg 9293494).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
101.	Adaption kit ablative material and protective finish damaged	Visual
102.	Adaption kit component and hardware loose or missing	Visual
103.	Adaption kit guide pins not properly engaged in station 100 support plate	Visual
104.	Incorrect torque at station 100 swing bolts at support plate (4 places)	Gage
105.	Lower strap liner for lower strap cushion missing or incorrect, permitting strap cushion to come in contact with AK	Visual
106.	Upper strap liner missing, allowing upper strap cushion to come in contact with AK	Visual
107.	Incorrect torque for securing upper strap assembly over AK	Gage
108.	Protective cover assembly torque incorrect	Gage
109.	A2P2 connection of W53U cable not mated to A2J2 connector on skin of adaption kit	Visual
110.	Incorrect torque for humidity indicator	Gage
111.	Incorrect torque for valves (2)	Gage
112.	Incorrect torque for W53U cable	Gage
113.	Dessicant insufficient	Visual
114.	Tee handle wrench missing	Visual
115.	Gasket nicked, cut, or damaged to the extent of rendering it unusable	Visual
116.	Marked mailing bags with contents missing or improper in storage box	Visual
117.	Hardware in bottom assembly container incorrectly torqued (see table)	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

118. PAL cover not installed on rear of support plate in container.....Visual
119. Workmanship (see 3.10).....Visual

Minor: None defined.

4.3.2.1.19 Packing for adaption kit assembly in M511 shipping and storage container after closing of cover (see dwg 9293494).

Categories	Characteristics	Method of Inspection
Critical: None defined.		
Major:		
101.	Flange bolts torque incorrect (22).....	Gage
102.	All external hardware on exterior of container torque incorrect (see table).....	Gage
103.	Contents incorrect or missing in Records Container Assembly.....	Visual
104.	Lead wire seals missing (9) required.....	Visual
105.	Records container cover loose, missing, unserviceable, gasket missing, unserviceable.....	Visual
106.	H4244 wrench(es) unserviceable, missing (2 required). EML missing, mutilated.....	Visual/Manual
107.	Markings illegible or do not agree with dwg 9293494 and EML.....	Visual
108.	Structural damage which will preclude use of container for intended purpose.....	Visual
109.	Paint peeling, scratched, inadequate coverage, wrong color.....	Visual
110.	Hardware missing unserviceable, loose.....	Visual/Manual
111.	Pressure equalizing valves loose, unserviceable.....	Visual/Manual
112.	Humidity indicator card reads 30 percent or more.....	Visual
113.	Humidity indicator assembly loose, unserviceable.....	Visual/Manual
114.	Quick access cover loose, damaged, unserviceable.....	Visual/Manual
115.	Presence of corrosion, fungus, and other foreign material.....	Visual
116.	External PAL connector cover missing or unserviceable.....	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

117. Lift bars and handles cracked, broken or loose.....Visual
118. Lift handle clips unserviceable or missing.....Visual
119. Fork lift bars missing, loose or damaged.....Visual
120. Stacking bolt holes, skid guides on cover and grooves on skids missing or incorrectly located.....Visual
121. Dessicant access cover loose, unserviceable.....Visual/Manual
122. Wooden runner (skid) unserviceable. Splits more than 3" long regardless of depth.....Visual/Gage
123. Identification plate missing, NSN Ser No., Contract No., nomenclature, date of manufacturing, missing or illegible....Visual

Minor: None defined.

4.3.2.1.20 Preparation for delivery (see 5).

Categories	Characteristics	Method of Inspection
Critical:	None defined.	
Major:		
101.	Preservation, packaging and packing not in accordance with dwg 9293494	Visual
102.	Marking not in accordance with dwg 9293494	Visual
Minor:		
201.	Evidence of poor workmanship (see 3.10)	Visual

4.3.3 Testing. All tests shall be performed. Tests shall be performed in the order specified below:

	Test	Test Classification
a.	Continuity	Major
b.	Quick access door assembly	Major
c.	Parameter setting door assembly	Major
d.	Weight	Major
e.	Center of gravity	Major

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

None of these tests are considered destructive and samples so tested may be returned to the lot.

4.3.3.1 Continuity, quick access door assembly, parameter setting door assembly and center of gravity. Each adaption kit shall be tested in accordance with 4.4.1, 4.4.2, 4.4.3 and 4.4.4. If any item fails to comply with 3.4, 3.5, 3.6 and 3.8, the item shall be rejected and removed from the lot.

4.3.3.2 Weight. The first two adaption kits produced shall be tested in accordance with 4.4.4. If any item fails to comply with 3.7, the item shall be rejected and removed from the lot.

4.3.4 Acceptance inspection equipment.

4.3.4.1 Major characteristics and tests. Inspection and testing shall be performed with the acceptance inspection equipment, operating instructions and calibration instructions specified on the Equipment Lists (EL). Els for assemblies are listed on the Equipment Tabulation, ET-9236993. When either of the conditions listed below exist, the contractor shall design required equipment or specify suitable commercial equipment and obtain approval prior to use on the contract.

a. Any deviation from equipment or procedures specified on the EL is desired (see 6.3).
b. The code "CD" is listed in the "Part or Identifying Number" column on the EL (see 6.1.2).

4.3.4.2 Minor characteristics and tests. The acceptance inspection equipment, operating instructions and calibration instructions used by the contractor for minor classification inspection shall be approved by the Government representative authorized by the procuring agency.

4.4 Test methods. The tolerances specified herein are absolute with no allowance for test equipment inaccuracy. The tolerances used by the manufacturer shall be equal to the absolute tolerances less the accuracy tolerances of the test equipment used.

4.4.1 Continuity (see 3.4). The continuity loop of the assembled adaption kit (Type W) with a simulated training warhead installed, shall be verified by utilizing the T4186 Test Set connected to the 1A1J1 Connector. Continuity check-out of major subassemblies shall be performed by utilizing the test set connected to the 1J13 Connector. Testing is to be performed in accordance with the following test procedures.

a. Adaption kit

1. Open the test set and remove W70U cable.
2. Connect the W70UP1 cable connector to the J1 test set connector and the W70UP2 connector to the J2 connector.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

3. Rotate the rotary switch to position 1.
4. Turn the hand crank generator and check for illumination of the red No Go lamp light. If the light fails to illuminate, reject the test set for maintenance.
5. Rotate the rotary switch to position number 2.
6. Turn the hand crank generator and check for illumination of the green GO lamp light. If the light fails to illuminate, reject the test set for maintenance.
7. Remove the W70UP2 connector from the test set J2 connector and connect it to the 1A1J1 adaption kit connector, located at station 100.
8. Certify that the rotary switch is located in position number 2. Rotate the hand crank generator. If the adaption kit is proper, the green GO lamp will light.

b. Major subassemblies

1. Connect the W71UP1 cable connector to the J1 test set connector and the W71UP3 to the J3 connector.
2. Rotate the rotary switch between positions 2 and 18. Stop at each position and rotate the hand crank generator. If the GO lamp light fails to illuminate, or the No Go lamp light illuminates, reject the test set for maintenance.
3. Remove the W71UP3 connector from the test set J3 connector and connect it to the 1J13 adaption kit connector, located at station 94.
4. Verify the condition of the adaption kit components by turning the hand crank generator to insure the green GO lamp lights between positions 2 and 18. Stop at each position and rotate the hand crank generator. If the GO or the No Go lamp light illuminates, the test set is functioning correctly. However, if no light is visible, rotate the rotary switch on the test set to position number 1. Turning of the hand crank generator should illuminate the red No Go lamp light, thereby, confirming that the continuity loop is defective.

4.4.2 Quick access door assembly. The quick access door assembly shall be capable of being operated and removed by pushing the button per marking and rotating the handle one quarter turn counterclockwise. Reinstallation is to be accomplished by observing the alignment marking during emplacement, rotating the handle one quarter turn in the reverse direction and reinstalling the handle into its storage cavity.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

4.4.3 Parameter setting door assembly. The parameter setting door assembly shall be capable of being operated and removed by rotating the center socket one quarter turn in the direction of the marking arrow. This is to be accomplished by utilizing the tee handle wrench (P/N 9237287) stored within the M511 shipping and storage containers. Reinstallation is to be accomplished by observing the alignment markings during emplacements, rotating the center socket one quarter turn in the opposite direction until the alignment marks for the center socket coincide.

4.4.4 Weight and center of gravity. The weight and center of gravity of each adaption kit (Type W) shall be measured using suitable equipment and fixtures.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging. Preservation and packaging shall be level A or C as specified (see 6.1).

5.1.1 Level A. The adaption kit (Type W) shall be packaged in accordance with dwg 9293494 using the specified moisture barrier.

5.1.2 Level C. The adaption kit (Type W) shall be packaged in accordance with dwg 9293494 except that the moisture barrier may be omitted.

5.2 Packing.

5.2.1 Level A and C. The adaption kit shall be packed in accordance with dwg 9293494.

5.3 Marking. Marking shall be as specified in accordance with dwg 9293494.

6. NOTES

6.1 Ordering data. Procurement documents should specify the following:

6.1.1 Procurement requirements.

a. Title, number, and date of this specification.
b. Selection of applicable level of packaging and packing required (see 5.1 and 5.2).

6.1.2 Contract data requirements (see 4.3.4.1). Data specified in 4.3.4.1 will be delivered as identified on a numbered DD Form 1664 when required on a DD Form 1423 incorporated in the contract.

6.2 Objective evidence. Records of contractor quality control and inspections which can be verified.

6.3 Acceptance inspection equipment (see 4.3.4.1). The contractor shall obtain approval from the Commander, Picatinny Arsenal, Dover, New Jersey 07801, ATTN: SARPA-QA-T.

6.4 Supersession data. This specification supersedes the requirements of Purchase Description PA-PD-1208A dated 10 October 1972, with Amendment 5 dated 16 July 1974.

Custodian:
Army - PA

Preparing activity:
Army - PA

Project No. 1135-A231

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?
   A. GIVE PARAGRAPH NUMBER AND WORDING.

   B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

   ☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 66 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T04:04Z
Check the source to verify that this is the current version before use.