NOTICE OF INACTIVE
FOR NEW DESIGN

NOT MEASUREMENT SENSITIVE

MIL-PRF-63003B(TM)
NOTICE 1
30 July 2007

PERFORMANCE SPECIFICATION

MANUALS, TECHNICAL: BATTLEFIELD DAMAGE ASSESSMENT AND REPAIR, PREPARATION OF

MIL-PRF-63003B(TM) including Amendment 1, dated 15 November 2001, and any subsequent revisions or change notices are inactive for new design and shall be no longer used to acquire technical manuals for new systems.

New systems should use MIL-STD-40051-1 with change 2 entitled "DOD Standard Practice, Preparation of Technical Information for Interactive Electronic Technical Manuals (IETMs)" and MIL-STD-40051-2 with change 2 entitled "DOD Standard Practice, Preparation of Technical Information for Page-Based Technical Manuals", to acquire technical manuals. CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

Custodians:

Army - TM

Preparing Activity:

Army - TM

Review Activities:

Army - AR, AT, AV, CR, MI

Project Number:

TMSS 2007-007

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change , you should verify the currency of the information above using the ASSIST Online database at http://assist.daps.dla.mil.

AMSC N/A

AREA TMSS

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:53Z
Check the source to verify that this is the current version before use.