MIL-C-46695B (AR)
2 June 1981
SUPERSEDING
MIL-C-46695A (MU)
25 April 1967

MILITARY SPECIFICATION

CHARGE, PROPELLING, 8 INCH, M2 (WHITE BAG) LOADING, ASSEMBLING AND PACKING

This specification is approved for use by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of propelling charge designated as Charge, Propelling M2, for 8 inch Howitzer.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-223	-Black Powder
MIL-A-48078	-Ammunition, Standard Quality Assurance Provisions, General Specification For

☆ U.S. GOVERNMENT PRINTING OFFICE: 1981—703-023/4557

FSC: 1320

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-414	-	Sampling Procedures and Tables for Inspection by Variables for Percent Defective
MIL-STD-1235	-	Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes

DRAWINGS

ARRADCOM

8861374	-Charge, Propelling, 8 Inch: M2, For 8 Inch Howitzer, M2
7548187	-Packing and Marking of Metal Containers For Propelling Charges and details.

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with applicable drawings and specifications.

3.2 Propelling charge. The propelling charge shall comply with all requirements specified on Drawing (dwg.) 8861374 and with all requirements specified in applicable specifications.

3.3 Moisture content of black powder. The moisture content of the black powder at the igniter loading shall not exceed the amount specified in MIL-P-223, when tested as specified in 4.5.2.1.

3.4 Weights

3.4.1 Propellant weight. The net weight of the propellant shall comply with the weights specified in the loading authorization within the following tolerance:

Source: https://assist.dla.mil -- Downloaded: 202610-22T06:42Z
Check the source to verify that this is the current version before use.

Increment Number	Tolerance Plus or Minus (+) ounces
5	.30
6	.10
7	.10

3.4.2 Charge, propelling assembly weight. The charge propelling assembly weight shall not differ by more than + 1.0 ounces from the total of the amount specified in the loading authorization, plus average or actual weights of the empty increment bag and loaded igniter assembly (see 6.7).

3.5 Dimensional Gage

3.5.1 Maximum length and Diameter. The completed charge shall freely enter the prescribed gage. The gage shall be designed to inspect the maximum diameter and length.

3.6 Proving Ground. The muzzle velocity, pressure and velocity standard deviation at 70°F shall be as specified in Table I.

Table I

Zone	Velocity (fps) Minimum	Velocity (fps) Maximum	Std Dev (fps)	Individual Max Press (psi)
7	1900	2000	6.5	42,000

3.7 Plug Assembly Torque. The packing container test plug shall be assembled to withstand subsequent reapplication of the minimum assembly torque specified on the applicable drawing, without moving. (see 6.8).

3.8 First Article Inspection. This specification contains technical provisions for the submission of the First Article inspection. Requirements for the submission of First Article samples by the contractor shall be as specified in the contract.

3.9 Workmanship. All components shall be free of dirt, grease and other foreign material. There shall be no discoloration or deterioration of cloth and no evidence of rips, tears, or other cloth defects. All work shall be performed in a thorough workmanlike manner.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection.

4.3.1 Submission. The contractor shall submit a first article sample from the initial production lot as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. This sample shall consist of the following:

Description	Drawing	Quantity
Igniter Assembly	8861369	5
Base, Increment	8861370	5
Igniter and base Loading Assembly	8861371	5
Igniter, Inner	8861367	5
Igniter, Outer	8861368	5
Body Increment	8861372	5
Increment Loading Assembly	8861373	5
End	8861365	5
Strap, Tying	8861366	5
Charge, propelling, 8 inch, M2, for 8 inch How. M2 (in sealed containers)	8861374/ 7548187	10

4.3.2 Inspections to be performed. The First Article parts submitted in accordance with paragraph 4.3.1 will be subjected by the Government to any or all the requirements of the applicable drawings and specifications and to the inspections of Table II. All inspections listed in Table II shall be classified Major unless otherwise specified in referenced paragraphs and specifications.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 202610-22T06:42Z
Check the source to verify that this is the current version before use.

TABLE II - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER / NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Propelling Charge Components and Assemblies				
	Igniter Assembly (Dwg 8861369)	5		3.2	4.4.2.1
	Base, Increment (Dwg 8861370)	5		3.2	4.4.2.2
	Igniter and Base Loading Assesmbly (Dwg 8861371)	5		3.2	4.4.2.3
	Igniter, Inner (Dwg 8861367)	5		3.2	4.4.2.4
	Igniter, Outer (Dwg 8861368)	5		3..2	4.4.2.5

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

TABLE II - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
	CONTINUTATION SHEET				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Body, Increment (Dwg 8861372)	5		3.2	4.4.2.6
	Increment Loading Assembly (Dwg 8861373)	5		3.2	4.4.2.7
	End (Dwg 8861365)	5		3.2	4.4.2.8
	Strap, Tying (Dwg 8861366)	5		3.2	4.4.2.9
	Charge, Propelling, 8 Inch M2, for 8 Inch How M2 (in sealed containers) (Dwg 8861374/7548187)	10		3.2	4.4.2.10/4.4.2.11/ 4.4.2.12

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

4.4 Quality Conformance Inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of propelling charge assemblies shall contain:

a. Propellant from not more than one lot number from one manufacturer.

b. Black powder from not more than one interfix number from one manufacturer.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46695B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.	Igniter Assembly		8861369
			NEXT HIGHER ASSEMBLY 8861371

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper		0.40%	3.2	See 4.5.4
102	Diameter of seam		0.40%	3.2	gage
103	Any seam incompletely stitched		0.40%	3.2	visual/manual
104	Quilting missing or improper		0.40%	3.2	visual
Minor					
201	Marking not visible after sewing		0.65%	3.2	visual
202	Evidence of poor workmaship		0.65%	3.9	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46695B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.2	Base, Increment		8861370
			NEXT HIGHER ASSEMBLY
			8861371

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper		0.40%	3.2	see 4.5.4
102	Seam improper or incompletely stitched		0.40%	3.2	visual
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	visual
202	Evidence of poor workmanship		0.65%	3.9	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil-- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.3	Igniter and Base Loading Assembly		8861371
			NEXT HIGHER ASSEMBLY 8861374

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Igniter charge assembly missing		100%	3.2	visual
2	Assembly damaged or improper to the extent that black powder can escape (prior to propellant loading)		100%	3.2	visual/manual
Major					
101	Assembly damaged to the extent that propellant can escape (including any seam or opening incompletely stitched, or broken threads)		0.4%	3.2	visual/manual
102	Weight of propellant		(a)	3.4	4.5.1
103	Tying straps missing, insecure or improperly assembled		0.4%	3.2	visual/manual

NOTES:

a The frequency of inspection of weight of propellant shall be depended on the method used. see 4.5.1

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.3	CONTINUATION SHEET				8661371
					NEXT HIGHER ASSEMBLY 8661374
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
104	Black powder weight		100%	3.2	4.5.2.2
105	Moisture content of black powder		(a)	3.3	4.5.2.1
Minor					
201	Evidence of poor workmanship		0.65%	3.9	visual

NOTES: (a) One sample from every eight hours production of igniter and base loading assemblies

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8861367
4.4.2.4	Igniter, Inner				NEXT HIGHER ASSEMBLY 8861369
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper		0.40%	3.2	see 4.5.4
Minor 201	Diameter		0.65%	3.2	gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 20260-22106:422
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8861368
4.4.2.5	Igniter, Outer				NEXT HIGHER ASSEMBLY 8861369
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper		0.40%	3.2	see 4.5.4
Minor 201	Diameter		0.65%	3.2	gage
202	Marking missing, misleading or unidentifiable		0.65%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil/ Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8861372
4.4.2.6	Body, Increment				NEXT HIGHER ASSEMBLY 8861373
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper		0.40%	3.2	see 4.5.4
102	Any seam incompletely stitched		0.40%	3.2	visual
Minor					
201	Marking missing, misleading or unidentifiable		0.65%	3.2	visual
202	Evidence of poor workmanship		0.65%	3.9	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8861373
4.4.2.7	Increment Loading Assembly				NEXT HIGHER ASSEMBLY 8861374
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Assembly damaged to the extent that propellant can escape including any seam or opening incompletely stitched and broken threads		0.4%	3.2	visual/manual
102	Weight of propellant		(a)	3.4	see 4.5.1
Minor					
201	Evidence of poor workmanship		0.65%	3.9	visual

NOTES:

a The frequency of inspection of weight of propellant shall be depended on the method used. see 4.5.1.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.8	End		8861365
			NEXT HIGHER ASSEMBLY
			8861371/8861373

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor 10 201	Diameter of end		0.65%	3.2	gage

NOTES:

DRLAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 20260-22106:422
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Strap, Tying				8861366
					NEXT HIGHER ASSEMBLY
					8861371
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper		0.40%	3.2	see 4.5.4
Minor 201	Length		0.65%	3.2	gage
202	Width	(a)	0.65%	3.2	gage

NOTES:
a If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet, i.e. two measurements per roll

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46695B (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.10	Charge, Propelling, 8 Inch, M2 for 8 Inch How M2	1 OF 1	8861374
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged to the extent that black powder can escape		100%	3.2	visual/manual
Major					
101	Propelling charge assembly weight		100%	3.3	see 4.5.5
102	Proving ground	5		3.6	see 4.5.6
103	Dimensional gage failure (maximum length and diameter)		100%	3.5	gage
104	Any component missing or improperly assembled		100%	3.2	visual
105	Assembly damaged to the extent that propellant can escape		100%	3.2	visual
106	Igniter protector cap missing or improperly assembled		0.40%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-02-22 06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.10	CONTINUATION SHEET				8861374
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Strap loose, broken or insecurely tied		0.65%	3.2	visual/manual
202	Marking misleading or unidentifiable		0.65%	3.2	visual
203	Evidence of poor workmanship		0.65%	3.9	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.11	Container, Prior to Sealing		7548187
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Any packing component missing or improperly assembled		0.40%	3.2	visual
Minor 201	Charge cannot be removed by hand		0.65%	3.2	manual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://20.dsit.dla.mil -- Downloaded: 20260-22106:422
Check the source to verify that this is the current version before use.

QUALTIY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-46695B (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.12	Container Sealed		7548187
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Test plug missing		100%	3.2	visual
102	Test plug assembly torque		0.40%	3.7	test
103	Air pressure test		100%	3.2	4.5.3
Minor					
201	Test plug not greased (prior to assembly)		0.65%	3.2	visual
202	Metallic seal missing or incorrectly applied		0.65%	3.2	visual
203	Marking missing, misleading or unidentifiable		0.65%	3.2	visual
204	Cover incompletely engaged		0.65%	3.2	visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

4.4.3 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment design in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and paragraph 6.3 of this specification.

4.5 Test Methods and Procedures

4.5.1 Propellant weight (See 3.4). Any increment which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.3.

4.5.1.1 Method 1. The loaded increments will be inspected 100 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.1.2 Method 2. The propellant in a container shall be weighed and then check-weighed 100 percent on a different balance and if performed manually, by another production operator (no adding or subtracting of propellant shall be done during the check-weighing operation). The propellant shall then be placed in the bag and the bag sewn. The weight of the loaded bag should be checked as a major defect using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.2 Black Powder

4.5.2.1 Moisture content of Black Powder. The moisture content of the black powder will be determined in accordance with MIL-P-223. If any sample fails to meet the specified requirement the eight hours production represented by the sample shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 202610-22T06:42Z
Check the source to verify that this is the current version before use.

4.5.2.2 Weight of Black Powder - The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. The weight of the black powder will be inspected 100 percent. The weight of the black powder will be determined by subtracting an average weight of the empty assembly (no black powder) or the actual weight as marked on the individual assembly from the loaded assembly weight.

4.5.3 Air Pressure Test. Each container shall be tested as specified on the appropriate drawing. A pressure drop equivalent to or greater than the applicable requirement shall be cause for rejection and removal from the lot.

4.5.4 Cloth. At the time cloth is introduced to the sewing and/or cutting operation, an identification will be made for each roll to verify that proper material is used. Any cloth failing to be identified as proper material in accordance with applicable drawings and specifications shall be removed from sewing and/or cutting.

4.5.5 Charge, Propelling, Assembly Weight. (See 3.4.2) The assembly shall be weighed 100 percent. Any assembly which fails to comply with the applicable requirement shall be classed defective and removed from the lot.

4.5.6 Proving Ground. (See 3.6). This test shall be conducted at a Government Proving Ground in accordance with the applicable acceptance test procedure using HE M106 projectiles inert loaded within 0.05 pound of an as fired weight of 200.0 pounds using Primer, MK2A4 and fired in 8 inch Cannon, M2 series. Prior to firing, all charges shall be temperature conditioned in a large conditioning box with adequate air circulation at the required temperature ($\pm$ 2°F) for a minimum of 24 hours and assurance will be made that, when fired, the charges are at the conditioning temperature. Copper crusher gages (2) shall be used to measure the maximum chamber pressure of each charge.
Velocity coils will be used to measure the muzzle velocity of each charge.

Source: https://assist.dla.mil -- Downloaded: 202610-22T06:42Z
Check the source to verify that this is the current version before use.

4.5.6.1 Muzzle Velocity and Muzzle Velocity Standard Deviation. Determination of acceptance will be in accordance with MIL-STD-414, Section B, Table B3, AQL of 0.65%. All muzzle velocity and muzzle velocity standard deviation samples will be ballistic tested at 70°F. Five (5) charges at zone 7 will be fired for muzzle velocity and muzzle velocity standard deviation. If the sample is determined unacceptable the lot will be rejected. In addition, if the velocity standard deviation of the sample multiplied by the factor 0.65 exceeds the applicable lot requirement, the lot shall be rejected. Five (5) calibration charges will be fired alternately with the test samples and the muzzle velocity and pressure of all test charges will be corrected to standard conditions.

4.5.6.2 Pressure. If any propelling charge individual maximum pressure exceeds the applicable requirement, the lot shall be rejected.

5. PACKAGING

5.1 Packing and Marking. The propelling charges shall be packed, sealed, tested and marked in accordance with the specified requirements of drawing 7548187.

6. NOTES

6.1. Intended Use. The propelling charges covered by this specification are intended for use in 8 inch Howitzers.

6.2 Ordering Data. See MIL-A-48078.

6.3 Submission of Designs for Aproval. See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, US Army Armament Research and Development Command, ATN: DRDAR-QAR-I, with a copy to DRDAR-LCA-G Dover, New Jersey 07801.

6.4 Visual Examination Qualification. When compliance with the applicable requirement is in doubt as a result of visual examination, the characteristic may be measured or gaged to determine acceptability.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:42Z
Check the source to verify that this is the current version before use.

6.5 Inspection Lot Size. It is noted that the size of inspection lots of components, assemblies, or items of delivery may differ from the actual quantities contractually scheduled for delivery. However, in order to facilitate scheduling of tests or deliveries, inspection lots of items of delivery may be equivalent to such contract quantities provided all of the lot formation criteria and sampling provisions of this specification are maintained.

6.6 Proving Ground. A copy of all proving ground data should be submitted to Commander, US Army Research and Development Command, ATTN: DRDAR-QAR-R and DRDAR-LCA-G, Dover, New Jersey 07801.

6.7 Charge, Propelling Assembly Weight. This requirement applies to the load plant at the time of loading only. Due to subsequent change in tare weight of the components because of variation in material and moisture content, this test cannnot be repeated after initial manufacture to the degree of accuracy required.

6.8 Test Plug Assembly Torque. This requrement applies to the load plant at the time of loading only. Due to creep of the mechanical properties of the test plug, this test cannot be repeated after initial manufacture.

6.9 Data Cards. A copy of all data cards should be submittted to Commander, ARRADCOM, ATTN: DRDAR-QAR-R and DRDAR-LCA-G, Dover, New Jersey 07801.

Custodian:
Army-AR

Preparing Activity
Army-AR

Project Number:1320-A545

Source: https://assist.dla.mil -- Downloaded: 202610-22T06:42Z
Check the source to verify that this is the current version before use.