INCH-POUND

MIL-T-46691B(OS)
AMENDMENT 1
19 December 1995

MILITARY SPECIFICATION

THRUSTER, CARTRIDGE ACTUATED, M16 METAL PARTS ASSEMBLY

This amendment forms a part of MIL-T-46691B, dated 12 April 1993, and is approved for use by the Naval Sea Systems Command, Department of the Navy, and is available for use by all Departments and Agencies of the Department of Defense.

GENERAL COMMENT

Note: MIL-T-46691B, dated 12 April 1993, was issued with incorrect concluding information. It is a limited coordinated specification within Navy-OS. Each page should be marked MIL-T-46691B(OS).

PAGE 3

3.6.1, Delete in its entirety and substitute: "**3.6.1 Fluid leakage.** Prior to assembly of the head and cartridge, a load of 20 ± 2 pounds, for 15 seconds minimum, shall be applied to the floating piston to determine presence of O-ring and quad ring. Ensure there is no fluid leakage. Insert spring and retainer into cylinder assembly and assemble head to cylinder until fully seated. Remove all excess fluid and position vertical with head pointing down for a minimum of 16 hours. After 16 hours, remove head and inspect for evidence of fluid leakage externally or past the floating piston."

Preparing activity:
Navy - OS
(Project 1377-034)

Distribution Statement A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:41Z
Check the source to verify that this is the current version before use.