MIL-D-45495A(AR)
AMENDMENT 1
1 February 1983

MILITARY SPECIFICATION

DETONATOR, ELECTRIC, M84
PARTS FOR AND LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-D-45495A(MU), dated 5 March 1969, and is approved for use by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.4 Delete in its entirety and substitute the following:

"3.4 Porosity. The plug assembly (dwg 9335754) shall show no evidence of porosity as indicated by air bubbles when tested as specified in 4.4.2."

PAGE 8

4.3.2.3 Delete: "Plug (see dwg 8860883 covering a detail of dwg 8838107)." and substitute: "Plug (dwg 9335753 covering a detail of dwg 8838107)."

4.3.2.4 Delete: "Plug assembly (see dwg 8860881 ... dwg 8838107)". and substitute: "Plug assembly (dwg 9335754 covering a detail of dwg 8838107)".

PAGE 9

4.3.2.5 Delete in its entirety.

4.3.2.6 Delete in its entirety.

PAGE 10

4.3.2.7 Delete: "Bridge and plug assembly (see dwg 8838117 ... dwg 8838107)." and substitute: "Bridge and plug assembly (dwg 9335755 covering a detail of dwg 8838107)."

FSC 1330

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T03:13Z
Check the source to verify that this is the current version before use.

PAGE 13

4.3.3.4 Delete in its entirety and substitute the following:

"4.3.3.4 Plug assembly push test (dwg 9335754) - Major defect - Code No. 04010. The sampling plan shall be in accordance with Code Letter L with an AQL of 0.40 percent. The test shall be performed as specified in 4.4.4.

PAGE 14

4.3.3.5 Delete in its entirety and substitute the following:

"4.3.3.5 Resistance between pin and plug (dwg 9335754) - Major defect - Code No. 04011. The test shall be performed 100 percent in accordance with the procedure specified in 4.4.5. Any assembly that fails to comply with the requirement shall be classed defective and removed from the lot."

4.4.2 Delete "Porosity of plug assembly (see dwg 8860881)" and substitute: "Porosity of plug assembly (see dwg 9335754)."

Custodians:
Army-AR

Preparing activity:
Army-AR

(Project 1330-A187)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T03:13Z
Check the source to verify that this is the current version before use.