MIL-D-51083C
AMENDMENT 4
19 September 1984
SUPERSEDING
INT. AMENDMENT 3(EA)
22 April 1981

MILITARY SPECIFICATION

DETECTOR TICKET, ANTICHOLINESTERASE AGENT

This amendment forms a part of Military Specification MIL-D-51083C, dated 29 December 1967, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.2, lines 8 and 9: Delete "202 Union Station, 516 West Jackson Boulevard" and substitute "Room 1106, 222 South Riverside Plaza."

2.2, line 16: Delete "56" following "D1193."

PAGE 4

3.7: Add "and poor heat seals."

4.1.1: Delete in its entirety and substitute:

"4.1.1 Contractor's responsibility. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

Page 6

4.3.3.3: Delete and substitute:

FSC 6665

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:49Z
Check the source to verify that this is the current version before use.

"4.3.3.3 Classification of defects.

(a) Belts, detector ticket, assembly and detail (Dwg 5-77-808).

Categories		Defects
Critical:		None defined
Major:	AQL 1.0 percent defective	
101		Perforations incorrectly located
Minor:	AQL 2.5 percent defective	
201		Retaining ring not properly sealed (bulging)
202		Glass fiber disc incorrectly located
203		Incorrect number of tickets per belt
204		Incorrect marking
205		Workmanship (3.7)"

4.3.4, line 1: Following "ASTM D1193" add "type III."

PAGE 8

4.3.4.2(b)(1): Add "The Munsell color shall be read using a 7400°K light source in an enclosure having a neutral gray-colored interior."

4.3.4.2(b)(2): Add "The Munsell color shall be read using a 7400°K light source in an enclosure having a neutral gray-colored interior."

PAGE 9

6.5: Delete this paragraph in its entirety.

Custodians:

Army - EA
Navy - SH
Air Force - 99

Review activity:

Air Force - 82

User activities:

Navy - MC, OS

Preparing activity:

Army - EA

Project No. 6665-0463

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:49Z
Check the source to verify that this is the current version before use.