INCH-POUND

MS22069F
20 June 1997
SUPERSEDING
MS22069E
05 November 1987

MILITARY STANDARD

CYLINDER ASSEMBLY, EMERGENCY OXYGEN

This specification sheet is approved for use by all Departments and Agencies of the Department of Defense.

The Part or Identifying Number (PIN), shall be as follows: M22069-(Dash number from table I).

TABLE I. Configuration

Dash number	Valve, hose and pull cable assy	Cable length	Cable type	Hose length	Superseded P/N
4	M7560/1-4	16.25	Open	24	
21	M7560/1-21	N/A	N/A	28	
31	M7560/1-31	16.25	Open	28	MS22069-1
32	M7560/1-32	6.00	Open	28	MS22069-2, -3
33	M7560/1-33	27.31	Housed	28	MS22069-5



M22069-21

DISTRIBUTION STATEMENT A. Approved for public release; distribution unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:45Z
Check the source to verify that this is the current version before use.

Attach identification label to the “Shipping Gaurd” or “Housing Sheetmetal” as applicable. The label may wrap around one sheetmetal corner if necessary. Commercially available “Mylar Tape” self adhesive labels shall be used. The label shall read “Cyl Assy, Emerg Oxy” on the 1st line and the applicable PIN shall be shown on the 2nd line (see table I).

Leak test - Charge each assembly to 2100 psig pressure with type I oxygen conforming to MIL-O-27210. Submerge each charged assembly in water to cover the complete assembly except the gage. The connection between the gage and valve shall be covered. Development of air bubbles after being submerged for 30 seconds shall be cause for rejection.

Alternate methods - Charge each assembly as specified above. After charging, record the pressure gage indication. Record the pressure gage indication after three weeks. Any decrease in gage indication shall be cause for rejection.

After completion of the leak test, the cylinder assembly shall be individually packaged and shipped fully charged to 2100 psig, using MIL-O-27210 oxygen.

Referenced documents shall be of the issue in effect on date of invitation for bid.



Custodian:
Army - AV
Navy - AS
Air Force - 99

Preparing activity:
Air Force - 71

Agent:
Air Force - 99

Project 1660-0650

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:45Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waiver any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	1. DOCUMENT NUMBER	2. DOCUMENT DATE (YYMMDD)
	MS22069	97/06/20

3. DOCUMENT TITLE
CYLINDER ASSEMBLY,EMERGENCY OXYGEN

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.)*

5. REASON FOR RECOMMENDATION

6. SUBMITTER		
a. NAME *(Last, First, Middle Initial)*	b. ORGANIZATION	
c. ADDRESS *(include Zip Code)*	d. TELEPHONE *(Include Area Code)* (1) Commercial (2) AUTOVON *(If applicable)*	e. DATE SUBMITTED *(YYMMDD)*

8. PREPARING ACTIVITY	
a. NAME OC-ALC/TICLA	b. TELEPHONE *(Include Area Code)* (1) Commercial (405) 736-5960 (2) AUTOVON 336-5960
c. ADDRESS *(Include Zip Code)* 3001 STAFF DR STE 1AE1 101A TINKER AFB, OK 73145-5990	**IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT:** Defense Quality and Standardization Office 5203 Leesburg Pike, Suite 1403, Falls Church, VA 22041-3466 Telephone (703) 756-2340 AUTOVON 289-2340

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:45Z
Check the source to verify that this is the current version before use.