MIL-C-3372E
AMENDMENT-1
26 September 1985

MILITARY SPECIFICATION

CASE, TENTAGE REPAIR KIT

This amendment forms a part of Military Specification MIL-C-3372E, dated 13 September 1982, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1, "STANDARDS MILITARY": Add "MIL-STD-147 - Palletized Unit Loads." Delete " MIL-STD-1188 - Commercial Packaging of Supplies and Equipment".

Add the following paragraph:

"2.1.1 Other publications. Unless otherwise specified, the following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this document to the extent specified herein.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 3951 - Standard Practice for Commercial Packaging

(Application for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.)

(Technical society and technical association documents are generally available for reference from libraries. They are also distributed among technical groups and using Federal agencies.)"

PAGE 5

3.4.1 Delete the first item in the list and substitute

"1	Cloth duck, cotton, OD, 9.85 ounce, FWWMR	2 yds
1	Cloth, duck, polyester, FWWR, Army Desert Tan, Shade 459	2 yds
1	Cloth duck polyester, FWWR, Forest Green, Shade 433	2 yds"

FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T17:35Z
Check the source to verify that this is the current version before use.

PAGE 6

"List of contents (cont'd)."

Item 11, under "Quantity": Delete "1 lb" and substitute "1 cone or 2 lbs".
Item 13, line 2: Delete "(1/2 pt. cans)" and substitute "(6 oz cans)".
Item 17: Delete "sadler's" and substitute "saddler's".

PAGE 13

4.4.4, in "Defect" column: Delete fourth defect and substitute:
"Inadequate application of components such as:
incomplete closure of container flaps, improper taping,
loose strapping, or inadequate stapling.
Bulged or distorted container."

Add the following paragraph:

"4.4.5 Palletization examination. An examination shall be made to determine that the palletization complies with the section 5 requirements. Defects shall be scored in accordance with the list below. The sample unit shall be one palletized unit load fully packaged. The lot size shall be the number of palletized unit loads in the inspection lot. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirements.
Palletization	Pallet pattern not as specified. Interlocking of loads not as specified. Load not bonded with required straps as specified.
Weight	Exceeds maximum load limits.
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application."

PAGE 14

5.1.2, line 2: Delete "MIL-STD-1188" and substitute "ASTM D 3951."

5.2.1, line 10: Delete period and add ", except that the inspection shall be in accordance with 4.4.4."

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T17:35Z
Check the source to verify that this is the current version before use.

PAGE 14 (cont'd)

5.2.2, line 10: Delete period and add "except that the inspection shall be in accordance with 4.4.4."

PAGE 15

5.2.3, line 2: Delete "MIL-STD-1188" and substitute "ASTM D 3951".

5.3, line 2: After "containers": Add "and palletized unit loads."

line 3: Delete "MIL-STD-1188" and substitute "ASTM D 3951".

Add the following paragraph:

"5.4 Palletization. When specified (see 6.2), cases, packed as specified in 5.2, shall be palletized on a 4-way entry pallet in accordance with load type Ia of MIL-STD-147. Pallet type shall be type I (4-way entry), type III, type IV or type V in accordance with MIL-STD-147. Each prepared load shall be bonded with primary and secondary straps in accordance with the bonding means K and L, or film bonding O or P. Pallet pattern No. 6 shall be in accordance with the appendix of MIL-STD-147. Interlocking of loads shall be effected by reversing the pattern of each course."

6.4, line 2: Delete "DAR 7-104.55" and substitute "FAR 52.209".

Custodians:

Army - GL
Navy - MC
Air Force - 99

Preparing activity:

Army - GL

Project No. 8340-0470

Review activities:

Army - MD
Air Force - 82
DLA - CT

User activity:

Air Force - 45

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T17:35Z
Check the source to verify that this is the current version before use.