INCH-POUND

NOTE: The document identifier and heading has been changed on this page to reflect that this is a performance specification. There are no other changes to this document. The document identifier on subsequent pages has not been changed, but will be changed the next time this document is revised.

MIL-PRF-39012/32A
AMENDMENT 2
26 September 1994
AMENDMENT 1
1 November 1979

PERFORMANCE SPECIFICATION SHEET

CONNECTORS, COAXIAL, RADIO FREQUENCY, SERIES TNC (UNCABLED-RECEPTACLE, SOCKET, FLANGE MOUNTED, CLASS 2)

This amendment forms a part of MIL-C-39012/32A, dated 11 January 1973, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 1

FIGURE 1, notes, add:

"6. There shall be a solid barrier in the socket between the pin entry and the solder pocket to prevent solder wicking."

PAGE 2

* FIGURE 2: Delete in its entirety.

PAGE 3

* Under REQUIREMENTS, mating characteristics: Delete "See figure 2 for dimensions" and substitute "See MIL-STD-348."

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only, and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

CONCLUDING MATERIAL

Custodians:
Army - CR
Navy - EC
Air Force - 85
NASA - NA

Review activities:
Army - AR, AT, AV, ME, MI
Navy - AS, OS,
Air Force - 11, 19, 99

Preparing activity:
DLA - ES

(Project 5935-3932-22)

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T16:53Z
Check the source to verify that this is the current version before use.