MIL-W-48272 (AR)
Amendment 10
2 OCTOBER 1987
SUPERSEDING
Amendment 9
4 August 1981

MILITARY SPECIFICATION

WARHEAD SECTION, GM, HE: M251, M251A1 AND M251 (MOD) WITH LIVE FLSC AND INERT BOMBS, DUMMY LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of MIlitary Specification MIL-W-48272(AR), dated 26 November 1973, and approved for use within the US Army Armament Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Title - change warhead section number to read: "(M251), M251A1"

1.1, Delete in its entirety and replace with the following:

1.1 This specification covers the loading, assembling and packing for three types of warhead sections designated as Warhead Sections, GM HE: M251, M251A1 and M251 (Modified) with Live FLSC and Inert Loaded Bombs, Dummy".

2.1, Specifications, Military - Add the following:

"DOD-D-1000 -Drawing, Engineering and Associated List"

Lower right corner, change FSC from "1340" to "1336".

PAGE 2

2.1, Standards, Military - Add the following:

"DOD-STD-100 -Engineering Drawing Practices
MIL-STD-1167 -Ammunition Data Card"

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

2.1, Add the following:

HANDBOOKS

MILITARY

MIL-HDBK-204 - Inspection Equipment Design

* 2.1, Drawings, Change "U.S. Army Armament Command" to "U.S. Army Armament Research, Development and Engineering Center (ARDEC) Product and Packaging Drawings".

2.1, Drawings, U.S. Army Armament Command, Add:

9211190	-Pkg and Mkg for Warhead Sect., GM, HE: M251, Prac: XM198E1; Tng: M201
9208657	-Cable Assembly, M251
9266382	-Roll Moment Fixture
9266418	-Test Fixture, Insulation Resistance
9266419	-Test Procedure and Calibration Instr. -Insulation Resistance Test for Warhead -Section Cable Assembly-XM251 for C9266418
9266422	-Continuity and Resistance, LANCE Warhead with Fuze
9266424	-Weight Measurement Fixture on Lance Warhead XM251
9266425	-Operating Instructions and Calibration Procedures for Weight Measurement on Lance Warhead XM251 for B9266624
9266426	-Pitch and Yaw Moment of Inertia Fixture
9266427	-Operating Instructions Lance Warhead, XM251, (to be used with A9266426)
9266428	-Operating Instructions Lance Warhead, XM251, (to be used with F9266382)
9283999	-Metal Parts Assembly M251
9332549	-Warhead Section, GM, HE: M251A1
9266435	-Test Set, Continuity and Resistance Warhead -Section M251
11430220	-Gage Assembly, Acceptance Warhead Interface, M.S. 100.00
11430988	-Instruction Tag, Warhead Gage for Missile Interface

Source: https://assist.dla.mil -- Downloaded: 20260-22T19:20Z
Check the source to verify that this is the current version before use.

* 2.1, Drawings, U.S. Army Armament Research, Development and Engineering Center (ARDEC) Product and Packaging Drawings: Change the Nomenclature number to read: "M251, M251A1 and M251 (Mod)" in the title of the following drawings: 9211190, 9266419, 9266425, 9266424, 9266427, 9266428, and 9266435.

* 2.1, Drawings, U.S. Army Armament Command; Add:

"12555998 -Warhead Section, GM, M251 (Modified) with Live FLSC and Inert Loaded Bombs, Dummy

12597937 -Pkg and Mkg for Warhead Section, GM, M251 (Modified) with Live FLSC and Inert Loaded Bombs, Dummy"

2.2, Add the following:

"AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

ASTM D1621-73	-Test for Compressive Strength of Rigid Cellular Plastics
ASTM D1622-63	-Test for Apparent Density of Rigid Cellular Plastics

* 3.2, Delete in its entirety and substitute the following:

"3.2 Parts. The parts shall comply with all requirements specified on Drawings 9284000, 9332549, and 12555998, all associated drawings, and with all requirements specified in applicable specifications."

3.4 - Delete in its entirety.

3.5 - Delete in its entirety

PAGE 6

4.3.2.1, Title - Change "XM251" to "M251"

4.3.2.1, Major Defects; Change "100% Inspection" to "AQL = 0.40% (Note 1)"

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

4.3.2.1 - Delete Major 106 and substitute:

"106. Distance from aft ring assembly to longitudinal end primer (with booster cover off) - See View L GAGE 01006"

4.3.2.1, Major 107; Change "barrier cover" to "booster cover".

4.3.2.1; Add Note 1 as follows:

"Note 1. For Lot Sizes below 90 items, the AQL shall equal 1.0%"

PAGE 7

4.3.2.1, Minor 201 - Change Code No. "01010" to "01012".

PAGE 9

4.3.2.7; Add the following:

"104. Holes missing Visual 07005"

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

* 4.3.2.10; Delete in its entirety and replace with the following:

"4.3.2.10 Warhead Section, during loading, GM, HE: M251, M25A1 and M251 (Modified) with live FLSC and inert loaded bombs, dummy (See Dwgs. 9284000, 9332549 and 12555998).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	100% Inspection		
101.	Presence of plate (Dwg. 9331775) prior to loading. (M251A1 only)	Visual	10013
102.	Presence of aft filler (M251A1 only)	Visual	10014
103.	Containment block pad missing or improperly installed	Visual	10001
104.	Wood blocks missing	Visual	10002
105.	Distance to bombs and wood blocks	Gage	10003
106.	Polyethlene sheets improperly installed, torn, or missing	Visual	10004
107.	Incorrect number of bag and bag filler assemblies	Visual	10005
108.	Bag and bag filler assembly flaps facing forward	Visual	10006
109.	Wedges missing or improperly assembled	Visual	10007
110.	Skin missing or improperly assembled	Visual	10008
111.	Spacer missing or improperly assembled	Visual	10009
112.	Insulation tape missing damaged or improperly installed on aft ring assembly	Visual	10010
113.	O-Ring missing, damaged or improperly installed on aft ring assembly	Visual	10011
Minor:			
201.	Evidence of poor workmanship (see 3.6)	Visual	10012

Source: https://assist.dla.mil -- Downloaded: 2026l0-22T19:20Z
Check the source to verify that this is the currentversion before use.

* 4.3.2.11, Title: Delete in its entirety and substitute the following:

"4.3.2.11, Warhead Section, GM, HE: M251, M251A1 and M251(Modified) with live FLSC and inert loaded bombs, dummy after assembly of aft ring assembly and prior to assembly of boosters (See dwgs 9284000, 9332549 and 12555998)."

PAGE 11

4.3.2.11, Major 105; Delete "See Dwg. 9283999 - View L" and substitute "See Section G-G".

4.3.2.11; Add the following:

"114	Shims or adhesive covering ends of booster that is inserted through booster cover hole (prior to assembly of booster)	Visual	11015
115	Shims or adhesive on side of booster that contacts end primer in MDF and primer assembly (after assembly of booster)"	Visual	11016

4.3.2.11, Major 106: Delete in its entirety and substitute:

"106 Distance from aft ring assembly to longitudinal end primer (with booster cover off) - See Section G-G 11018

PAGE 12

* 4.3.2.12, Title: Delete in its entirety and substitute:

"4.3.2.11 Warhead Section, GM, HE: 251, M251A1 and M251(Modified) with live FLSC and inert loaded bombs, dummy during and after assembly of fuze, port covers and boosters (See dwgs 9284000, 933549 and 12555998)."

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:20Z
Check the source to verify that this is the currentversion before use.

4.3.2.12: Add the following:

"110 Booster (3) installed in reversed direction.	Visual	12012

* 4.3.2.13, Title: Delete in its entirety and substitute:

"4.3.2.13 Warhead section, during loading, GM, HE: M251, M251A1 and M251 (modified with live FLSC and inert loaded bombs, dummy (See dwgs 9284000, 9332549 and 12555998)."

4.3.2.13, Major 101: Delete phrase "and between forward and aft skins".

4.3.2.13, Major 104: Delete in its entirety and substitute:

"104 Tee bolts bind or too loose in cavities"	Manual	13004

4.3.2.13, Major 106: Delete "Gage" and substitute "Dwgs. 9266424 and 9266425".

4.3.2.13, Major 109: Delete "Test" and substitute "Dwgs. 9200664, 9266387 and 9266430".

4.3.2.13, Major 110: Delete "Test" and substitute "Dwgs. 9266382 and 9266428".

4.3.2.13, Major 112: Change "Gage" to "Visual".

4.3.2.13: Add the following:

115. Forward facing step at nose cone assembly, max.	Gage	13016
116. Aft facing step at nose cone assembly, max.	Gage	13017
117. Marking missing, incomplete or illegible.	Visual	13018

Source: https://assist.dla.mil -- Downloaded: 20260-22T19:20Z
Check the source to verify that this is the current version before use.

4.3.2.13, Major 111: Delete "Gage" and substitute "11430220/11430988".

* 4.3.2.14, Title: Delete in its entirety and substitute:

"4.3.2.14 Pkg and Mkg for Warhead Section GM, HE: M251 M251A1 and M251 (Modified) with live FlSC and inert loaded bombs, dummy; Prac: XM198E1, Tng: XM201, prior to assembly of cover assembly (See dwg 9211190 or 12597937)."

4.3.2.14, Major Defects - Add: "100% Inspection"

PAGE 14

* 4.3.2.15, Title: Delete in its entirety and substitute:

"4.3.2.15 Pkg and Mkg for Warhead Section GM, HE: M251 M251A1 and M251 (Modified) with live FLSC and inert loaded bombs, dummy; Prac: XM198E1, Tng: XM201 (See dwg 9211190 or 1259737."

4.3.2.15, Major Defects - Add: "100% Inspection".

4.3.2.15: Add Major 106 as follows:

"106. Stacking bolts, missing or damaged. Visual 15007"

Add the following:

"4.3.2.16 Spacer, foam (See Dwg. 9312646).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major			
101.	Thickness	Gage	23001
102.	Depth of cut (2 sides)	Gage	23002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

Minor			
201.	Outside diameter	Gage	23003
202.	Inside diameter	Gage	23004
203.	Width of small cutout	Gage	23005
204.	Depth of small cutout	Gage	23006
205.	Width of large cutout	Gage	23007
206.	Depth of large cutout	Gage	23008
207.	Evidence of poor workmanship (See 3.6)"	Visual	23009

Add Para: 4.3.2.17 as follows:

"4.3.2.17 Filler, aft (See Dwg. 9331772)

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:			
101.	Length	Gage	24001
102.	Largest outside diameter	Gage	24002
103.	Second largest outside diameter	Gage	24003
104.	Inside diameter	Gage	24004
105.	Density (Note 1)	Test	24005
106.	Compressive strength (Note 1)	Test	24006
107.	Surface Finish (See Note 2)	Visual	24007
108.	Forward lead angle improper	Gage	24008
Minor:			
201.	Evidence of poor workmanship (See 3.6)"	Visual	24009

Note 1: A three (3) sample (from 1 part) average shall be used to verify compliance.

Note 2: The surface finish shall be smooth and hard (as molded) with no evidence of loose, crumbling particles.

Add para 4.3.2.18 as follows:

"4.3.2.18 Filler, nose (See Dwg. 9331774)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:			
101.	Length	Gage	25001
102.	Largest outside diameter	Gage	25002
103.	Second largest outside diameter	Gage	25003
104.	Inside diameter	Gage	25004
105.	Width of small cutout (2 places)	Gage	25005
106.	Width of large cutout (2 places)	Gage	25006
107.	Depth of small cutout (2 places)	Gage	25007
108.	Depth of large cutout (2 places)	Gage	25008
109.	Chamfer	Visual	25009
110.	Density (Note 1)	Test	25010
111.	Compressive strength (Note 1)	Test	25011
Minor:			
201.	Evidence of poor workmanship (See 3.6)"	Visual	25010

Note 1: A three (3) sample (from 1 part) average shall be used to verify compliance.

Add Para 4.3.2.19 as follows:

"4.3.2.19 Plate (See Dwg. 9331775)

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:			
101.	Outside diameter	Gage	26001
102.	Inside diameter	Gage	26002
103.	Thickness	Gage	26003
104.	Protective finish	Visual	26004

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

Minor:

201.	Evidence of poor workmanship (see 3.6)	26005

4.3.3.2: Add after "4.3.4", "(See Dwgs. 9266435)".

4.3.3.4: Add after "4.3.4", "(See Dwg. 9266418 and 9266419). This test to be performed after performance of tests and inspections in Para 4.3.2.13, Majors 106 thru 110."

4.3.3.5: Add after second sentence, "This test to be performed after performance of tests and inspections in Para 4.3.2.13, Majors 106 thru 110."

4.3.3.5: Add after "4.3.4", "(See Dwg 9266435)".

4.3.3.6: Add after "4.3.4", "(See Dwg. 9266422 This test to be performed after performance of tests and inspections in Para 4.3.2.13, Majors 106 thru 110."

4.3.3.6: Change "See 3.4" to "(See Dwg. 9284000, 9332549, and 12555998)".

4.3.3.7: Delete in its entirety.

Add Para 4.3.3.8 as follows:

"4.3.3.8 Density and compressive strength of polyurethane fillers (See Dwgs. 9331772 and 9331774), Major Defect, Codes 24005/25010 and 24006/25011. One (1) part from each lot of nose and aft fillers shall be selected for test. The density tests (non-destructive) shall be conducted on the compressive test specimens prior to performing the compressive tests. The compressive strength specimens shall be taken from the part after removal of the filler part skin. The three 2-inch cube specimens shall be cut at 120° intervals around the part; one at the top, one at the bottom, and one midway up the part. These tests shall be performed using equipment in accordance with 4.3.4. Any lot which fails to comply with the specified requirement shall be rejected."

PAGE 16

4.4.6 - Delete in its entirety and replace with the following:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

"4.4.6: Continuity and resistance of cable assembly of loaded warhead when fuze is installed at the time of loading. The continuity and resistance of the cable assembly/fuze shall be tested in accordance with Dwg. 9284000 (M251) or Dwg. 9332549 (M251E1), using approved test equipment. This is a nondestructive test. Assemblies subjected to this test shall be returned to the lot."

* 4.4.6: Change "Dwg. 9284000 (M251) or Dwg. 9332549 (M251A1)" to "Dwgs. 9284000 (M251), 9322549 (M251A1) or 12555998 (M251) (Mod)".

PAGE 17

4.4.7: Delete in its entirety.

Add Para 4.4.9 as follows:

"4.4.9 Density and compressive strength of polyurethane fillers. The density tests shall be conducted in accordance with ASTM standard D-1622 and the compressive strength tests in accordance with ASTM standard D-1621. Parts from which specimens are taken shall not be returned to the lot."

Add Para 4.4.10 as follows:

"4.4.10 Longitudinal center of gravity. - The loaded warhead shall be subjected to the longitudinal center of gravity test using approved test equipment. This is a nondestructive test. Assemblies subjected to this test shall be returned to the lot."

Add Para 4.4.11 as follows:

"4.4.11 Pitch and yaw moment of inertia. - The loaded warhead shall be subjected to the pitch and yaw moment of inertia test using approved test equipment. This is a nondestructive test. Assemblies subjected to this test shall be returned to the lot."

Add Para 4.4.12 as follows:

"4.4.12 Roll moment of inertia. - The loaded warhead shall be subjected to the roll moment of inertia test using approved test equipment. This is a non-destructive test. Assemblies subjected to this test shall be returned to the lot."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

PAGE 18

Para 6.3.1, section b. & c. - Change "MIL-STD-100" to "DOD-STD-100".

PAGE 19

6.3.2: Change "Picatinny Arsenal design..." to "Design ...".

* 6.4: Delete the phase "... and ammunition data cards...".

6.4, 6.5, 6.6 - Change forwarding address to read as follows: "Commander, U.S. Army Armament Research, Development and Engineering Center (ARDEC), ATTN: AMSMC-QAR-R(D), Picatinny Arsenal, NJ 07806-5000.

PAGE 20

Figure 1.: Delete in its entirety.

NOTE: The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications,corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project No. 1336-A540)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.