MILITARY SPECIFICATION

LIGHT, MARKER, AIRPORT, SEMIFLUSH, GENERAL SPECIFICATION FOR

This amendment forms a part of Military Specification MIL-L-26202D(ASG), 18 December 1964, and has been approved by the Department of the Air Force and by the Naval Air Systems Command.

Page 1, paragraph 1.2.2, last sentence: Add "(MS21999)" after "(MS26579)".

Page 2:

(a) Paragraph 2.1: Under Military Standards, add the following:

"MS21999 Lamp, Incandescent, PAR 36 Airport Lighting, Screw Terminal"

(b) Paragraph 2.2: Add the following new document:

"American Standards Association

ASA B46.1 - 1962 Surface Texture (Surface Roughness, Waviness and Lay)

(Copies of the above publication may be obtained from the American Standards Association, Inc., 10 East 40th Street, New York, N. Y. 10016.)"

Page 5:

(a) Paragraph 3.5.5.1, third line: Delete "type SA" and substitute "type SFF-2".

(b) Paragraph 3.5.8.1, first and second sentences: Delete, and substitute:

"Unless otherwise specified in the contract or order, the housing material shall be ductile iron having a minimum tensile strength of 70,000 pounds per square inch (psi), a minimum yield strength of 50,000 psi, a minimum elongation of 12 percent, and a Brinell hardness of not less than 166 (see 6.2(m))."

Page 6:

(a) Paragraph 3.5.8.1.1.1, second line: Between the words "casting" and "of" insert "or forging".

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T07:57Z
Check the source to verify that this is the current version before use.

(b) Paragraph 3.5.8.3: Delete, and substitute:

"3.5.8.3 Fasteners.- On unidirectional and bidirectional units all bolt heads shall be below the external surface of the housing, and a counterbore shall be provided for the bolt hole in the top of the housing so that a standard 1/2-inch socket wrench can be used. The depth of the counterbore in each of the six holes shall be such that the specified bolts will not bottom on the gasket used between the base and the inner rings."

(c) Paragraph 3.5.8.3.1, seventh line: Add the following at the end of the fourth sentence:

"and threaded high enough for tightening the housing to the locator ring."

Page 9: Add the following new paragraph:

"3.5.13 Surfaces.- All surfaces facing gaskets shall have a maximum roughness height rating of 125 RHR and a flatness of 0.020 maximum waviness height value in accordance with ASA B46.1 - 1962."

Page 10, paragraph 4.3.1: Add the following to the end of the paragraph:

"When specified by the activities responsible for qualification, qualification samples that have passed all other qualification examinations and tests shall be forwarded as instructed by the activity responsible for qualification for the performance of tests specified in 4.6.9, 4.6.10, 4.6.11, and 4.6.12."

Page 11:

(a) Paragraph 4.3.2: Delete, and substitute:

"4.3.2 Qualification tests.- Qualification tests shall consist of the examinations and tests specified in 4.5 and 4.6, except 4.6.9, 4.6.10, 4.6.11, 4.6.12, and 4.6.13. The tests specified in 4.6.9, 4.6.10, 4.6.11, and 4.6.12 shall be performed as part of the qualification tests only when specified by the activity responsible for qualification."

(b) Paragraph 4.6.3: Add the following to the end of the paragraph:

"The light shall be mounted on the vibration machine by attaching necessary brackets or adaptors to the light where the base, clamp ring, and housing join."

Page 12:

(a) Paragraph 4.6.6, fourth line: After "water penetration" insert "(except for class C lights)".

(b) Paragraph 4.6.9, first line: Delete "At the discretion of the activity responsible for qualification,".

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T07:57Z
Check the source to verify that this is the current version before use.

Page 13, paragraphs 4.6.10, 4.6.11, and 4.6.12, first line: Delete "At the discretion of the activity responsible for qualification,".

Page 14, paragraph 6.2: Add as last item "(m) Housing material, if other than as specified in paragraph 3.5.8.1."

Custodians:
Navy - AS
Air Force - 11

Preparing activity:
Air Force - 11

Reviewer activities:
Navy - AS
Air Force - 11, 82, 85

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T07:57Z
Check the source to verify that this is the current version before use.