NOTICE OF CANCELLATION

INCH-POUND

AN894 Rev 9
NOTICE 3
11 May 2009
SUPERSEDING
NOTICE 2
23 February 2001

MILITARY STANDARD

BUSHING, SCREW THREAD, EXPANDER

AN894 Rev 9, dated 6 April 1984, is hereby cancelled. Future acquisitions for this item should refer to SAE-AS5173, “FITTING, BUSHING, PORT, REDUCER”.

(Copies of these documents are available online at http://www.sae.org or from SAE World Headquarters, 400 Commonwealth Drive, Warrendale, PA 15096-0001.)

Reason for NOTICE 3: SAE inactivated Part or Identifying Numbers (PIN) with material code letter D for replacement parts and for new design to use code letter W. This is because code letter W is stronger in tensile strength than code letter D. This is based on the previous PA’s revision, as a result of lessons learned. Plus to add back material code letter S for replacement parts and for new design to use code letter R. The code letter R is better for applications requiring higher temperature.

Table I provides a detailed supersession cross-reference of cancelled AN894 Rev 9 PINs and replacement SAE-AS5173 PINs.

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

AMSC N/A

FSC 4730

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:17Z
Check the source to verify that this is the current version before use.

TABLE I. AN894 Rev 9 to SAE-AS5173, cross-reference data.

Cancelled AN PIN	Replacement AS PIN 1/		Cancelled AN PIN	Replacement AS PIN 1/	
AN894-3-2	AS5173-0302		AN894-6-5	AS5173-0605	
AN894D3-2	AS5173D0302	2/	AN894D6-5	AS5173D0605	2/
AN894D3-2	AS5173W0302	3/	AN894D6-5	AS5173W0605	3/
AN894J3-2	AS5173J0302		AN894J6-5	AS5173J0605	
AN894K3-2	AS5173K0302		AN894K6-5	AS5173K0605	
AN894S3-2	AS5173S0302	4/	AN894S6-5	AS5173S0605	4/
AN894S3-2	AS5173R0302	5/	AN894S6-5	AS5173R0605	5/
AN894T3-2	AS5173T0302		AN894T6-5	AS5173T0605	
AN894W3-2	AS5173W0302		AN894W6-5	AS5173W0605	
AN894-4-2	AS5173-0402		AN894-8-4	AS5173-0804	
AN894D4-2	AS5173D0402	2/	AN894D8-4	AS5173D0804	2/
AN894D4-2	AS5173W0402	3/	AN894D8-4	AS5173W0804	3/
AN894J4-2	AS5173J0402		AN894J8-4	AS5173J0804	
AN894K4-2	AS5173K0402		AN894K8-4	AS5173K0804	
AN894S4-2	AS5173S0402	4/	AN894S8-4	AS5173S0804	4/
AN894S4-2	AS5173R0402	5/	AN894S8-4	AS5173R0804	5/
AN894T4-2	AS5173T0402		AN894T8-4	AS5173T0804	
AN894W4-2	AS5173W0402		AN894W8-4	AS5173W0804	
AN894-4-3	AS5173-0403		AN894-8-5	AS5173-0805	
AN894D4-3	AS5173D0403	2/	AN894D8-5	AS5173D0805	2/
AN894D4-3	AS5173W0403	3/	AN894D8-5	AS5173W0805	3/
AN894J4-3	AS5173J0403		AN894J8-5	AS5173J0805	
AN894K4-3	AS5173K0403		AN894K8-5	AS5173K0805	
AN894S4-3	AS5173S0403	4/	AN894S8-5	AS5173S0805	4/
AN894S4-3	AS5173R0403	5/	AN894S8-5	AS5173R0805	4/
AN894T4-3	AS5173T0403		AN894T8-5	AS5173T0805	
AN894W4-3	AS5173W0403		AN894W8-5	AS5173W0805	
AN894-5-4	AS5173-0504		AN894-8-6	AS5173-0806	
AN894D5-4	AS5173D0504	2/	AN894D8-6	AS5173D0806	2/
AN894D5-4	AS5173W0504	3/	AN894D8-6	AS5173W0806	3/
AN894J5-4	AS5173J0504		AN894J8-6	AS5173J0806	
AN894K5-4	AS5173K0504		AN894K8-6	AS5173K0806	
AN894S5-4	AS5173S0504	4/	AN894S8-6	AS5173S0806	4/
AN894S5-4	AS5173R0504	5/	AN894S8-6	AS5173R0806	5/
AN894T5-4	AS5173T0504		AN894T8-6	AS5173T0806	
AN894W5-4	AS5173W0504		AN894W8-6	AS5173W0806	

See notes at end of tables.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:17Z
Check the source to verify that this is the current version before use.

TABLE I. AN894 Rev 9 to SAE-AS5173, cross-reference data – Continued.

Cancelled AN PIN	Replacement AS PIN 1/		Cancelled AN PIN	Replacement AS PIN 1/	
AN894-6-4	AS5173-0604		AN894-10-4	AS5173-1004	
AN894D6-4	S5173D0604	2/	AN894D10-4	AS5173D1004	2/
AN894D6-4	AS5173W0604	3/	AN894D10-4	AS5173W1004	3/
AN894J6-4	AS5173J0604		AN894J10-4	AS5173J1004	
AN894K6-4	AS5173K0604		AN894K10-4	AS5173K1004	
AN894S6-4	AS5173S0604	4/	AN894S10-4	AS5173S1004	4/
AN894S6-4	AS5173R0604	5/	AN894S10-4	AS5173R1004	5/
AN894T6-4	AS5173T0604		AN894T10-4	AS5173T1004	
AN894W6-4	AS5173W0604		AN894W10-4	AS5173W1004	
AN894-10-5	AS5173-1005		AN894-12-10	AS5173-1210	
AN894D10-5	AS5173D1005	2/	AN894D12-10	AS5173D1210	2/
AN894D10-5	AS5173W1005	3/	AN894D12-10	AS5173W1210	3/
AN894J10-5	AS5173J1005		AN894J12-10	AS5173J1210	
AN894K10-5	AS5173K1005		AN894K12-10	AS5173K1210	
AN894S10-5	AS5173S1005	4/	AN894S12-10	AS5173S1210	4/
AN894S10-5	AS5173R1005	5/	AN894S12-10	AS5173R1210	5/
AN894T10-5	AS5173T1005		AN894T12-10	AS5173T1210	
AN894W10-5	AS5173W1005		AN894W12-10	AS5173W1210	
AN894-10-6	AS5173-1006		AN894-16-6	AS5173-1606	
AN894D10-6	AS5173D1006	2/	AN894D16-6	AS5173D1606	2/
AN894D10-6	AS5173W1006	3/	AN894D16-6	AS5173W1606	3/
AN894J10-6	AS5173J1006		AN894J16-6	AS5173J1606	
AN894K10-6	AS5173K1006		AN894K16-6	AS5173K1606	
AN894S10-6	AS5173S1006	4/	AN894S16-6	AS5173S1606	4/
AN894S10-6	AS5173R1006	5/	AN894S16-6	AS5173R1606	4/
AN894T10-6	AS5173T1006		AN894T16-6	AS5173T1606	
AN894W10-6	AS5173W1006		AN894W16-6	AS5173W1606	
AN894-10-8	AS5173-1008		AN894-16-8	AS5173-1608	
AN894D10-8	AS5173D1008	2/	AN894D16-8	AS5173D1608	2/
AN894D10-8	AS5173W1008	3/	AN894D16-8	AS5173W1608	3/
AN894J10-8	AS5173J1008		AN894J16-8	AS5173J1608	
AN894K10-8	AS5173K1008		AN894K16-8	AS5173K1608	
AN894S10-8	AS5173S1008	4/	AN894S16-8	AS5173S1608	4/
AN894S10-8	AS5173R1008	5/	AN894S16-8	AS5173R1608	5/
AN894T10-8	AS5173T1008		AN894T16-8	AS5173T1608	
AN894W10-8	AS5173W1008		AN894W16-8	AS5173W1608	

See notes at end of tables.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:17Z
Check the source to verify that this is the current version before use.

TABLE I. AN894 Rev 9 to SAE-AS5173, cross-reference data –Continued.

Cancelled AN PIN	Replacement AS PIN 1/		Cancelled AN PIN	Replacement AS PIN 1/	
AN894-12-6	AS5173-1206		AN894-16-10	AS5173-1610	
AN894D12-6	AS5173D1206	2/	AN894D16-10	AS5173D1610	2/
AN894D12-6	AS5173W1206	3/	AN894D16-10	AS5173W1610	3/
AN894J12-6	AS5173J1206		AN894J16-10	AS5173J1610	
AN894K12-6	AS5173K1206		AN894K16-10	AS5173K1610	
AN894S12-6	AS5173S1206	4/	AN894S16-10	AS5173S1610	4/
AN894S12-6	AS5173R1206	5/	AN894S16-10	AS5173R1610	5/
AN894T12-6	AS5173T1206		AN894T16-10	AS5173T1610	
AN894W12-6	AS5173W1206		AN894W16-10	AS5173W1610	
AN894-12-8	AS5173-1208		AN894-16-12	AS5173-1612	
AN894D12-8	AS5173D1208	2/	AN894D16-12	AS5173D1612	2/
AN894D12-8	AS5173W1208	3/	AN894D16-12	AS5173W1612	3/
AN894J12-8	AS5173J1208		AN894J16-12	AS5173J1612	
AN894K12-8	AS5173K1208		AN894K16-12	AS5173K1612	
AN894S12-8	AS5173S1208	4/	AN894S16-12	AS5173S1612	4/
AN894S12-8	AS5173R1208	5/	AN894S16-12	AS5173R1612	5/
AN894T12-8	AS5173T1208		AN894T16-12	AS5173T1612	
AN894W12-8	AS5173W1208		AN894W16-12	AS5173W1612	
AN894-20-8	AS5173-2008		AN894-20-12	AS5173-2012	
AN894D20-8	AS5173D2008	2/	AN894D20-12	AS5173D2012	2/
AN894D20-8	AS5173W2008	3/	AN894D20-12	AS5173W2012	3/
AN894J20-8	AS5173J2008		AN894J20-12	AS5173J2012	
AN894K20-8	AS5173K2008		AN894K20-12	AS5173K2012	
AN894S20-8	AS5173S2008	4/	AN894S20-12	AS5173S2012	4/
AN894S20-8	AS5173R2008	5/	AN894S20-12	AS5173R2012	4/
AN894T20-8	AS5173T2008		AN894T20-12	AS5173T2012	
AN894W20-8	AS5173W2008		AN894W20-12	AS5173W2012	
AN894-20-10	AS5173-2010		AN894-20-16	AS5173-2016	
AN894D20-10	AS5173D2010	2/	AN894D20-16	AS5173D2016	2/
AN894D20-10	AS5173W2010	3/	AN894D20-16	AS5173W2016	3/
AN894J20-10	AS5173J2010		AN894J20-16	AS5173J2016	
AN894K20-10	AS5173K2010		AN894K20-16	AS5173K2016	
AN894S20-10	AS5173S2010	4/	AN894S20-16	AS5173S2016	4/
AN894S20-10	AS5173R2010	5/	AN894S20-16	AS5173R2016	5/
AN894T20-10	AS5173T2010		AN894T20-16	AS5173T2016	
AN894W20-10	AS5173W2010		AN894W20-16	AS5173W2016	

See notes at end of tables.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:17Z
Check the source to verify that this is the current version before use.

TABLE I. AN894 Rev 9 to SAE-AS5173, cross-reference data –Continued.

1/ The SAE replacement part is a functional equivalent of the military part except that some sizes require longer lengths. An adjustment of the length of the mating tube may be required for ease of installation.
2/ For replacements parts, use code letter “D”. Reason: SAE G3 and DoD-SAE liaisons agreed to use code “D” for replacement PINs.
3/ For new design parts, use code letter “W” . Reason: SAE G3 and DoD-SAE liaisons agreed to use code “W” for new design
4/ For replacement parts use code letter “S”. Reason: SAE G3 and DoD-SAE liaisons agreed to use code “S” for replacement PINs.
5/ For new design parts use code Letter “R”. Reason: SAE G3 and DoD-SAE liaisons agreed to use code “R” for new design

CONCLUDING MATERIAL

Custodians:
Army - AV
Navy - AS
Air Force - 99
DLA - CC

Preparing activity:
DLA-CC

(Project 4730-2009-018)

Review activities:
Army – AR ,CR4
Navy - MC, SA
Air Force – 70, 71

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at http://assist.daps.dla.mil.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:17Z
Check the source to verify that this is the current version before use.