MIL-I-82437(OS)
Amendment 3
29 April 1969
Superseding
Amendment 2
14 August 1968

MILITARY SPECIFICATION

IGNITER

This amendment forms a part of Military Specification MIL-I-82437(OS) of 10 May 1966 and has been approved by the Naval Ordnance Systems Command, Department of the Navy

Wherever it appears in specification delete "Bureau of Naval Weapons" and substitute "Naval Ordnance Systems Command"; also delete the term "Acceptance Tests" and substitute "Quality Conformance Tests".

Page 1, paragraph 2.1, under SPECIFICATIONS: Delete "MIL-A-9836" and its associated title; delete "QQ-S-633" and associated title and substitute "QQ-S-637 Steel, Bar, Carbon, Cold Finished (Standard Quality, Free Machining)"; under STANDARDS, add "MIL-STD-1167 Ammunition Data Card".

Page 3, add the following new paragraph:
"3.2.5 Safety. The supplier or manufacturer, as may apply, shall provide adequate safety precaution for protection of personnel during the handling of igniters (see 6.5)".

Page 8, paragraph 3.6: Delete "MIL-A-9836" and substitute "MIL-STD-1167".

Page 9, paragraph 4.3.3d.: Delete "acitivity" and substitute "activity".

Page 14, paragraph 4.4.4.5, first sentence. Delete "Eight preproduction igniters shall be subjected" and substitute "The igniter shall be subjected"; in lines 17, 18, and 19 delete the following sentence: "Thereafter, 4 igniters shall be operated in accordance with 4.4.4.6 and 4 igniters shall be operated in accordance with 4.4.4.7.".

Page 19, paragraph 4.5.6.1e., under subheading "Materials:": Delete "QQ-S-633" and substitute "QQ-S-637".

Page 20, paragraph 4.5.6.2a., line 3: Delete "ampers" and substitute "amperes".

Page 20, paragraph 4.5.7, line 2: Delete "suppler" and substitute "supplier".

FSC 1355

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.

Page 21, paragraph 4.6a., last sentence: Delete "Table IX." and substitute "Table IX. (Col II)".

Page 21, paragraph 4.6b., last sentence: Delete "Table IX." and substitute "Table IX (Cols III and IV)".

Page 21, paragraph 4.6c last sentence: Delete "Sample 4, etc." and substitute "Sample 4, etc. (Col II)".

Page 22. Replace Table IX with new Table IX attached.

Pages 26 through 28. Delete paragraph 6.5 and its subparagraphs and substitute the following:

"6.5 Explosives safety precautions

6.5.1 Applicability. The loading, assembly, and handling of the explosives, subassemblies, and the finished items covered by this specification, involve hazardous operations and therefore require suitable explosives safety precautions. At plants of the Naval Ordnance System Command, Department of the Navy, and other Government plants where the government is responsible for safety, the precautions listed below are mandatory. These same minimum provisions listed below are recommended for observance by a contractor or manufacturer that explosively loads the item covered in this specification, in order to fulfill his own safety responsibility. Other warnings and precautions pertaining to the operational effectiveness or safety of the specified item during its use (for example, during its handling, launching, or firing) are included in the detailed technical requirements of the specification. Use of this specification shall not be construed as replacing other safety regulations of Governmental agencies or as relieving the contractor or manufacturer of responsibility for the safety of his operations.

6.5.2 Personnel and equipment. Proper care must be exercised at all times to protect personnel from accidents, fires or explosions, and to limit damage to equipment and loading areas. In connection with the above, the precautionary measures in the following paragraphs should be observed. (See also 6.5.4, Static and electrical, and other applicable parts of these safety precautions.)

6.5.2.1 Keep explosives operations under strict supervision. Periodic inspections shall be employed to ensure compliance with established safety regulations.

6.5.2.2 Use safe equipment and methods when handling and transporting explosives and loaded parts.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.

6.5.2.3 Where required, use remote control, barricaded handling equipment for explosives operations such as mixing, pouring, weighing, charging, sifting, drying, pressing, casting, crimping, etc.

6.5.2.4 Employ properly proportioned and properly located protective barricades, screens, or shields at all required points.

6.5.2.5 Maintain equipment such as presses, dies, crimpers, blenders, mixers, sifters, conveyors, and the like, in safe operating condition.

6.5.2.6 Enforce, where necessary, the wearing of suitable safety footwear, gloves, goggles, respirators, and impregnated garments to protect personnel against burns, poisoning, and associated industrial hazards.

6.5.2.7 During static tests, restrain propulsion units such as rocket motors against full thrust to prevent flight if ignited (for example, during test of igniter circuit). Also employ means for harmlessly venting flames and exhaust gases.

6.5.3 Operating procedures. All loading operations shall be conducted in full accordance with a formalized operating procedure that shall include the following:

6.5.3.1 Keep only minimum, limited quantities of explosives and completed or partially loaded parts present at each stage of operations.

6.5.3.2 Allow no fires or exposed electrical or other sparking equipment, and little or no flammable material to be present in loading, handling, and storage spaces. Enforce proper "Match" and "No Smoking" rules where necessary.

6.5.3.3 Post appropriate safety instructions for specific operations and instruct personnel as to the hazards present and precautions involved.

6.5.3.4 Establish and post in each work space the number of working personnel and transients permitted in such areas. The number established shall be the minimum number required to accomplish necessary operations.

6.5.3.5 Conduct all loading operations in a neat and orderly manner.

6.5.3.6 Enforce good housekeeping procedures and maintain effective policing, inspection, and supervisory methods throughout the loading area and surroundings.

6.5.3.7 Employ effective cleaning methods periodically to minimize the accumulation of explosives or explosive dust and other contamination upon,

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.

and to ensure its removal from, floors, walls, ceilings, ledges, tables, benches, piping, and equipment or the items loaded. Clean up any spilled material immediately.

6.5.3.8 Control the exposure of explosive materials and related parts so as to minimize the absorption of moisture from the atmosphere or other sources during loading and handling operations.

6.5.3.9 Ensure that personnel handling detonators, primers, delay elements, lead-ins, boosters, and related parts which affect functioning, avoid, insofar as practicable, using bare fingers or improper equipment, in order to prevent damage, corrosion, or deterioration from perspiration or other contaminating deposits.

6.5.3.10 Keep explosives and explosive parts in approved covered receptacles with covers in place when material is not being taken out of or put into the receptacles. Where necessary, receptacles should be conductive to ground electrostatic charges. (See 6.5.4)

6.5.4 Static and electrical

6.5.4.1 Protect operations from electrostatic charges by effectively grounding all machinery, equipment, and fixtures; and, where necessary, employ suitable grounded conductive coverings for floors, work benches, tables, and workers' conductive shoes. Workers' clothing of a type to minimize the accumulation of static charges shall be employed. Fabrics, such as silk and nylon, which promote static generation shall be avoided. Additional grounding devices such as grounded bracelets for workers should be employed where operations are conducted with items which are unusually sensitive to initiation by static electricity. Such items include initiating explosives, tracer mixtures, and low energy type electric primers, detonators, and squibs. The latter types of items shall have the free ends of lead wires bared and twisted together, and shall be packed in relatively small groups wrapped in bare, noninsulated aluminum foil or other uncoated metal foil. During assembly and processing operations, such sensitive electric items should be short circuited by clips or other devices until installed with safety shunt in the final device. Additional precautions for these items should include mechanical shielding to contain or deflect fragments and blast, also electrical shielding from induced electric currents originated by sources such as lightning, static, electromagnetic radiations, etc. Where necessary for safety, humidity in work rooms should be appropriately increased, as required, to lessen electrostatic effects but without inducing excessive moisture absorption by any of the components of the item being processed.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.

6.5.4.2 Protect all explosive operations from effects of electric currents originating in equipment such as soldering irons, or guns, heaters, switches, wiring, motors, lights, test instruments, etc., by suitable insulation, grounding, separation, or shielding. Such electric sources may initiate explosives by heat, sparks, arcs, or due to the completion of an electric circuit through an electric primer, by detonator or squib. For example, circuits may be inadvertently completed from a defective electric soldering iron through a grounded contact. All electric type primers, detonators, or squibs provided with wire leads shall have the free ends of the wire bared and twisted together to short circuit each unit, except when in process of assembly into a finished item. Removable short circuiting clips, or other devices should be employed during manufacturing operations involving items such as electric primers, detonators, or squibs.

6.5.4.3 Where necessary, protect personnel and operations from electromagnetic energy. In certain work with very sensitive explosives or items, a shielded environment free from significant electromagnetic energy should be provided.

6.5.5 Operating facility and storage regulations. All explosives and completely or partially loaded items should be stored in suitable storage magazines located in accordance, at a minimum, with the American Table of Distances (ATD) and, while in process, in safety lockers and chests if in loading rooms or in adequate ready or service magazines located in accordance with Intraplant Distances set forth in the ATD when outside of loading rooms. For Navy-managed or contractor-managed Navy-owned explosives loading plants, the Armed Services Explosives Safety Board standards approved by the Department of Defense, the Secretary of the Navy, and the Naval Ordnance Systems Command, covering quantity-distance relations for explosives, apply."

Page 29. Replace Figure 1 with new Figure 1, attached.

Project No. 1355-N047

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.

Table IX

PERIODIC TEST SEQUENCE

I Tests	Sample and Test Sequence								
	II 1, 4, Etc.			III 2, 5, Etc.			IV 3, 6, Etc.		
	(3)	(3)	(3)	(3)	(3)	(3)	(3)	(3)	(3)
Inspection, Prior to Firing	1	1	1	1	1	1	1	1	1
Vibration, Ready Condition					2*				2*
Acceleration, Ready Condition									3*
Shock, Ready Condition								2*	4*
Temperature and Humidity		2						3	5
Jolt							2		
Jumble				2					
Forty Foot Drop	2								
Transportation Vibration			2						
Auto-Ignition, Low Temperature		3							6
Auto-Ignition, High Temperature			3				3		
Low Temperature, Operating		4						4	
High Temperature, Operating						2			
Accelerated Storage Life, Ready Condition					3				
Maximum No-Fire Current					4				7
Minimum Firing Current					5				
Maximum Firing Current									8
Inspection, Post Firing		5			6	3		5	9

*Visual Check After Testing

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.




FIGURE 1. PRESSURE-TYPE ENVELOPE

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.