MILITARY SPECIFICATION

REGULATOR ASSEMBLY, CARBON DIOXIDE PRESSURE

This amendment forms a part of Military Specification MIL-R-82441A(OS) dated 9 October 1974.

PAGE 4

Paragraph 3.3.5, line 2: Delete "4 ± 2 psig" and substitute "6 ± 4 psig."

PAGE 13

Delete paragraph 4.5.3(c) and substitute the following:

"(c) Case leakage. Cap the outlet port of the regulator and apply an inlet pressure of 135 ± 5 psig. Liberally apply leak detector fluid to all assembly interface areas on the regulator. Hold pressure for 5 minutes minimum. There shall be no evidence of continuous leakage (other than that permitted in 4.5.3(b) above)."

PAGE 14

Paragraph 4.5.3(d), last line: Delete "4 ± 2 psig" and substitute "6 ± 4 psig."

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commanding Officer, Naval Ordnance Station, Standardization Division (Code 501), Indian Head, MD 20640 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Preparing Activity
Navy-OS
(Project No. 1355-N401)

FSC 1355

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T07:08Z
Check the source to verify that this is the current version before use.