MIL-F-50726(MU)
28 April 1972
SUPERSEDING
FA-PD-MI-2725, Rev. 0
21 March 1967

MILITARY SPECIFICATION

FUZE, MTSQ, M564E2 ASSEMBLY
LESS BOOSTER PELLET AND CLOSING CUP (LEAD) CHARGE

1. SCOPE

1.1 This specification covers Fuze, MTSQ, M564E2 Assembly, less booster pellet and closing cup (Lead) charge.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal form a part of this specification to the extent specified herein.

SPECIFICATIONS

Military

MIL-P-60412	- Packaging, Packing and Marking for Shipment of Artillery Type and Rocket Fuzes, General Specification for

STANDARDS

Military

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-109	- Quality Assurance Terms and Definitions
MIL-STD-331	- Fuze and Fuze Components Environmental and Performance Test for
MIL-STD-414	- Sampling Procedures and Tables for Inspection by Variables for Percent Defective
MIL-STD-1167	- Ammunition Data Card

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

2.1 (Cont'd)

DRAWINGS

Munitions Command

F8864492	- Box, Ammunition, Metal for Artillery Type and Rocket Fuzes
F10520700	- Fuze, MTSQ, M564E2 Assembly
IEL-10520700	- Inspection Equipment List for Fuze, MTSQ, M564E2 Assembly

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

2.2 Other publication.-The following document forms a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on date of invitation for bids or request for proposal shall apply.

ASA-B46.1 - Surface Texture

(Application for copies should be addressed to the American National Standards Institute (ANSI), 1430 Broadway, New York, N.Y. 10018).

3. REQUIREMENTS

3.1 General.-Materials, parts and assemblies shall comply with the requirements specified on the applicable drawings, referenced standards and specifications except as provided in 6.1.

3.2 Dynamic regulation.-The movement subassembly shall be regulated to the frequency specified on the applicable drawing. The timing error between 2 to 100 seconds shall not exceed 0.07% while spinning at the specified revolutions per minute (rpm).

3.3 Environmental.

3.3.1 Jolt.-The fuze shall comply with MIL-STD-331, Test No. 101.

3.3.2 Jumble.-The fuze shall comply with MIL-STD-331, Test No. 102.

3.3.3 Forty-foot drop.-The fuze shall comply with MIL-STD-331, Test No. 103.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

3.3.4 Waterproofness.-The fuze shall comply with MIL-STD-331, Test No. 108, except that the duration of immersion shall be five (5) minutes and the pressure shall be three (3) psi gauge.

3.3.5 Transportation-vibration.-The fuze shall comply with MIL-STD-331, Test No. 104.

3.4 Ballistics (see 6.3.4)

3.4.1 The fuze shall not function prematurely (see 6.3.1)

3.4.2 Target impact nonfunction distance.-The fuze shall not initiate detonation of the round upon impact element function when fired in the 105MM Howitzer, Charge 7 (1550 feet per second, fps) with the fuze set safe "S" on a target 180 plus 5 feet from the muzzle of the weapon.

3.4.3 Target impact function distance.-The fuze shall initiate detonation of the round upon impact when fired in the 105MM Howitzer, Charge 7 (1550 fps) with the fuze set safe "S" on a target 400 minus 5 feet from the muzzle of the weapon.

3.4.4 Ground or water impact function.-The fuze shall initiate detonation of the round upon impact when fired as follows:

Weapon	Charge	Impact Angle	Setting
105MM Howitzer	1 (650 fps)	45° minimum	Safe "S"
105MM Howitzer	7 (1550 fps)	45° minimum	Safe "S"

3.4.5 Time-to-burst (Ambient Temperature).-The fuze shall initiate detonation of the round during flight within the time limits specified in Table I, when fired as follows:

Weapon	Charge	Setting
155MM Howitzer	1 (680 fps)	3 seconds
105MM Howitzer	7 (1550 fps)	60 seconds

TABLE I

Weapon	Charge	Fuze Setting	Individual Round Function Time Limits (seconds)	
155MM How.	1	3 second	UL	3.48
			LL	2.88
105MM How.	7	60 second	UL	60.50
			LL	58.90

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

3.4.6 Excess pressure.-The fuze shall initiate detonation of the round during flight when fired in the 105MM Howitzer at 112% of the normal charge 7 pressure with the fuze set at 60 seconds.

3.4.7 Low temperature.-The fuze temperature conditioned at minus 65 to minus 70 degrees Fahrenheit (F) shall initiate detonation of the round during flight when fired as specified in 3.4.5 (see 6.4).

3.4.8 High temperature.-The fuze temperature conditioned at plus 145 to plus 150 degrees Fahrenheit shall initiate detonation of the round during flight when fired as specified in 3.4.5 (see 6.4).

3.4.9 High and Low Temperature Conditioning.-For the high and low temperature firings only the fuze shall be temperature conditioned. The elapsed time for the conditioning chamber to the firing in the weapon shall not exceed five (5) minutes. Reconditioning is not permitted.

3.5 Workmanship.-The requirements for workmanship are as specified on the applicable drawings, referenced specifications and the following:

3.5.1 Metal defects.-All components shall be free from cracks, splits, cold shuts, inclusions, porosity or any similar defect.

3.5.2 Threads.-Threads shall be full and undamaged for the entire minimum length or depth as required by the applicable drawing.

3.5.3 Burr.-No part shall have a burr which might interfere with the assembly or function of the item or which might be injurious to personnel handling the item.

3.5.4 Foreign matter.-No part or assembly shall contain chips, dirt, grease, rust, corrosion or other foreign matter. The methods and agents used in process and cleaning shall not adversely affect the finish or contaminate the parts.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure that supplies and services conform to prescribed requirements.

4.1.1 Quality assurance terms and definitions.-Reference shall be made to MIL-STD-109 to define quality assurance terms used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.1.2 Lot formation.-Each inspection lot of fuzes shall be comprised of components (except explosive components) each produced by one manufacturer, by one process in accordance with the same drawing and revision and specification and revisions, as applicable, and assembled on one assembly line. Each explosive component within a lot of assembled fuzes shall be limited to one manufacturer and one interfix number.

4.2 First article sample.-When required, the first article sample shall be as specified in the contract and shall consist of the following:

340 (aggregate) component parts as delineated in 4.2.2
475 (aggregate) subassemblies as delineated in 4.2.3
147 (aggregate) fuze assemblies (Drawing F10520701) as delineated in 4.2.5 and 4.2.6.

The sample shall be manufactured using the same materials, equipment, processes and procedures as will be used in regular production. All parts and materials, including packaging and packing, shall be the same as used for production and shall be obtained from the same source of supply.

4.2.1 Examination and test.-After inspection by the contractor and provisional acceptance at source by the Government, 125 fuze assemblies shall be forwarded to a designated proving ground as specified in the contract. Three hundred and forty (340) component parts, 475 subassemblies and 22 fuze assemblies shall be inspected, as provided herein, at a Government laboratory or such other facility as specified in the contract.

4.2.2 Components.

4.2.2.1 Twenty (20) of each of the (17) component shall be tested as in 4.3.3.1 (Hardness). The firing arms shall be tested as in 4.3.3.2 (Bend).

4.2.3 Subassemblies.

4.2.3.1 Twenty-five (25) of each of the (15) subassembly shall be tested as in 4.3.3.5.1 (Static Load).

4.2.3.2 Twenty-five (25) of each of the (3) subassembly shall be tested as in 4.3.3.5.2 (Torque).

4.2.3.3 Twenty-five (25) of each assembly (1) shall be tested in 4.3.3.4 (Pull test).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.2.4 Acceptance criteria.-Failure of any component or subassembly to comply with the requirements of the applicable drawing for the above characteristics shall be cause for rejection of the first article sample.

4.2.5 Fuze assemblies.-Twenty-two (22) fuze assemblies shall be subjected to the following MIL-STD tests, with the fuzes set on safe "S".

Test	Quantity	Requirement	Test Method
Jolt	4	3.3.1	4.4.14.1
Jumble	4	3.3.2	4.4.14.2
Forty-foot drop	5	3.3.3	4.4.14.3
Waterproofness	4	3.3.4	4.4.14.4
Transportation-Vibration	5	3.3.5	4.4.14.5

4.2.5.1 Acceptance criteria.-The criteria of the applicable MIL-STD shall apply as determined by disassembly and examination in accordance with the procedures in 4.4.14. Where the accept/reject decision is based on engineering judgement, concurrence by the responsible technical agency must be obtained.

NOTE: Evidence of water entry through the D.A.M. flash hole or setback screw hole does not constitute reason for rejection.

4.2.6 Ballistics.-One hundred and twenty-five (125) fuzes, of the first article sample, shall be subjected to the following ballistic test phases.

Phases	Quantity	Requirement	Test Method
Target Impact Nonfunction Distance (Ambient Temperature)	20	3.4.1 & 2	4.4.15.1
Target Impact Function Distance (Ambient Temperature)	10	3.4.1 & 3	4.4.15.2
Ground or Water Impact Function (Ambient Temperature)			
105MM Howitzer Charge 1	5	3.4.1 & 4	4.4.15.3
105MM Howitzer Charge 7	5	3.4.1 & 4	4.4.15.3
Time-to-Burst (Ambient Temperature)			
155MM Howitzer Charge 1	20	3.4.1 & 5	4.4.15.4
105MM Howitzer Charge 7	20	3.4.1 & 5	4.4.15.4
Excess Pressure (Ambient Temperature)	25	3.4.1 & 6	4.4.15.5

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.2.6 (Cont'd)

Phases	Quantity	Requirement	Test Method
Low Temperature (-65 to -70 F)			
155MM Howitzer Charge 1	5	3.4.1 & 7	4.4.15.6
105MM Howitzer Charge 7	5	3.4.1 & 7	4.4.15.6
High Temperature (+145 to +150 F)			
155MM Howitzer Charge 1	5	3.4.1 & 8	4.4.15.6
105MM Howitzer Charge 7	5	3.4.1 & 8	4.4.15.6

4.2.6.1 Acceptance criteria.-The occurrence of any of the following shall be cause for rejection of the first article sample.

a. A premature burst in any phase (see 6.3.1)

b. Function of one or more rounds upon target impact in the Target Impact Nonfunction Distance Phase.

c. Failure of more than one round to function in the Target Impact Function Distance Phase.

d. Failure of more than one round to function in the Ground or Water Impact Function Phase.

e. Any of the following in the ambient Time-to-Burst Phase at each time setting.

(1) More than one time failure (6.3.2)

(2) More than one outlier-offtime (6.3.3)

(3) Failure to meet the limits specified in Table I by an estimated lot percent defective greater than the appropriate value given in Table II (see 4.4.15.4.1).

f. More than two time failures (6.3.2) in the Excess Pressure Phase.

g. More than two time failures (6.3.2) in either of the Environmental Phases (Low Temperature, High Temperature).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.2.6.1 (Cont'd)

TABLE II

3 Sec. Setting

Sample Size	Allowable Percent Defective
20	2.95
19	2.96
18	2.97
17	2.99
16	3.01
15	3.05

60 Sec. Setting

20	4.00
19	4.01
18	4.03
17	4.06
16	4.12
15	4.20

4.3 Inspection provisions.

4.3.1 Submission of product.-The product shall be presented in accordance with MIL-STD-105.

4.3.2 Examination.-One hundred percent examination shall be performed for all critical defects. Examination for defects shall be performed on a single defect basis in accordance with MIL-STD-105. For each classification of defects contained herein, the AQL given shall be applied to each major defect listed. All nonconforming material shall be rejected. The roughness comparison specimens prescribed by ASA-B46.1 shall be used as a basis of comparison for surface roughness determination. Four power (4X) magnification may be used in performing visual examination for such defects as burr and foreign matter.

4.3.2.1 Closing Cup, Drawing B8595508, covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
1. Split, cut or crack	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.1 (Cont'd)

Defect	Method of Inspection
MAJOR AQL = 1.0%	
101. Thickness of base, improper	Gage
102. Length under flange, improper	Gage
103. Outside diameter exceeds max.	Gage
104. Score, wrinkle or dent	Visual
105. Foreign matter	Visual

4.3.2.2 Booster Cup, Drawing C8595509, covering a detail of Drawing F10520700.

CRITICAL

None defined

MAJOR AQL = 1.0%	
101. Inside depth, improper	Gage
102. Pitch diameter of thread, improper	Gage
103. Minor diameter of thread exceeds max.	Gage
104. Outside diameter, improper	Gage
105. Effective length of thread, less than min.	Gage
106. Metal defective	Visual
107. Cut, score, or gouge on inside wall	Visual
108. Foreign matter	Visual

4.3.2.3 Pin, Setting Drawing B10520656 covering a detail of Drawing F10520700.

CRITICAL

None defined

MAJOR AQL = 1.0%	
101. Large diameter below min. allowable	Gage
102. Radius at base of small diameter	Visual
103. Length of small diameter	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.4 Plate No. 1 First Lamina Drawing F10523181 covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
None defined	
MAJOR AQL = 1.0%	
101. Diameter of holes M and 20, incorrect	Gage
102. Location of holes M and 20, incorrect	Gage
103. Surface finish of holes M and 20, improper	Visual
104. Metal burred or damaged	Visual
105. Chamfer on holes M and 20 missing or incorrect	Visual

4.3.2.5 Plate No. 2 Second Lamina Drawing F8595968, covering a detail of Drawing F10520700.

CRITICAL	
None defined	
MAJOR AQL = 1.0%	
101. Diameter of holes M and 20, incorrect	Gage
102. Location of holes M and 20, incorrect	Gage
103. Surface finish of holes M and 20, improper	Visual
104. Metal burred or damaged	Visual
105. Chamfer on holes M and 20 missing or incorrect	Visual

4.3.2.6 Plate No. 2 First Lamina Drawing F8595967, covering a detail of Drawing F10520700.

CRITICAL	
None defined	
MAJOR AQL = 1.0%	
101. Flatness incorrect	Gage
102. Metal burred or damaged	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.7 Slide, Pallet Lock Drawing C10521169, covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
1. Large radius on extension above max.	Gage
MAJOR	
None defined	

4.3.2.8 Gear, Escapement Drawing D10542765 covering a detail of Drawing F10520700.

CRITICAL	
None defined	
MAJOR AQL = 1.0%	
101. Tooth profile, incorrect	Gage
102. Surface finish, improper	Visual

4.3.2.9 Plate No. 7 Drawing F10520737 covering a detail of Drawing F10520700.

CRITICAL	
None defined	
MAJOR AQL = 1.0%	
101. Outside diameter, incorrect	Gage
102. Surface finish on O.D., improper	Visual
103. Burr	Visual

4.3.2.10 Escapement Gear and Pinion Assembly Drawing C10542766 covering a detail of Drawing F10520700.

CRITICAL	
None defined	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.10 (Cont'd)

Defect	Method of Inspection
MAJOR AQL = 1.0%	
101. Eccentricity of gear with datum	Gage
102. Perpendicularity of gear, incorrect	Gage
103. Burr	Visual

4.3.2.11 Escapement Lever Assembly Drawing D10551145 covering a detail of Drawing F10520700.

CRITICAL

None defined

MAJOR AQL = 1.0%	
101. Perpendicularity of lever with datum incorrect	Gage
102. Spring burred or damaged	Visual
103. Improper assembly	Visual

4.3.2.12 Arbor, Escapement Drawing D10535526 covering a detail of Drawing F10520700.

CRITICAL

None defined

MAJOR AQL = 1.0%	
101. Perpendicularity of lever seat with datum C, incorrect	Gage
102. Diameter of pivots, incorrect	Gage
103. Metal burred or damaged	Visual

4.3.2.13 Head Drawing D10542776 covering a detail of Drawing F10520700.

CRITICAL

None defined

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.13 (Cont'd)

Defect	Method of Inspection
MAJOR AQL = 1.0%	
101. Diameter at forward datum length, incorrect	Gage
102. Diameter at rear datum length, incorrect	Gage
103. Runout at datum lengths	Gage

4.3.2.14 Firing Pin, Drawing C10521154, covering a detail of Drawing F10520700.

CRITICAL

None defined

MAJOR AQL = 1.0%	
101. Diameter of striker point, improper	Gage
102. Surface finish on shoulder angle, improper	Visual

4.3.2.15 Firing Pin, Drawing B10542778 covering a detail of Drawing F10520700.

CRITICAL

1. Diameter of neck area exceeds max.	Gage
2. Length of striker exceeds max.	Gage
3. Diameter of body over the striker less than min.	Gage
4. Corner radius of body shoulder exceeds max.	Gage
MAJOR AQL = 1.0%	
101. Diameter of neck area less than min.	Gage
102. Diameter of body over the striker exceeds max.	Gage
103. Diameter of striker point, improper	Gage
104. Run out of striker diameter	Gage

4.3.2.16 Plug, Closing Drawing D10520733 covering a detail of Drawing F10520700.

CRITICAL

None defined

MAJOR AQL = 1.0%	
101. Location of locating pin hole incorrect	Gage

Source: https://assist.dla.mil - Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.17 Cap, Drawing F10520711 covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
1. Letter "S" and arrowhead not over its respective line	Visual
MAJOR AQL = 1.0%	
101. Diameter of large cavity, incorrect	Gage
102. Diameter incorrect at forward datum length	Gage
103. Diameter incorrect at rear datum length	Gage
104. Cumulative error of time scale exceeds max. (to be measured from zero line to 3, 30, 60 and 90 second lines)	Gage
105. Location of zero line, incorrect	Gage
106. Diameter of small hole between spotface exceeds max.	Gage
107. Location of numerals, incorrect	Visual
108. Relief groove in small hole, missing	Visual
109. Spot face, missing	Visual
110. Surface finish of large cavity, improper	Visual

4.3.2.18 Body (Fuze) Drawing F10520709 covering a detail of Drawing F10520700.

CRITICAL	
1. Minor diameter of internal thread exceeds max.	Gage
MAJOR AQL = 1.0%	
101. Pitch diameter of internal thread, improper	Gage
102. Eccentricity of pitch diameter of D.A.M. cavity thread with datum "C" excessive	Gage
103. Major diameter of external thread, improper	Gage
104. Pitch diameter of external thread, improper	Gage
105. Diameter of internal flange (mid-section) incorrect	Gage
106. External diameter at forward datum incorrect	Gage
107. External diameter at rear datum incorrect	Gage
108. Threads damaged or not full	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.19 Base, Movement Drawing F10520728 covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
None defined	
MAJOR AQL = 1.0%	
101. Location of closing plug locating hole incorrect	Gage

4.3.2.20 Ring, Locking, Drawing C10520731 covering a detail of Drawing F10520700.

CRITICAL	
1. Large I.D. exceeds max.	Gage
2. Major diameter of thread, below min.	Gage
MAJOR AQL = 1.0%	
101. Pitch diameter of thread, improper	Gage

4.3.2.21 Body and Cap Assembly, Drawing F10520720 covering a detail of Drawing F10520700.

CRITICAL	
None defined	
MAJOR AQL = 1.0%	
101. Wave washer missing	Visual
102. Snap ring missing	Visual
103. Threads damaged or not full	Visual
104. Improper or incomplete assembly	Visual

4.3.2.22 Ring Reinforcing, Drawing B10520736 covering a detail of Drawing F10520700.

CRITICAL	
1. O.D. below min.	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.22 (Cont'd)

Defect	Method of Inspection
MAJOR AQL = 1.0%	
None defined	

4.3.2.23 Body, Delay Arming Mechanism Drawing D10520703 covering a detail of Drawing F10520700.

CRITICAL	
1. Major diameter of large external thread, less than min.	Gage
2. Large straight I.D. exceeds max.	Gage
MAJOR AQL = 1.0%	
101. Pitch diameter of large external thread, improper	Gage
102. Major diameter of small external thread, improper	Gage
103. Pitch diameter of small external thread, improper	Gage
104. Depth of set back screw hole, incorrect	Gage
105. Threads damaged or not full	Visual

4.3.2.24 Detonator Screw Assembly Drawing C10520294, covering a detail of Drawing F10520700.

CRITICAL	
1. Detonator extends above flush of detonator screw	Visual
MAJOR AQL = 0.40%	
101. Green end of detonator not at bottom (thread end)	Visual
102. Crimping inadequate	Visual
103. Thread damaged	Visual

4.3.2.25 Detent Safety Mechanism Assembly, Drawing F10520250, covering a detail of Drawing F10520700.

CRITICAL	
1. Length from top of detents to bottom of housing less than min.	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.25 (Cont'd)

Defect	Method of Inspection
MAJOR AQL = 0.40%	
101. Improper or incomplete assembly	Manual/Visual
102. Staking of cover to housing inadequate	Visual
103. Foreign matter	Visual

4.3.2.26 Cap Assembly Drawing D10520710 covering a detail of Drawing F10520700.

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Protrusion of pin improper	Gage
102. Edge of hammer spring not contacting surface "A"	Visual
103. Threads damaged or not full	Visual
104. Burr	Visual

4.3.2.27 Firing Arm Assembly, Drawing C10521115, covering a detail of Drawing F10520700.

CRITICAL	
1. Fracture of upright bend of firing arm	Visual
2. Firing arm not staked to shaft	Visual
MAJOR AQL = 0.40%	
101. Insecure weight	Manual/Visual
102. Improper or incomplete assembly	Visual
103. Metal burred or damaged	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.28 Timing Disc Assembly, Drawing D10520653 covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
1. Safety disc tabs not engaged with timing disc bushing slots	Visual
MAJOR AQL = 0.40%	
101. Safety disc radius below periphery of timing disc	Visual
102. Improper or incomplete assembly	Visual

4.3.2.29 Movement Subassembly (after dynamic regulation) Drawing F10520716 covering a detail of Drawing F10520700.

CRITICAL	
1. Firing pin fires on "not fire" position of firing arm	Gage
2. Extension of firing arm upright above top plate less than minimum (with firing arm shaft shoulder bottomed on plate No. 2)	Gage
*3. Escapement gear not locked in sufficiently by lever pallet *(check after rewind and removal of backlash)	Visual
MAJOR AQL = 0.40%	
101. Firing pin does not fire on "must fire" position of firing arm	Gage
102. Firing pin protrusion less than min. in fired position	Gage
103. Extension of firing arm upright above top plate exceeds maximum (with firing arm shaft shouldered against top plate).	Gage
104. Firing pin protrudes	Manual/Visual
105. Staking of body assembly screws inadequate (check prior to dynamic regulation)	Visual
106. Arbor center hole missing	Visual
107. Escapement lever not locked on proper side of pallet lock slides	Visual
108. Firing pin striker point damaged	Visual
109. Foreign matter	Visual
110. Firing arm shaft spring protrudes	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.30 Movement Assembly - Drawing F10520715 covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
1. Drop off edge of firing arm outside of lines on safety disc	Visual
2. Timing disc bushing loose on knurl of arbor (check prior to assembly of locknut).	Manual/Visual
3. Timing disc retainer insecure, missing or fractured at bend	Manual/Visual
4. Distance from top of top plate to underside of retainer exceeds max.	Gage
MAJOR AQL = 0.40%	
101. Clearance between No. 7 plate and safety disc below min. allowable	Gage
102. Interference of the timing disc retainer with the safety disc	Visual
103. Staking of assembly screws inadequate	Visual
104. Foreign matter	Visual
105. Improper or incomplete assembly	Visual

4.3.2.31 Body, Movement and Cap Assembly Drawing F10520708, covering a detail of Drawing F10520700.

CRITICAL	
1. Setting pin not engaged in timing disc tab slot	Visual
2. Timing disc tab not contacting setting pin shoulder	Visual
3. Primer extends above flush	Visual
MAJOR AQL = 0.40%	
101. Primer missing or installed incorrectly (red end not visible)	Visual
102. Movement not properly secured by locking ring	Visual
103. Burr	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.32 Head Assembly Drawing D10542782, covering a detail of Drawing F10520700.

Defect	Method of Inspection
CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Firing pin guide missing	Visual
102. Firing pin missing	Visual
103. Staking missing or inadequate	Visual
104. Thread damaged	Visual
105. Burr	Visual
106. Foreign matter	Visual

4.3.2.33 Setback Mechanism Assembly Drawing D10551357, covering a detail of Drawing F10520700.

CRITICAL	
None defined	
MAJOR AQL = 0.40%	
101. Length from shoulder to top of pin less than min. allowable (to be checked after the load test, see 4.3.3.8.1)	Gage
102. Crimp missing or inadequate	Visual
103. Thread damaged or not full	Visual

4.3.2.34 Mechanism, Delay Arming Assembly Drawing F10520702 covering a detail of Drawing F10520700.

CRITICAL	
1/ 1. Setback mechanism assembly not restricting movement of the rotor	Gage
2. Rotor not locked in the unarmed position (see 6.2.2) (to be checked immediately prior to assembly into fuze)	Visual

1/ NOTE: Manually disengage both spring loaded blocks from rotor gear and apply a push load of 1 ± 0.5 pound to the rotor through the kidney hole. After this check, the rotor gear shall be fully re-engaged by both spring loaded blocks.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.34 (Cont'd)

	Defect	Method of Inspection
MAJOR	AQL = 0.40%	
101.	Length from base of body to top plate including all protrusions exceeds max.	Gage
102.	Bulge or protrusion on the base surface	Visual
103.	Staking of screw(s) inadequate	Visual
* 104.	Detonator installed incorrect (with yellow end at crimp)	Visual
* 105.	Staking or crimping of detonator inadequate	Visual
106.	Foreign matter	Visual
	*(to be checked prior to assembly of top plate)	

4.3.2.35 Fuze, Subassembly Drawing F10520701 covering a detail of Drawing F10520700.

CRITICAL		
1.	Reinforcing ring missing (to be checked prior to assembly of D.A.M.)	Visual
2.	Fuze not set on safe "S" (to be checked immediately prior to packaging	Visual
3.	Delay arming mechanism rotor armed or partially armed as viewed through the flash hole (to be checked immediately prior to packaging)	Visual
* 4.	Detent safety mechanism missing	Visual
* 5.	Detent safety mechanism above flush	Visual
	*(check prior to assembly of head assembly)	
MAJOR	AQL = 0.40%	
101.	Total length, exceeds max.	Gage
102.	M47 detonator missing (to be checked prior to assembly of closing plug)	Visual
103.	Relay improperly inserted in closing plug (closed end not visible - to be checked prior to assembly of D.A.M.)	Visual
104.	Staking of closing plug screws inadequate	Visual
105.	Threads damaged	Visual
106.	Marking missing, incorrect or illegible	Visual
107.	Dust cover (over flash hole) missing	Visual
108.	Sealing compound missing or inadequate	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.36 Packing, packing and marking.-The sample size and acceptance criteria for packaging, packing and marking shall be in accordance with MIL-P-60412, except as specified in paragraph 5.1.1.

4.3.2.37 Process control audit.-Periodic unscheduled monitoring shall be conducted for the process operations on the following assemblies to determine compliance with the requirements of the applicable drawings. Bending adjustment of the firing arm upright is not permitted at any time.

a. Laminated Plates No. 1 and No. 2 Assembly, Drawing F10542853.

(1) Application of lubricant

b. Movement Subassembly, Drawing F10520716

(1) Application of lubricant

(2) Top and bottom assembly screws staked prior to dynamic regulation

(3) Mainspring wound before assembly of flat headscrew

(4) Dynamic regulation operation (see 4.4.9.2)

(5) Movement fully wound after dynamic regulation

c. Escapement Lever Assembly, Drawing D10551145

(1) Securing escapement lever spring

d. Movement Assembly, Drawing F10520715

(1) Locknut torqued prior to timing disc torque test

e. Body and Cap Assembly, Drawing F10520720

(1) Insertion of "O" ring between cap and body

(2) Fuze setting torque

f. Movement D.A.M. Assembly, Drawing F10520704

(1) Staking of plate screws prior to arming and nonarming test

(2) Lubrication

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.2.37 (Cont'd)

g. Mainspring Housing and Arbor Assembly, Drawing F10520717

(1) Assembly of #5 gear and arbor assembly for static load and torque test (see 4.3.3.5)

(2) Staking of lug and push test

h. Fuze Subassembly, Drawing F10520701

(1) Application of lubricant

(2) Application of sealant

(3) Insertion of dessicant pellet and cushion

(4) Insertion of "O" ring between head and cap

(5) Head torque operation (note 8)

(6) D.A.M. tightening operation (note 9)

4.3.3 Inspection testing.-The following tests shall be performed in accordance with the provisions of 4.4.

4.3.3.1 Hardness (destructive).-Twenty samples from each lot of the following components shall be subjected to the hardness test. Where plating is required, the sample parts tested shall be unplated, where feasible. Failure of any component to comply with the requirements specified on the applicable drawing shall be cause for rejection of the lot of components, as applicable (see 4.4.1).

Component	Drawing Number
Pin, Firing	C10521154
Arbor, escapement	D10535526
Gear, escapement	D10542765
Pinion, escapement	D10521101
Pinion, No. 1	D10521119
Pinion, No. 2	D10521120
Pinion, No. 3	D10521118
Pinion, No. 4	C10521123
Wheel, escape (D.A.M.)	D10523171
Arm, firing (see 4.3.3.2)	D10521116
Guide, adjusting	C8594273
Lever, escapement	C10551070 or 10551071
Spring, hammer	C10520713
Spring, timing disc	C10520645
Washer, wave	C10520664
Pin pallet	B10523175
Ring, Snap	C10520724

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.3.2 Bend - firing arm (destructive).-The same 20 firing arms that comply with the hardness requirement shall be subjected to the bend specified on Drawing D10521116. Failure of any firing arm to comply with the requirements shall be cause for rejection of the lot of firing arms (see 4.4.2).

4.3.3.3 Compression - springs (destructive).-Twenty firing pin springs from each lot shall be subjected to the compression specified on Drawing C10521132. Failure of any spring to comply with the requirement shall be cause for rejection of the lot of firing pin springs (see 4.4.3).

4.3.3.4 Pull test - escapement spring (nondestructive).-Twenty-five (25) escapement springs from each lot of escapement lever assemblies shall be tested to determine compliance with the requirement of Drawing D10551145. Failure of any spring to comply with the requirement shall be cause for rejection of the lot of escapement lever assemblies (see 4.4.4).

4.3.3.5 Static load and torque.

4.3.3.5.1 Static load.-Twenty-five (25) samples from each lot of the following subassemblies shall be subjected to the static load test. Failure of any subassembly to comply with the requirement specified on the applicable drawing shall be cause for rejection of the lot of subassemblies, as applicable (see 4.4.5 and 6.6).

Static Load	Drawing Number
Escapement Gear and Pinion Assembly	C10542766
Escapement Lever and Arbor Assembly	D10551798
Firing Arm Assembly (Test Pin and Arm)	C10521115
No. 1 Gear and Pinion Assembly	D10521102
No. 2 Gear and Pinion Assembly	C10521104
No. 3 Gear and Pinion Assembly	C10521106
No. 4 Gear and Pinion Assembly	C10521111
Detent Safety Mechanism Assembly	F10520250
Pallet Lock Assembly	B10521168
Lever Assembly	B10521148
Escape Wheel Assembly (D.A.M. Assembly)	D10523170
No. 1 Gear and Pinion Assembly (D.A.M. Assembly)	D10523167
Pallet Assembly (Pins and Shaft)	D10523174
*Mainspring Housing and Arbor Assembly (Push on Lug)	F10520717
Closing Plug Loading Assembly	D10520732

* Arbor, Drawing C10520648 and Gear #5, Drawing C10521117 only shall be assembled for static load and torque test sample, using the same assembly methods and equipment that shall be used in production of Mainspring Housing and Arbor Assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.3.5.2 Torque.-Twenty-five (25) samples from each lot of the following subassemblies shall be subjected to the torque test. Failure of any subassembly to comply with the requirement specified on the applicable drawing shall be cause for rejection of the lot subassemblies, as applicable (see 4.4.5 and 6.6).

Torque	Drawing Number
Escapement Gear and Pinion Assembly	C10542766
Escapement Lever and Arbor Assembly	D10551798
*Mainspring Housing and Arbor Assembly	F10520717 - Reference only

* Arbor, Drawing C10520648 and Gear #5, Drawing C10521117 only shall be assembled for static load and torque test sample, using the same assembly methods and equipment that shall be used in production of Mainspring Housing and Arbor Assembly.

4.3.3.6 Hammerspring deflection (nondestructive).-Hammersprings from each lot of hammerspring assemblies shall be tested to determine compliance with the load requirement of Drawing F10520710. The sample size and criteria for acceptance shall be as specified in MIL-STD-105, using an AQL of 1.0 percent (see 4.4.6).

4.3.3.7 Nest pushout - head assembly (destructive).-Twenty (20) head assemblies from each lot of head assemblies produced shall be tested to determine compliance with the nest pushout requirement of Drawing D10542782. Failure of any nest to comply with the requirement shall be cause for rejection of the lot of head assemblies (see 4.4.7).

4.3.3.8 Setback mechanism assembly.

4.3.3.8.1 Load (nondestructive).-Each setback mechanism assembly produced shall be tested to determine compliance with the load requirement of Drawing D10551357. Failure to comply with the requirement shall be cause for rejection of the setback mechanism assembly (see 4.4.8).

4.3.3.9 Movement subassembly.

4.3.3.9.1 Kinetic energy of firing pin (nondestructive).-Fifty (50) movement subassemblies from each lot produced shall be tested to determine compliance with the requirement of Drawing F10520716. Failure of any firing pin to comply with the requirement shall be cause for rejection of the lot of movement subassemblies (see 4.4.9.1).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.3.9.2 Dynamic regulation (nondestructive).-The regulation tape record (100 seconds) of each movement subassembly produced shall be inspected to determine acceptability of the movement. Any movement subassembly which fails to comply with the requirement of 3.2 shall be rejected (see 4.4.9.2).

4.3.3.9.3 Spin function (nondestructive).-The pallet lock and safety lever assemblies within each movement subassembly produced shall be tested to determine compliance with the function requirement of Drawing F10520716. Failure to comply with the requirement shall be cause for rejection of the subassembly (see 4.4.9.3).

4.3.3.9.4 Spin nonfunction (nondestructive).-Each movement subassembly produced shall be tested to determine compliance with the nonfunction requirement of Drawing F10520716. Failure of the lever lock slides to remain in the locked position shall be cause for rejection of the subassembly (see 4.4.9.4).

4.3.3.10 Timing disc torque (nondestructive).-The timing disc of each movement assembly produced shall be tested to determine compliance with the torque requirement of Drawing F10520715. Failure to comply with the requirement shall be cause for rejection of the movement assembly (see 4.4.10).

4.3.3.11 Delay arming mechanism assembly less setback mechanism assembly.

4.3.3.11.1 Spin arming (nondestructive).-Each D.A.M. assembly produced shall be tested to determine compliance with the arming requirement of Drawing F10520702. Failure of the rotor to become locked in alignment with the flash hole, when spun at the arming spin requirement on the drawing shall be cause for rejection of the assembly (see 4.4.11.1).

4.3.3.11.2 Spin nonarming (nondestructive).-Each D.A.M. assembly produced shall be tested to determine compliance with the nonarming requirement of Drawing F10520702. Failure of both spring loaded blocks to remain engaged in the rotor recesses, when spun at the nonarming spin requirement on the drawing shall be cause for rejection of the assembly (see 4.4.11.2).

4.3.3.12 Detent safety mechanism.

4.3.3.12.1 Arming (nondestructive).-Each detent safety mechanism produced shall be tested to determine compliance with the arming requirement of Drawing F10520250. Failure to comply with the requirement shall be cause for rejection of the assembly (see 4.4.12).

4.3.3.12.2 Nonarming (nondestructive).-Each detent safety mechanism produced shall be tested to determine compliance with the nonarming requirement of Drawing F10520250. Failure to comply with the requirement shall be cause for rejection of the assembly (see 4.4.12).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.3.13 Fuze subassembly.

4.3.3.13.1 Setting torque (nondestructive).-Each fuze subassembly produced shall be tested to determine compliance with the setting torque requirement of Drawing F10520701. Failure to comply with the requirement shall be cause for rejection of the fuze subassembly (see 4.4.13.1).

4.3.3.13.2 Breakaway torque - head assembly (destructive).-Twenty (20) head assemblies from each lot of fuze subassemblies produced shall be tested to determine compliance with the breakaway torque requirements of Drawing F10520701. Failure to comply with the requirements shall be cause for rejection of the lot of fuze subassemblies (see 4.4.13.2).

4.3.3.14 Environmental tests (lots) (destructive).-Twenty-two (22) fuze assemblies from each production lot shall be subjected to the following MIL-STD tests, with the fuzes set safe "S".

Test	Quantity	Requirement	Test Method
Jolt	4	3.3.1	4.4.14.1
Jumble	4	3.3.2	4.4.14.2
Forty-foot drop	5	3.3.3	4.4.14.3
Waterproofness	4	3.3.4	4.4.14.4
Transportation-Vibration	5	3.3.5	4.4.14.5

4.3.3.14.1 Acceptance criteria.-Lot acceptance criteria shall be as specified in 4.2.5.1.

4.3.3.15 Ballistics (destructive).-Eighty (80) fuzes from each lot shall be subjected to the following ballistic test phases:

Phases (ambient temperature)	Quantity	Requirement	Test Method
Impact Nonfunction Distance	20	3.4.1 & 2	4.4.15.1
Impact Function Distance	10	3.4.1 & 2	4.4.15.2
Ground or Water Impact			
105MM Howitzer Charge 1	5	3.4.1 & 4	4.4.15.3
105MM Howitzer Charge 7	5	3.4.1 & 4	4.4.15.3
Time-to-Burst			
155MM Howitzer Charge 1	20	3.4.1 & 5	4.4.15.4
105MM Howitzer Charge 7	20	3.4.1 & 5	4.4.15.4

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.3.3.15.1 Acceptance criteria.-The occurrence of any of the following shall be cause for rejection of the lot the ballistic sample represents:

a. A premature burst in any phase (see 6.3.1)

b. Function of one or more rounds upon target impact in the Impact Nonfunction Distance Phase

c. Failure of more than one round to function in the Impact Function Distance Phase

d. Failure of more than one round to function in the Ground or Water Impact Function Phase

e. Any of the following in the Ambient Time-to-Burst Phase at any time setting

(1) More than one time failure (6.3.2)

(2) More than one outlier-offtime (6.3.3)

(3) Failure to meet the limits specified in Table I by an estimated lot percent defective greater than the appropriate value given in Table II (see 4.4.15.4.1).

4.3.4 Inspection equipment.-The examinations and tests shall be made using equipment listed in IEL-10520700. Equipment design shall be in accordance with the code designation on the applicable IEL.

4.4 Test methods and procedures.

4.4.1 Hardness.-Samples shall be tested in an area which is solidly supported in order to obtain valid readings. The median value of three hardness readings taken on each sample unit shall be used as the individual value.

4.4.2 Bend (firing arm).-The test shall be performed as specified on Drawing D10521116. The firing arms that have been subjected to the bend test shall be scrapped.

4.4.3 Compression.-The firing pin springs shall be compressed for the length of time specified on Drawing C10521132. The springs that have been subjected to the compression test shall be scrapped.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.4.4 Pull test (escapement spring).-The test shall be performed prior to cutting the spring to proper length. Caution shall be exercised so no bending or twisting of the spring occurs during test. The value as specified on Drawing D10551145 (escapement lever assembly) shall be used.

4.4.5 Static load and torque.-Escapement lever assemblies shall be tested prior to insertion of the escapement lever spring. The test shall be performed using the values as specified on the applicable drawing. All samples tested shall be scrapped, except Mainspring Housing and Arbor Assembly on which the lug was subjected to a push test (see 4.3.2.35, g).

4.4.6 Hammerspring deflection (simulated cap assembly).-The required load shall be applied at the specified location parallel to the vertical axis of the assembly as specified on Drawing F10520710. The test shall be performed using a fixture simulating the cap assembly and location therein.

4.4.7 Nest push out (head assembly).-The test shall be performed after the unit has been cured per Drawing B10542789, using the values as specified on Drawing D10542782. The head assemblies that have been subjected to the nest push out shall be scrapped.

4.4.8 Setback mechanism assembly.

4.4.8.1 Load.-The test shall be performed using the value specified on Drawing D10551357. The load shall be applied gradually.

4.4.9 Movement subassembly.

4.4.9.1 Kinetic energy of firing pin.-The assembly shall be placed in a fixture and tested for kinetic energy by releasing the firing pin from the cocked position.

4.4.9.2 Dynamic regulation.-The following procedure shall be observed: The movement subassemblies shall be regulated, using the operational procedures furnished with the equipment. The movement subassemblies shall be rotated in a clockwise direction when viewed from the bottom at a constant speed of 6,000 plus or minus 15 rpm. Timekeeping and performance shall be recorded over a period of not less than 100 seconds. No adjustment shall be made on the escapement during the 100 second check run.

4.4.9.3 Spin function.-The completely wound subassembly shall be spun in a clockwise direction when viewed from number one plate end at a constant rpm as specified on Drawing F10520716. The duration of spin shall be for a period of not less than ten seconds. The movement subassembly shall begin functioning immediately at the specified rpm and the lever assembly shall be released (contacting the periphery of the collar) after spinning for ten (10) seconds. At the conclusion of the test, the subassembly shall be rewound. The function test shall be performed prior to the nonfunction test.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.4.9.4 Spin nonfunction.-The completely wound subassembly shall be spun in a clockwise direction when viewed from number one plate end at a constant rpm as specified on Drawing F10520716. The duration of spin shall be for a period of not less than three (3) seconds. Nonfunction shall be determined by use of a strobe light. This test shall be the last spin test to which the movement is subjected.

4.4.10 Timing disc torque.-The torque test shall be performed after assembly of the timing disc assembly to the movement and assembly of the locknut on the arbor. The highest and lowest readings will be taken in one uninterrupted complete revolution of the timing disc for determination of compliance with the requirements of Drawing F10520715.

4.4.11 Delay arming mechanism assembly less setback mechanism assembly.

4.4.11.1 Spin arming.-The unarmed D.A.M. assembly shall be spun in a counterclockwise direction when viewed from movement plate end at a constant rpm as specified on Drawing F10520702. The duration of spin shall be three (3) seconds maximum. Arming shall be determined by use of a strobe light. At the conclusion of the test, the rotor shall be returned to the unarmed position (see 6.2.1 and 6.2.2).

4.4.11.2 Spin nonarming.-The unarmed D.A.M. assembly shall be spun in a counterclockwise direction when viewed from movement plate end at a constant rpm as specified on Drawing F10520702. The duration of spin shall be three seconds minimum. Nonarming shall be determined by use of a strobe light. The nonarming test shall be performed subsequent to the arming test and shall be the last spin test to which the D.A.M. assembly is subjected prior to assembly into the fuze.

4.4.12 Arming and nonarming (Detent Safety Mechanism).-The assembly shall be spun in the counterclockwise direction when viewed from the cover plate end at the rpm specified on Drawing F10520250. The arming test shall be performed prior to the nonarming test. Arming and nonarming shall be determined by use of a strobe light.

4.4.13 Fuze subassembly.

4.4.13.1 Setting torque.-The test shall be performed using the values as specified on the applicable drawing. The highest and lowest readings will be taken in one uninterrupted complete revolution of the lower cap for determination of compliance with the requirement of Drawing F10520701.

4.4.13.2 Breakaway torque.-The test shall be performed in accordance with the requirements on Drawing F10520701.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.4.14 Environmental tests.-The procedures used shall be as set forth in the following subparagraphs, as applicable. Where spin testing is required, the nonarming or nonfunction test shall be performed prior to the arming or function test. The components of the disassembled fuzes shall be scrapped. All adverse conditions observed shall be reported to the responsible engineering element.

4.4.14.1 Jolt.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 101 with the fuze orientations in the following sequency:

a. Nose down
b. Horizontal
c. Nose up

4.4.14.1.1 The fuze shall be disassembled and inspected as follows:

a. Prior to disassembly, check position of "S" line relative to zero line. Check position of rotor through the flash hole.
b. Remove welsh plugs and check engagement of setting pin with timing disc.
c. Remove head and check for detent assembly, detonator and firing pin.
d. Remove D.A.M. and check position of blocks. Manually release blocks and apply push load against rotor through kidney hole (where rotor is found in the unarmed position).
e. Remove reinforcing ring and closing plug, check relay.
f. Remove movement from body. Check position of safety disc lines relative to firing arms. Check timing disc torque, position of lever back slides and for separation of movement plates.
g. Spin detent safety mechanism for nonarming and arming.
h. Disassemble major subassemblies to the extent that all critical parts can be examined, such as gear and pinion assemblies, etc., for security of assembly, broken or bent pivots and teeth, fractured or bent firing arm or shaft or other part which might allow accidental release of firing pin. Check condition of all explosive elements.

4.4.14.2 Jumble.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 102. The fuze shall be disassembled and inspected as outlined in 4.4.14.1.1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.4.14.3 Forty-foot drop.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 103. The fuze shall be disassembled and inspected as follows:

a. Prior to disassembly, check position of rotor through the flash hole.
b. Remove D.A.M. and check position of blocks. Manually release blocks and apply push load against rotor through kidney hole (where rotor is found in the unarmed position).
c. Remove D.A.M. cover plate and check condition of parts (where rotor is found in a partially armed or fully armed position).

4.4.14.4 Waterproofness.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 108 except as provided in 3.3.4. The D.A.M. setback screw and flash hole shall be adequately sealed for the test. The fuze shall be diasssembled and inspected as follows:

a. Prior to disassembly, remove seal from flash hole and check position of rotor.
b. Remove D.A.M. head, movement assembly, check all internal surfaces for evidence of water entry.

4.4.14.5 Transportation-vibration.-The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 104 with the fuze orientations in the following sequence:

a. Parallel to longitudinal axis, nose up.
b. First transverse axis to be parallel to a line running through the 100 second marking.
c. Second transverse axis to be parallel to a line running through the 70 second marking.

4.4.14.5.1 The fuze shall be disassembled and inspected as follows:

a. Prior to disasssembly, check position of "S" line relative to zero line. Check position of rotor through the flash hole.
b. Remove welsh plugs and check engagement of setting pin with timing disc.
c. Remove head and check for detent assembly, detonator and firing pin. Spin detent assembly for nonarming and arming.
d. Remove D.A.M. and check position of blocks. Remove setback mechanism assembly and test pin for deflection requirements of Drawing 10551663. Spin D.A.M. for nonarming and arming.
e. Remove movement from body. Check position of safety disc lines relative to firing arm. Check timing disc torque, position of lever lock slide. Spin movement for nonfunction and function.
f. Disassemble major subassemblies to the extent that all critical parts can be examined, such as gear and pinion assemblies, etc., for broken or bent pivots and teeth, fractured or bent firing arm or shaft or other part which might allow accidental release of firing pin. Check condition of all explosive elements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.4.15 Ballistics.-The complete fuze assembly, Drawing F10520700 shall be assembled to a suitable projectile and fired as follows (see 6.3.4).

4.4.15.1 Target impact nonfunction distance phase.-The sample fuzes shall be fired as specified in 3.4.2 against a suitably supported one inch plywood screen of adequate size under the conditions delineated in 4.2.6 or 4.3.3.15 as appropriate. Observation of impact element function is required.

4.4.15.2 Target impact function distance phase.-The sample fuzes shall be fired as specified in 3.4.3 against a suitably supported one inch plywood screen of adequate size under the conditions delineated in 4.2.6 or 4.3.3.15 as appropriate.

4.4.15.3 Ground or water impact function phase.-The sample fuzes shall be fired as specified in 3.4.4 under the conditions as delineated in 4.2.6 or 4.3.3.15 as appropriate.

4.4.15.4 Time-to-burst phase.-The sample fuzes shall be fired as specified in 3.4.5 under the conditions delineated in 4.2.6 or 4.3.3.15 as appropriate. Time-to-burst shall be measured to the nearest millisecond by using two independent fuze chronograph systems. Time-to-burst shall also be measured by using two electric clocks or stop watches. All measurements shall be recorded (see 6.3.3.2).

4.4.15.4.1 Lot percent defective.-The time values obtained by the chronograph systems shall be used to calculate the estimate of lot percent defective. Where both chronograph systems provide a time value, the average shall be taken as the individual fuze value. Individual fuze values shall be rounded off to the second decimal place using the method prescribed by the American Society for Testing Materials. The estimate of lot percent defective shall be calculated using the method prescribed in MIL-STD-414, Example B3. For sample sizes 16 through 19 the estimated lot percent defective value shall be determined by interpolation between the values given in Table B5, MIL-STD-414 for sample sizes 15 and 20. All appropriate time values obtained for each time-to-burst phase shall be used in the initial calculation of the sample average ($\bar{x}$) and standard deviation (s). The standard deviation value obtained shall then be used to determine statistical outliers (non-normal values) by using the criteria $\bar{x}$ plus or minus 2.88 times the standard deviation. A value judged to be an outlier shall be excluded and the remaining values used to recalculate $\bar{x}$ and s. A minimum of 15 statistically normal values are required for each time-to-burst phase (see 6.3.3.1).

4.4.15.5 Excess pressure phase.-The sample fuzes shall be fired as specified in 3.4.5 under the conditions delineated in 4.2.6. Time-to-burst shall be measured in the nearest millisecond, using two independent timing devices. The data shall be recorded for informational purposes.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

4.4.15.6 Extreme temperature phase.-The sample fuzes shall be fired as specified in 3.4.5 under the conditions delineated in 4.2.6. Time-to-burst shall be measured to the nearest millisecond, using two independent timing devices. The data shall be recorded for informational purposes.

4.4.15.6.1 Temperature conditioning (-65°F. and +145°F.).-The test chamber shall be at ambient temperature at the start of the test and the chamber maintained at a temperature of minus 65°F or plus 145°F. as applicable, until stabilization of the fuze temperature is reached (see 6.4). After stabilization, the fuze shall be saturated at minus 65°F or plus 145°F as applicable, for one hour, minimum.

5. PREPARATION OF DELIVERY

5.1 Preservation, packaging and marking.-Preservation, packaging, packing and marking shall be as specified in the contract and in accordance with MIL-P-60412 with the following exception:

5.1.1 Level "B".-Packaging shall be as required for Level "A" except pressure test is not required.

5.2 The ICC marking shall be "Percussion Fuzes-Handle Carefully."

6. NOTES

6.1 Dimensions.

6.1.1 Compliance with tests (proving ground, ballistic performance, and shop) required by the specification and drawings is mandatory. The contractor will not assume, nor does the government guarantee, that all possible combinations permitted by the tolerance limits of the specifications and drawings will consistently satisfy the test requirements. Therefore, the manufacturer is obligated to choose those combinations of tolerances and fits within the limits of the specifications and drawings that best suit his process needs and still satisfy the testing requirements.

6.1.2 Dimensions which are specifically referred to in the classification of defects, as listed in Section 4, are mandatory. Pertaining to other dimensions, it is recognized that current mass production methods may occasionally produce parts which are not in full compliance with all dimensional requirements, but which may provide adequate fuze performance. Therefore, the contractor, at his own risk, may utilize these parts provided there is no adverse effect on fuze functionability. This relaxation of requirements applies to "after the fact" deviations only, to dimensions only, and does not constitute authority to establish new dimensions or to relax efforts to achieve the required sizes within the specified limits. The procedure for accomplishing dimensional changes is available under the established engineering change system. Nothing above is to be construed as relieving the contractor of any responsibility in connection with performance of the fuze.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

6.1.3 The contractor shall maintain records showing deviations from dimensional requirements, the extent of such deviations, the amount of material involved, and the date the material is introduced into the assembly line. Copies of these records shall be forwarded to the agency assigned custody of the technical data.

6.2 Armed/Unarmed delay arming mechanism.

6.2.1 Armed.-Rotor is locked by the spring loaded lock pin in the position in which the detonator is fully visible through the flash hole.

6.2.2 Unarmed.-Rotor fully engaged by both spring loaded blocks and the setback pin preventing rotor movement.

6.3 Ballistic parameters.

6.3.1 Premature function.-Shall be defined as the occurrence of any of the following:

a. The round detonates in the bore of the gun.
b. The round detonates before 45 seconds when set at 60 seconds or before 1.9 seconds when set at 3 seconds.
c. The round detonates before impact when set on safe "S" in the Impact Nonfunction Distance Phase, Impact Function Distance Phase, or the Ground or Water Impact Phase.

6.3.2 Time failure.-A time failure is considered to have occurred if the round fails to detonate during flight.

6.3.3 Outlier-offtime.-An outlier-offtime is statistical outlier (Non-normal value) which falls beyond the appropriate time limits specified in Table I.

6.3.3.1 Where the number of statistically normal time values obtained in either time-to-burst phase is less than 15 and the lot is not rejected because of other reasons, the disposition of the lot shall be referred to the responsible procuring activity. The Government reserves the right to require the contractor to submit additional test samples. The number of additional test samples shall be sufficient to obtain a combined total of 20 values in order that the occurrence of outliers will not reduce the number of normal values to less than the minimum required. All normal values obtained in the combined tests shall be used to determine lot acceptance or rejection. Attribute characteristic failures, e.g. duds occurring in the additional samples shall not be used to reject the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

6.3.3.2 Electric clock and stop watch time values - Where only electric clock or stop watch time measurements are obtained and these values indicate a premature burst or outlier which affects lot disposition, the lot shall be referred to the responsible procuring activity.

6.3.3.3 Defective fuzes - Where sample fuzes are found to be defective as received at the ballistic test facility, all tests of the lot sample shall be held in abeyance pending investigation by the responsible procuring activity.

6.3.4 Muzzle velocities mentioned in this specification are nominal only and are given for the guidance of the proving ground in selecting appropriate weapons and rounds.

6.4 Temperature stabilization of fuzes may be checked by a thermal measuring device in good thermal contact with the largest centrally located internal mass. A simulated fuze may be used for this purpose.

6.5 Data cards - Data card information shall be as specified in MIL-STD-1167.

6.6 Static load and torque - Screening of lots.- Caution shall be exercised so no damage occurs to components during testing.

6.7 Statement of Safety Requirements

6.7.1 Safety Limitations and Precautions Relating to Production Equipment and Facilities:

Assembly of explosive elements into fuzes shall be performed under protective hoods with static electricity controls. Protective barrier should be used when performing the Mil-Standard tests.

6.7.2 Hazards Presented by Materials:

Possible injury (burns or dismemberment) to limbs and body from flash or detonation of explosive elements.

6.7.3 Known Hazards in Hazardous Areas:

All areas in which explosive elements are used in assembly operations or stored.

6.7.4 Specific Instructions Relative to Manufacture, Handling, Storage and Shipment of Material: The number of persons exposed to explosive operations and the quantities of explosive materials should at all times be the minimum consistent with safety and the efficiency of operation. Signs setting forth personnel and explosive limits also should be posted. Prior to starting operations including any of the hazardous materials or items described herein, a standard operating procedure should be developed and approved by the contractor outlining the specific requirements to safely perform the particular operation. All personnel concerned should be cognizant of SOP contents. Applicable portions of the approved procedure should be conspicuously posted convenient to all stations involved in the operation for guidance of all personnel.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.

6.7.5 Explosive Hazard Classification of Material:

Assembled fuzes - Class 1, Detonators in Storage - Class 7.

6.8 Ordering data - Procurement documents should specify the following:

a. Title, number and date of this specification.

Custodian:

Army - MU

Preparing activity:

Army - MU(FA)

Project No. 1390-A210

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:35Z
Check the source to verify that this is the current version before use.