INCH-POUND

MIL-T-43416C
29 December 1988
SUPERSEDING
MIL-T-43416B(GL)
19 Feb 1974

MILITARY SPECIFICATION

TENT, SUNSHIELD, THEODOLITE

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers a 6-foot 2-inch square, flat roofed, 6-foot 4-inch pole supported tent.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation (see 6.2).

SPECIFICATIONS

FEDERAL

V-F-106	- Fasteners, Slide, Interlocking
TT-P-595	- Preservative Coating, Canvas
PPP-B-601	- Boxes, Shipping, Fiberboard

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: U.S. Army Natick Research, Development, and Engineering Center, Natick, MA 01760-5014 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:22Z
Check the source to verify that this is the current version before use.

MILITARY

MIL-C-2399 - Cement, Liquid, Tent Patching

STANDARDS

FEDERAL

FED-STD-751 - Stitches, Seams, and Stitchings

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129 - Marking for Shipment and Storage
MIL-STD-147 - Palletized Unit Loads
MIL-STD-731 - Quality of Wood Members for Containers and Pallets

(Unless otherwise indicated, copies of federal and military specifications, standards, and handbooks are available from the Naval Publications and Forms Center, (ATTN: NPODS), 5801 Tabor Avenue, Philadelphia, PA 19120-5099.)

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

Department of the Army Field Manual FM 10-16 -
General Repair of Tents, Canvas and Webbing

(Copies are available from the Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402.)

DRAWINGS

AOMC ORDNANCE CORPS

10601764 (sheet 1 of 3) - Tent, Sunshield Theodolite; Assembly and Illustration
10601764 (sheet 2 of 3) - Sidewall Details and Sections
10601764 (sheet 3 of 3) - Roof Details and Sections
10601765 - Bag, Storage and Shipping
10601766 - Line, Guy
10601767 - Clamp, Rope, Brass

(Copies of drawings are available from the U.S. Army Natick Research, Development, and Engineering Center, Natick, MA 01760-5014.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:22Z
Check the source to verify that this is the current version before use.

2.2 Non-Government publications. The following documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DoD adopted are those listed in the issue of the DODISS cited in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS are the issues of the documents cited in the solicitation (see 6.2).

AMERICAN SOCIETY FOR TESTING AND MATERIALS

D 3951 - Standard Practice for Commercial Packaging

(Application for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.)

THE COLOR CARD ASSOCIATION OF THE UNITED STATES

Department of Defense Standard Shades for Sewing Threads

(Application for copies should be addressed to the Color Association of the United States, 343 Lexington Avenue, New York, NY 10016.)

(Non-Government standards and other publications are normally available from the organizations that prepare or distribute the documents. These documents also may be available in or through libraries or other informational services.)

2.3 Order of precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document takes precedence. Nothing in this document, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 First article. When specified (see 6.2) a sample shall be subjected to first article inspection (see 6.3) in accordance with 4.3.

3.2 Materials and components. Materials and components shall be as referenced on applicable drawings listed in section 2 and as specified herein.

3.2.1 Fasteners, slide, interlocking. The slide fasteners shall conform to V-F-106. Type, style and size shall be as indicated on Drawing 10601764-1 of 3. Slide fastener chain shall be fabricated of brass or polyester coil. The slider for the brass chain shall be brass and the slider for the polyester coil shall be die cast zinc alloy. The slide fastener tape shall be dyed to match Olive Drab shades S (CA 66519) and be water repellent and mildew-rersistant. (Tapes made of 100 percent polyester need not be tested for mildew resistance.) The color of the tape after treatment will be considered acceptable. The tape shall show good fastness to weathering. Alternatively, the slide fastener chain shall

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

be polyester continuous monofilament in a ladder or coil type configuration. Color of the chain shall be olive drab or natural finish brass and the sliders shall be brass.

3.2.2 Thread, polyester. The thread shall conform to types, classes and shades specified in Drawing 10601764 (sheet 1 of 3). The dyed thread shall show fastness to weathering equal to or better than the standard shade sample (see 6.4). When no standard shade sample is available, the dyed thread shall show good fastness to weathering.

3.3 Construction. The construction shall conform to the drawings listed in section 2 and as specified herein.

3.3.1 Ends of stitching and stitching repairs. The stitching types specified herein shall conform to FED-STD-751.

3.3.1.1 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched 1/2 inch minimum except when caught in other stitching or turned under in a hem. Thread tension shall be maintained so that there will be no loose stitching resulting in puckering of material sewn. The lock shall be embedded in the material sewn.

3.3.1.1.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of 1 inch behind the end of the stitching. 1/

b. Thread breaks or two or more consecutive skipped run-off stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 1 inch before the defective area (1/2 inch on box, box and cross, and W-W stitching) and continue a minimum of 1 inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner. 1/

1/ When making the above repairs, the ends of the stitching are not required to be backstitched.

3.3.1.2 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of all seams or stitching produced with a 401 stitch type, when not turned under in a hem or held down by other stitching, shall have a 1/2 to 3/4 inch chain extending beyond each end. The looper (under thread) shall always be on the inside of the tent or cover. All repairs shall be made in accordance with 3.3.1.1.1a or 3.3.1.1.1b. Repairs may be made using 301 stitch type.

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

3.3.1.3 Automatic stitching. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements for stitch pattern, stitches per inch, and size and type of thread are met, and at least three tying, overlapping, or backstitches are used to secure the ends of the stitching.

3.3.1.4 Thread ends. All thread ends that are visible on the finished item shall be trimmed to a length of not more than 1/4 inch.

3.3.1.5 Lubrication of thread. The addition of any lubricant to the polyester sewing thread prior to or during the sewing operation is prohibited.

3.3.1.6 Stitching margins. Unless otherwise specified, all stitch margins shall be 1/8 +1/16, -0 inch.

3.3.2 Wicking of sewing thread (cup test). There shall be no seepage of water through the tent stitching when the tent is tested as specified in 4.5.1. The cup test is intended to insure that nonwicking thread has been used and that no lubrication has been added to the thread prior to or during the sewing operation.

3.3.3 Repairs. Any necessary repairs shall be affected in accordance with the Department of the Army Field Manual FM 10-16, except that handsewn patches, or cemented patches other than as specified herein, will not be acceptable. Cemented patches on holes, cuts or tears not more than 1 inch in diameter or length, using the cement specified in MIL-C-2399, shall be permitted. A maximum of three cemented patches per tent shall be allowed without prior authorization by the contracting officer. All other repairs shall require contracting officer authorization. Repairs required as a result of failure of the cup test shall be performed by treating with a compound conforming to type I, class 1, shade olive drab of TT-P-595 prior to retesting (see 4.5.1).

3.3.4 Splicing of webbing. If required, roof reinforcement webbing shall be spliced as shown on Drawing 10601764, sheet 3 of 3. A maximum of one splice per diagonal strip will be permitted.

3.3.5 Splicing of cloth. There shall be no splicing of roof, wall or tent cover panels. Splicing of sod cloth sections will be permitted and, if performed, shall conform to the following requirements:

a. The shortest length of any spliced piece shall not be less than 2 feet.
b. One splice allowed per section.
c. Pieces shall be joined as shown on Drawing 10601764- sheet 3 of 3, Section J-J.

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

3.3.6 Replacement of defective components. During the spreading, cutting and manufacturing process, components of the tent having material defects or damages that are classified as defects in 4.4.3 or 4.4.4 shall be removed from production and replaced with non-defective and properly matched components.

3.4 Workmanship. Cloth components shall be clean and free of holes, cuts, tears or cloth defects such as multiple floats or broken or missing yarns. Webbing and tapes shall contain no frayed or scalloped edges and rope components shall be free of cuts or breaks. Care shall be taken in sewing to insure that no needle chews shall occur. Metal components shall be free of burrs, sharp edges or corroded areas and shall not be broken or malformed. The tent shall conform to the quality of product established by this specification and the occurrence of defects shall not exceed the applicable acceptable quality levels.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements (examinations and tests) as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this specification where such inspections are deemed necessary to ensure supplies and services conform to prescribed requirements.

4.1.1 Responsibility for compliance. All items shall meet all requirements of sections 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of ensuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling inspection, as part of manufacturing operations, is an acceptable practice to ascertain conformance to requirements, however, this does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to accept defective material.

4.1.2 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for ensuring that all specified dimensions have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to assure compliance with all dimensional requirements.

4.2 Classification of inspection. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

Source: https://assist.dla.mil -- Downloaded: 202640-21T21:22Z
Check the source to verify that this is the current version before use.

4.3 First article inspections. When a first article is required (see 6.2), it shall be examined for the defects specified in 4.4.3 and 4.4.4 and tested for the characteristics specified in 4.5. The presence of any defect or failure to pass any test shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Unless otherwise specified, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified, or qualified in this specification or applicable purchase document.

4.4.2 In-process inspection. Inspection shall be made of the following operations or assemblies to establish conformance to specified requirements. Whenever nonconformance is noted, correction shall be made to the items affected and to the operation. Items which cannot be corrected shall be removed from production.

a. Holes punched to receive grommets are in compliance with note 10 on Drawing 10601764- sheet 1 of 3.

b. There shall be no lubrication on polyester thread prior to or during sewing operations in compliance with 3.3.1.5.

4.4.3 End item visual examination. The end items shall be in an erected position so that both the inside and outside of the tent can be examined, along with its cover, for defects listed in table I. The lot size shall be expressed in units of tents with covers. The sample unit shall be one tent with cover. The inspection level shall be I and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 10 for major defects, 25 for major and minor A combined defects, and 100 for total (major, minor A, and minor B combined) defects.

TABLE I. End item visual defects

Examine	Defect	Classification Major	Minor A	Minor B
Fabric	Cut or tear longer than 1/8 inch; hole (including exposed drill hole) larger than 1/8 inch diameter			
	- on roof	101		
	- on wall		201	
	- on storage bag or sod cloth			301

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Fabric (cont'd)	Exposed drill hole (1/8 inch or less) i.e., not covered by attached parts on roof:			
	- more than 1 but not more than 4			302
	- more than 4		202	
	Broken or missing yarns; multiple floats		203	
Webbing, tie tapes and wall ties	Edge frayed or scalloped			303
Hardware	Broken	102		
	Malformed:			
	- fails to perform intended function	103		
	- but will perform intended function		204	
	Corroded area			304
	Burr or sharp edge which may cause injury in handling or damage to fabric	104		
Grommets	Improperly set, two or more teeth exposed (except where set as specified but is in an area of uneven thickness which prevents uniform clinching)			305
	Clinched loosely allowing grommet to rotate in hole			306
	Clinched excessively tight, cutting fabric:			
	- on tent	105		
	- on storage bag		205	
	Insecurely clinched, i.e., grommet or washer may become disengaged:			
	- on tent	106		
	- on storage bag		206	

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Rope components	Any cut; any break			
	- on guy line		207	
	- on footstop			307
	Eye splice omitted		208	
	Eye splice not as specified			308
	Any free end not finished as specified			309
Seams and stitching	Open seam on stitch type 301:			
	- for more than 1/4 inch but not more than 1 inch		209	
	- for more than 1 inch			310
	Open seam on stitch type 401:			
	- one row of stitching open for 1 inch or less on tent or storage bag			311
	- one row of stitching open for more than 1 inch:			
	- on roof		210	
	- on wall or storage bag			312
	- both rows of stitching open (not necessarily at same location:			
	- on roof	107		
	- on wall or storage bag			313

NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken or when one or more skipped or runoff stitches occur. On double stitched seams, a seam shall be classified as open when one or both sides of a seam are open.

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)	Raw edges caught in stitching:			
	- more than 1 inch but not more than 3 inches			314
	- more than 3 inches		211	
	Thread breaks:			
	- overstitched less than 1 inch on stitch type 401 or 301			315
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Needle chews resulting in cut or tear longer than 1/4 inch in length or hole larger than 1/4 inch diameter:			
	- on roof	108		
	- on wall		212	
	- on sod cloth or storage bag			316
	Skipped stitches:			
	- overstitched less than 1 inch on stitch type 401 or 301			317
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	One or more required rows of stitching omitted (except on boxstitching)	109		
Boxstitching	Incomplete:			
	- one row of stitching omitted		213	
	- two or more rows of stitching omitted	110		

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitching ends	Overstitched less than 1/2 inch on stitch type 301 (except where ends are turned under in a hem, held down by other stitching, or where stitching is performed automatically)		214	
	Secured with less than three tying, overlapping or backstitches when automatic stitching is performed			318
Seams	Seams pleated:			
	- on roof		215	
	- at eave or on wall			319
Seam type	Wrong seam type	111		
Stitch type	Wrong stitch type	112		
Stitch tension	Loose resulting in an exposed bobbin or top thread for more than 6 inches		216	
	Tight, as evidenced by puckering on fabric for more than 6 inches		217	
Stitches per inch	Less than minimum specified (except on panel joining seams):			
	- one stitch			320
	- two or more stitches		218	
	Less than minimum specified on panel joining seams		219	
	More than maximum specified:			
	- one stitch			321
	- two or more stitches		220	

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitches per inch (cont'd)	NOTE: A variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows: a. Within the minor A defect classification - Minor B defect b. Within the minor B defect classification - No defect			
Stitching gage	Not as specified		221	
	NOTE: Applicable when double needle machine is used. When two rows of stitching are applied with a single needle machine, tolerance for stitching margin shall apply.			
Stitching margin	Larger than specified by more than 3/16 inch:			
	- for more than 2 inches but not more than 4 inches in length			322
	- for more than 4 inches in length		222	
	Less than specified:			
	- for more than 2 inches but not more than 4 inches in length			323
	- for more than 4 inches in length		223	
Stitching indicated by "Z" on drawing	Chain portion of stitching is on outside of tent or storage bag		224	

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Splicing of webbing	More than one splice per reinforcement strip (see 3.3.4)		225	
	Any splice not made as specified (see Drawing 10601764, sheet 3 of 3)			324
Components and assembly	Any required component part not fabricated of applicable referenced material	113		
Mends, darns or patches	Repairs not in accordance with Department of the Army Field Manual FM 10-16; not authorized by the contracting officer (see 3.3.3)	114		
Hems	Construction with a partial turnunder when a double turnunder is required		226	
Reinforcements	Improperly applied, causing excessive fullness on reinforcement or reinforced parts			325
	Not stitched to reinforced parts on all sides, or not caught in seams or stitching of reinforced parts, single ply construction where double ply is required		227	
Cloth splicing	Splice in roof, wall, or tent cover panels	115		
	Number of splices per reinforcement or sod cloth section more than specified		228	
	Spliced pieces not joined as shown on Drawing 10601764- sheet 3 of 3, section J-J		229	

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

tear, abrasion, or hole in

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification: Major	Minor A	Minor B
Slide fasteners	Slider jams or fails to interlock chain	116		
	Any tape improperly assembled causing failure of chain to effect a smooth and secure closure	117		
	Wrong length	118		
	Width not as specified	119		
	Puckering of tape	120		
	Broken or missing scoops	121		
	Thong omitted	122		
	NOTE: The inspector shall pull slide fasteners three or four times to an open and closed position to determine proper function and effectiveness of each fastener.			
Cleanness	Grease or oil stains			326
	Thread ends not trimmed to 1/4 inch or less (except in slide fastener area)			327
	Thread ends not trimmed to 1/4 inch or less in slide fastener area		230	
Marking "US" and nomenclature	Omitted, incorrect, illegible or misplaced; size characters not as specified		231	

4.4.4 End item dimensional examination. The end items shall be in an erected position so that both the inside and outside of the tent can be examined, along with its cover, for defects listed in table II. The lot size shall be expressed in units of tents with covers. The sample unit shall be one tent with cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 2.5 for major defects, 15 for major and minor A combined defects, and 40 for total (major, minor A and minor B combined) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:22Z
Check the source to verify that this is the current version before use.

shall be expressed in units of boles. The sample unit shall be one bole. The

TABLE II. End item dimensional defects

Examine	Defect	Classification Major	Minor A	Minor B
Overall dimensions of tent	Smaller than specified dimensions less applicable minus tolerance indicated on drawings	101		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			301
Overall dimensions of storage bag	Smaller than specified dimensions less applicable minus tolerance:			
	- by more than 1/4 inch but not more than 1/2 inch		201	
	- by more than 1/2 inch	102		
	Larger than specified dimensions and applicable plus tolerance by more than 1 inch			302
Location dimensions (unless otherwise specified)	Not within specified tolerances but not exceeding twice the applicable tolerance			303
	Exceeding twice the applicable tolerance		202	
Hems	Hems required to finish less than 3/4 inch in width, less than specified; hem required to finish more than 3/4 inch in width, less than specified by more than 1/4 inch			304
Webbing, tie tapes and wall ties	Finished length less than specified by more than 1/2 inch			305
	Out of specified location:			
	- by more than 1/4 inch but not more than 1/2 inch		203	
	- by more than 1/2 inch	103		

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:22Z
Check the source to verify that this is the current version before use.

loads not as specified. interlocking of

TABLE II. End item dimensional defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Rope components, tent lines	Any line less than specified finished length by more than 2 inches; eye of lines or footstops less than specified length by more than 1/2 inch			306
Reinforcements	Finished dimensions less than specified by more than 1/2 inch			307
Boxstitching	Cross boxstitching less than specified length or width by more than 1/8 inch			308
Sod cloths	Less than specified width by more than 1/2 inch			309

4.4.5 End item testing. Tents shall be tested as specified in 4.5.1 for compliance with 3.3.2. The sample unit shall be one completely fabricated tent. The lot shall consist of all completely fabricated tents offered for inspection and the inspection level shall be S-3. Failure in any area shall be cause for rejection of the lot.

4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed below. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units, shall be 2.5.

Examine	Defect
Marking (exterior and interior)	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application.
Materials	Any component missing, damaged, or not as specified.
Workmanship	Inadequate application of components.
Content	Number per container is more or less than required.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:22Z
Check the source to verify that this is the current version before use.

4.4.7 Palletization examination. The fully packaged and palletized end items shall be examined for the defects listed below. The lot size shall be expressed in units of palletized unit loads. The sample unit shall be one palletized unit load, fully packaged. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirements.
Palletization	Pallet pattern not as specified. Load not bonded as specified.
Weight	Exceeds maximum load limits.
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application.

4.5 Methods of inspection.

4.5.1 Wicking of sewing thread (cup test). The tent shall be tested in each of the three areas as follows: at the peak, ridge or joining seam abutting the peaks or ridge; at an intersection of a horizontal and vertical seam such as at an intersection of a side wall and roof; and on a roof panel seam. Suspend the seamed section of the test fabric in the center of a 6 ± 1/8 inch diameter hoop and form a depression with the seamed fabric in the hoop to a depth of 1 ± 1/4 inch. Slowly pour 500 mL of water at 77°F ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall constitute a failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial as specified (see 6.2).

5.1.1 Level A. Each tent, with corner slide fasteners open and window slide fasteners closed, shall be laid out flat, outside up. The guy lines shall be neatly coiled and tied and placed on the tent roof. The sod cloths shall be folded over the side walls. The side walls shall be folded over full length onto the tent roof. The tent shall then be adjusted to a width of approximately 43 inches by folding two opposite ends in toward the center of the tent, consisting of 4 tent poles, 8 wooden tent pins, and 16 metal tent

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:22Z
Check the source to verify that this is the current version before use.

pins, shall be neatly stacked width-wise at one end of the folded tent. The tent pole spindles shall all be placed on one side. The tent shall then be compactly rolled around the stacked components forming a neat bundle approximately 44 inches in length and 12 inches in diameter. Each bundled tent shall be tied approximately 8 inches from each end with cotton tape or twine. Each bundled and tied tent shall be inserted in the storage bag provided and the bag securely closed with the tie tapes.

5.1.2 Commercial. Each tent shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B or Commercial as specified (see 6.2).

5.2.1 Level A. One tent, preserved as specified in 5.1, shall be packed within a wood-cleated plywood box conforming to overseas type, style A of PPP-B-601. The inside dimensions of the box shall be approximately 45 inches in length, 12-1/2 inches in width, and 12-1/2 inches in depth. Each box shall be closed and reinforced in accordance with the appendix of PPP-B-601.

5.2.2 Level B. One tent, preserved as specified in 5.1, shall be packed as specified in 5.2.1, except a domestic-type box is acceptable.

5.2.3 Commercial. Tents preserved as specified in 5.1 shall be packed in accordance with ASTM D 3951.

5.3 Palletization. When specified (see 6.2), tents packed as specified in 5.2, shall be palletized on a 4-way entry pallet in accordance with load type I of MIL-STD-147. Pallet types shall be type I (4-way entry), type IV or type V in accordance with MIL-STD-147. Pallets shall be fabricated from wood groups I, II, III, or IV of MIL-STD-731. Each prepared load shall be bonded with primary and secondary straps in accordance with bonding means K and L or film bonding means O or P. Pallet pattern shall be number 85 in accordance with the appendix of MIL-STD-147.

5.4 Marking. In addition to any special marking required by the contract or purchase order, shipping containers shall be marked in accordance with MIL-STD-129 or ASTM D 3951, as applicable.

6. NOTES

(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

6.1 Intended use. The tent is designed to provide protection for both instruments and personnel involved in the operations of the Pershing Missile System.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:22Z
Check the source to verify that this is the current version before use.

6.2 Acquisition requirements. Acquisition documents must specify the following:

a. Title, number, and date of this specification.
b. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (see 2.1.1 and 2.2).
c. When first article is required (see 3.1, 4.3, and 6.3).
d. Levels of preservation and packing.

6.3 First article. When a first article is required, it shall be inspected and approved under the appropriate provisions of FAR 52.209. The first article should be a preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should also include specific instructions in acquisition documents regarding arrangements for selection, inspection, and approval of the first article.

6.4 Sample. For access to samples address the contracting activity issuing the invitation for bids (see note 7 on Drawing 10601764- sheet 1 of 3).

6.5 Repair of leaking seams. A satisfactory method of applying the textile compound for the repair of leaking seams is as follows:

a. A suitable volume of textile compound conforming to type E, class 1, shade Olive Drab of TT-P-595 shall be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tents must be dry. Special attention must be taken to insure adequate ventilation and that proper fire preventive measures are taken since the compound is flammable.

c. Two coats of the textile compound shall than be applied to the seams (on the outside of the tent only). A 4-inch wide stiff brush in recommended for use. The first coat shall be air dried for a minimum of 4 hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent shall be alowed to air dry for a period of at least 24 hours.

6.5.1 Seams to be treated. Seams which have failed the test specified in 4.5.1 shall be treated as follows:

a. Failure at sidewall and roof joining seams - treat all seams joining roof to sidewalls.

b. Failure at roof panel lap seam - treat all roof panel lap seams.

Source: https://assist.dla.mil -- Downloaded: 202640-21T21:22Z
Check the source to verify that this is the currentversion before use.

6.6 International standardization agreements. Certain provisions of this document are the subject of international standardization agreement as cited in NATO, STANAG No. 2882, relative to camouflage requirements for tents, shelters and subsidiary components. When amendment, revision, or cancellation of this document is proposed which will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

6.7 Subject term (key word) listing.

Cover, protective
Missile system, Pershing
Shell

6.8 Changes from previous issue. Marginal notations are not used in this revision to indentify changes with respect to the previous issue due to the extensiveness of the changes.

Custodians:

Army - GL
Navy - NU
Air Force - 99

Preparing activity:

Army - GL

(Project 8340-A514)

Review activities:

Army - MD
Navy - MC
Air Force - 82
DLA - CT

User activity:

Air Force - 45

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-T-43416C	TENT, SUNSHIELD, THEODOLITE

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR ☐ USER ☐ MANUFACTURER ☐ OTHER *(Specify)*: _____
b. ADDRESS *(Street, City, State, ZIP Code)*	

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

DD FORM 1426 PREVIOUS EDITION IS OBSOLETE.

Source: https://assist.dla.mil -- Downloaded: 202640-21T21:22Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

U.S. ARMY NATICK RESEARCH, DEVELOPMENT
and ENGINEERING CENTER
ATTN: STRNC-ES
Natick, MA 01760-5014

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. [illegible] WASHINGTON D.C.
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
U.S. Army Natick Research, Development
and Engineering Center
ATTN: STRNC-ES
Natick, MA 01760-5014

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:22Z
Check the source to verify that this is the current version before use.