MILITARY SPECIFICATION

MINE, ANTITANK, PRACTICE: M79
ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-M-48629(AR), dated 3 October 1985, and is approved for use within the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1.2 Other Government documents drawings and publications; Add the Following dwgs:

12624514 - Pkg & Mkg for Shipping & Storage Container, Mine for Mine, AT: HE, M75; Mine, AP: HE, M74 or Mine, AT, Prac: M79.
12624515 - Pkg. & Mkg for Container, Fiberboard for Mine, AP: HE, M74; Mine, AT: HE, M75; or Mine, AT, Prac: M79.

PAGE 5

TABLE I. First article inspection

Paint adhesion test: Delete (a), (a), and (a) and substitute (a), (a), and 3.3.1.

Salt spray test: Delete (a), (a), and (a) and substitute (a), (a), and 3.3.2.

PAGE 7

4.4.2.1 Paint adhesion test: Delete (a), (a), and (a) and substitute (a), (a), and 3.3.1.

PAGE 8

4.4.2.2 Title: Change to read: "Pkg for Plastic Ammunition Container: PA-83 for Mine, AP: HE, M74 or Mine, AT, Practice: M79".

Major 103: Delete "Any markings missing" and substitute "Any marking missing, incorrect or illegible".

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:34Z
Check the source to verify that this is the current version before use.

PAGE 9

4.4.2.3 Major 104: Delete "Fiberboard" and substitute "Plastic".

FOLLOWING PAGE 9

Add Page 9A, 4.4.2.4 included herein.

Add Page 9B, 4.4.2.5 included herein.

PAGE 10

5.1.1: Delete "Level A. The mines ... Dwg. 9333791." and substitute "Level A. (Fiberboard sleeve)...Dwg. 12624515."

Add: 5.1.2 "Level A. (Plastic sleeve) The mines shall be preserved and packaged in accordance with Dwg. 9333791."

5.2.1: Delete "Level A. "Packing... Dwg. 9243805." and substitute "Level A. (Fiberboard sleeve)... Dwg. 12624514."

Add: 5.2.2 "Level A. (Plastic sleeve) Packing shall be in accordance with Dwg. 9243805."

5.3.1: Delete "Level A. Marking ... with Dwgs. 9333791 and 9243805." and substitute "Level A. Marking ... with Dwgs. (9333791 and 9243805) or (12624515 and 12624514) as applicable."

PAGE 11

5.4.1: Delete "Level A. Unitizational mines as packed in 5.2.1 shall ... Ammo Center)." and substitute "Level A: Unitization of mines as packed in 5.2.1 or 5.2.2 shall ... Ammo Center)."

Add 5.5: Packing of the mines in Fiberboard Ammunition Containers and corresponding Steel Shipping and Storage Container (in accordance with Dwgs. 12624515 and 1264514) is the preferred packaging. When using Plastic Ammunition Container: PA-83 and the corresponding Steel Container packaging shall be in accordance with Dwgs. 9333791 and 9243805.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:34Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.4	Pkg & Mkg for Container, Fiberboard for Mine, AP: HE, M74; Mine, AT: HE, M75; or Mine, AT, Prac: M79	1 OF 1	12624515
			NEXT HIGHER ASSEMBLY: 12624514

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any mines missing from container		0.40%	3.2	Visual/Manual
102	Closure; not properly secured		0.40%	3.2	Visual/Manual
103	Marking missing, incorrect or illegible		0.40%	3.2	Visual
Minor					
201	Poor workmanship		0.65%	3.4	Visual

NOTES:

Source: https://assist.dla.mil (9A) downloaded: 2026-10-22T19:34Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.5	Pkg & Mkg for Shipping & Storage Container, Mine for Mine, AT: HE, M75; Mine AP: HE, M74, or Mine, AT, Prac: M79	1 OF 1	12624514
			NEXT HIGHER ASSEMBLY ---

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
	Prior to Securing Cover:				
101	Marking missing, incorrect or illegible		100%	3.2	Visual
102	Bag(s) of Desiccant missing		0.40%	3.2	Visual
103	Filler on bottom missing		0.40%	3.2	Visual
104	Any Fiberboard Ammo Container missing		0.40%	3.2	Visual
105	Number of Slotted Fillers not adequate for tight packing		0.40%	3.2	Visual/Manual
106	Slotted Fillers positioned incorrectly		0.40%	3.2	Visual
107	Number of top fillers not adequate for tight packing		0.40%	3.2	Visual/Manual
108	Dirt of foreign material on Gasket or Gasket Track (Cover and Base)		0.40%	3.2	Visual
	After Securing Cover:				
110	Vent Assembly Cap not hand tight		0.40%	3.2	Manual
111	Humidity Indicator torqued improperly		0.40%	3.2	Gage
112	Fastener Nut (s) torqued improperly		0.40%	3.2	Gage
113	Vent Assembly nut torqued improperly		0.40%	3.2	Gage
114	Humidity Indicator dots not proper color		100%	3.2	Visual
Minor					
201	Fiberboard Ammo Containers not positioned properly		0.65%	3.2	Visual
202	Poor workmanship		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:34Z
Check the source to verify that this is the current version before use.

Add: 5.6 Shipping. When mines from more than one lot interfix are shipped at one time, each lot shall be kept separate and the division between lots clearly indicated to prevent mixing of the lots in transit.

Custodian:
Army - AR

Preparing activity:
Army -AR

(Project 1345-A405)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:34Z
Check the source to verify that this is the current version before use.