MILITARY SPECIFICATION

TEST SET, ELECTRICAL CIRCUIT, M40E1
PARTS FOR, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-T-48236 (PA) dated 6 August 1973, and is approved for use by all Departments and Agencies of the Department of Defense.

Page 1, paragraph 2.1: Change title of MIL-A-2550 to read: "Ammunition, General Specification For:".

Page 1, paragraph 2.1: Add the following:

"MIL-P-116 - Preservation, Method of.
MIL-B-117 - Bag, Sleeve and Tubing-Interior Packaging.
MIL-B-2427 - Box, Ammunition Packing, Wood, Nailed.
MIL-B-46506 - Box, Ammunition Packing, Wood, Wirebound.
MIL-F-50449 - Filler, Sheet Form (For Use in Ammunition Container)."

Page 2, Paragraph 2.1: Delete "U.S. ARMY MUNITIONS COMMAND" and substitute "U.S. ARMY PICATINNY ARSENAL".

Page 3, paragraph 3.8: Delete in its entirety and substitute as follows:

"3.8 First Article Inspection. - This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract."

Page 11, Add new Paragraphs 4.3.2.11 and 4.3.2.12 as follows:

FSC 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:18Z
Check the source to verify that this is the current version before use.

"4.3.2.11 Sealed carton, prior to closing wooden box (see 5.1.2).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Bag ruptured, punctured, or incomplete seal	Visual	15001
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.7)	Visual	15002

4.3.2.12 Box, sealed wooden packing (see 5.1.2).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Strapping or hardware missing, broken or loose	Visual/ Manual	16001
102.	Box damaged to extent that contents are exposed or liable to become exposed	Visual	16002
Minor:	AQL 1.50 percent		
201.	Contents loose	Visual	16003
202.	Car seal missing, unsealed or improperly positioned	Visual	16004
203.	Marking missing, incorrect or unidentifiable	Visual	16005
204.	Evidence of poor workmanship (see 3.7)	Visual	16006

Page 17, Add new Paragraph 5.1.2 as follows:

"5.1.2 Level A. - Each box of test sets packed in accordance with 5.1.1 shall be inserted into a barrier bag conforming to MIL-B-117 for a Type I, Style 1, Class E bag. All excess air shall be exhausted from the bag and the bag opening closed by means of heatsealing. The seal shall meet the heatseal test of MIL-P-116. Bag size shall be approximately 21 by 31 inches inside dimensions.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:18Z
Check the source to verify that this is the current version before use.

Two boxes (400 test sets) inclosed in barrier bags shall be packed in a nailed wood or wirebound box conforming to MIL-[illegible] for Type I, Class 1 Grade A box or MIL-[illegible] requirements for a Grade A, Type I, Class 2 wirebound box. Box size shall be approximately 20 3/4 by 18 3/4 by 10 1/4 inches in depth, inside dimensions. All exterior surfaces of the box shall be lined with Fillers conforming to Specification MIL-F-50449. One or more fillers shall be placed on top of the box contents and additional fillers added as necessary to provide a tight pack. Size of fillers shall be equal to the interior length and width of the appropriate side, end, top or bottom of the box less approximately 1 inch.

Boxes shall be closed and strapped as required in accordance with instruction contained in the Appendix of the box specification."

Page 17, Paragraph 5.2: Delete "for Level C shipment" and substitute "for Level A or C shipment."

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: [illegible]

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:18Z
Check the source to verify that this is the current version before use.