INCH-POUND

MIL-M-28787/279
AMENDMENT 2
31 March 1993
SUPERSEDING
AMENDMENT 1
2 October 1984

MILITARY SPECIFICATION

MODULES, STANDARD ELECTRONIC

RELAY, ANALOG, KEY CODE RRF

This amendment forms a part of Military Specification MIL-M-28787/279(EC), dated 23 August 1979, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 1

1.2, second line: Delete "100°C" and substitute "85°C".

*1.2, Maximum power dissipation, 32 Vdc. - 55°C, class II: Delete "5.0 max" and substitute "3.44 max".

PAGE 4

TABLE I, column heading: Delete "100° ± 5°C" and substitute "85° ± 5°C".

PAGE 5

4.3: Delete and substitute the following:

"4.3 Test equipment. Test equipment specified on figures and in tables with a type designator shall be as specified in MIL-STD-1665. Other equipment and components shall be as specified on the figures. All resistors shall be metal film and all capacitors shall be ceramic unless otherwise specified."

4.4.2: Add the following sentence at the end of the paragraph:

"If test condition A is performed at any time during quality assurance inspection testing, it shall be followed by performance of at least all 100 percent tests."

PAGE 7

*FIGURE 2, ITEM P01 DC Power Supply box: Delete "40 +0/-1 V" and substitute "28 +0/-1 V".

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T17:21Z
Check the source to verify that this is the current version before use.

*FIGURE 3, NOTE 3: Delete "3. R12-R21 = 14 ohms ± 1%, 20 W non-inductive." and substitute "3. R12-R21 = 28 ohms ± 1%, 30 W non-inductive."

*Remove Item EL01 from the test setup.

*Add a new NOTE 5 as follows: "5. Voltage spikes at Item P06 during module operation shall not exceed 2 Vpk."

*Change the test setup. Connect the P01-1 + terminal to one side of all ten coils (P1-22, 26, 30, 34, 38, P2-22, 26, 30, 34, 38).

*Connect the other side of the coils to the Q1 collector. Connect the Q1 emitter to ground (see figure 9).

NOTE: The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodians:
Army - ER
Navy - SH
Air Force - 85

Review activities:
Army - AT
Navy - AS, MC
Air Force - 13, 19
DLA - ES

Preparing activity:
Navy - NW

(Project 5963-0225)

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T17:21Z
Check the source to verify that this is the current version before use.