INCH-POUND

NOTICE
OF CANCELLATION

MS39162E
NOTICE 1
30 September 1993

MILITARY SPECIFICATION SHEET

ELBOW, PIPE TO TUBE, 90°, MALE PIPE END, 45° FLARED TYPE, AUTOMOTIVE

MS39162E, dated 10 March 1987, is hereby cancelled. Future acquisitions for this product should refer to SAE J512, Automotive Tube Fittings.

A detailed cross-reference of cancelled MS39162E Part Identifying Numbers (PINs) to superseding SAE J512 Government Part Identifying Numbers (PINs) are contained herein.

NOTE: MS39162E superseded CNAX3 in part.

Copies of SAE J512 are stocked at the Standardization Documents Order Desk, Building 4D, 700 Robbins Avenue, Philadelphia, PA 19111-5094, for issue to DoD activities only. Other Government agencies, contractors, private concerns, or other requestors must obtain documents from the following or from some other authorized distributor:

Society of Automotive Engineers, Inc.
400 Commonwealth Drive
Warrendale, PA 15096

Preparing Activity:
Army - AR

Agent:
DLA-CS


(Project 4730-0225)

DISTRIBUTION STATEMENT A. Approved for public release, distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T17:47Z
Check the source to verify that this is the current version before use.

CANCELLED MS PART IDENTIFYING NO. (PIN)	TUBE O.D.	PIPE THREAD NPTF	SUPERSEDING SAE PART IDENTIFYING NO. (PIN)
MS39162-1	1/8 (.1250)	1/8 (.1250)	J5122-2010202B
MS39162-2	3/16 (.1875)	1/8 (.1250)	J5123-2010202B
MS39162-3	1/4 (.2500)	1/8 (.1250)	J5124-2010202B
MS39162-4	5/16 (.3125)	1/8 (.1250)	J5125-2010202B
MS39162-5	3/8 (.3750)	1/4 (.2500)	J5126-4010202B
MS39162-6	7/16 (.4375)	1/4 (.2500)	J5127-4010202B
MS39162-7	1/2 (.5000)	3/8 (.3750)	J5128-6010202B
MS39162-8	5/8 (.6250)	1/2 (.5000)	J51210-8010202B
MS39162-9	3/4 (.7500)	1/2 (.5000)	J51212-8010202B
MS39162-10	7/8 (.8750)	3/4 (.7500)	J51214-12010202B
MS39162-11	1 (1.000)	1 (1.000)	J51216-16010202B

Superseding PIN consists of identification of SAE document, nominal tube O.D., pipe thread NPTF, configuration, and brass material. SAE part numbers are constructed in accordance with SAE J846. Example: J5122-2010202B, as a replacement for PIN MS39162-1, is constructed as follows:



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T17:47Z
Check the source to verify that this is the current version before use.