MILITARY SPECIFICATION

SIMULATOR, BOOBY TRAP, ILLUMINATING M118
PARTS FOR, AND LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-S-10555H(AR), dated 5 September 1975, and is approved for use by the U.S. Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 6

TABLE I. First article inspection: Delete: "Upper Disc Assembly - Dwg. 8848584 - Examination of Defects - 25 - 3.2 - 4.4.2.13".

PAGE 14

4.4.2.5, Tube Outer: Add "Major 132 Vent hole missing, obstructed or mislocated - 0.40% - 3.2 - Visual".

PAGE 22

4.4.2.13: Delete in its entirety.

PAGE 25

4.4.2.16, Assembly, Prior To Assembling Cap: Add "Major 133 Outer tube vent hole not sealed by the sealing tape (applies after assembling cap and following 24 hours drying period) - 0.40% - 3.2 - Visual".

PAGE 26

4.4.2.17, Assembly: Add "Major 102 Outer tube vent hole covered by bracket - 0.40% - 3.2 - Visual".

Add "Major 103 Vent hole sealing tape not completely covered by binding tape - 0.40% - 3.2 - Visual".

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project: 1370-A133

FSC: 1370

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:13Z
Check the source to verify that this is the current version before use.