DATA ITEM DESCRIPTION

Form Approved
OMB No. 0704-0188
Exp. Date: Jun 30, 1986

1. TITLE	2. IDENTIFICATION NUMBER
DoD Property Record (Partial)	DI-MISC-80093

3. DESCRIPTION/PURPOSE

3.1 This Data Item Description (DID) identifies the content requirement covered by the specific and discrete task for contractor to prepare this data product identified in the contract purchase description and in DLAM 4215.1, Management of Defense-Owned Industrial Plant Equipment.

4. APPROVAL DATE (YYMMDD)	5. OFFICE OF PRIMARY RESPONSIBILITY (OPR)	6a. DTIC REQUIRED	6b. GIDEP REQUIRED
851211	S/DIPEC-STD		

7. APPLICATION/INTERRELATIONSHIP

7.1 This DID contains the format and content preparation instruction for the data product generated by the specific and discrete task requirement for this data included in the contract.

7.2 The DoD Property Record change data is required on certain IPE rebuild contracts.

8. APPROVAL LIMITATION	9a. APPLICABLE FORMS	9b. AMSC NUMBER
	DD Form 1342	S3743

10. PREPARATION INSTRUCTIONS

10.1 Contract. This data item is generated by the contract which contains a specific and discrete work task to develop this data product.

10.2 Specific Instructions for completion of page 1.

10.2.1 Block 1. Enter "x" in the change block.

10.2.2 Block 2. Enter the Julian date.

10.2.3 Block 3. Enter the identification/government tag number.

10.2.4 Block 8. Enter the year of manufacture of the item.

10.2.5 Block 9. Enter the appropriate power code listed in DLAM 4215.1, Appendix 1C.

10.2.6 Block 14. Enter the manufacturer's name.

10.2.7 Block 16. Enter the manufacturer's model number.

10.2.8 Block 17. Enter the manufacturer's serial number.

10.2.9 Block 18, 19, 20, and 21. Enter the length, width, height, and weight of the item, including skid. Dimensions shall be recorded to the next foot.

10.2.10 Block 26. Enter the description and capacity of the machine after rebuild/retrofit.

10.2.11 Block 27. Enter the electrical characteristics of each electric motor on item.

10.2.12 Section II. Enter "x" in the appropriate column in blocks 31, 32, 33, 35, 36, & 37 and enter the rebuild completion date in block 31.

10.2.13 Block 54. List all attachments, accessories and technical data identified with the item.

10.2.14 Block 57. Enter date and signature of individual responsible for accuracy of the data.

10.3 Specific Instructions for completion of page 2.

10.3.1 Enter the Julian date and the ID/Government Tag Number in the appropriate blocks.

10.3.2 Blocks 58 thru 61. Enter the manufacturer's name, model designation, serial number, and date of manufacturer of the numerical control.

10.3.3 Block 62. Check the appropriate box(s) to indicate the type of design utilized in the control unit.

10.3.4 Block 63. Check the appropriate box to indicate the type of numerical control system.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:34Z
Check the source to verify that this is the current version before use.

3. DESCRIPTION/PURPOSE (Cont'd)

3.2 The DoD Property Record (DD Form 1342) is designed to supply record keeping data on industrial plant equipment (IPE) to managers and accountable offices on the status, condition, identification and history of an individual item.

---

10. PREPARATION INSTRUCTIONS (Cont'd)

10.3.5 Block 64. Check the appropriate boxes to the system when the item is part of a Direct Numerical Control System.
10.3.6 Block 65. When applicable, enter the figure numbers in the referenced EIA Standard which identifies each axis of machine motion whether the motion is by NC or other means. See RS-267, Axis and Motion Nomenclature of Numerically Controlled Machines.
10.3.7 Block 66. Enter the format detail in accordance with Appendix A, para. A.2 of EIA Standard checked in Block 77A.
10.3.8 Block 67. Enter the format classification shorthand in accordance with Appendix A, para. A.1 of the EIA Standard checked in Block 77A.
10.3.9 Block 68. Name and identify rotary motions under NC (e.g.,: (1) a-axis-rotating spindle head, (2) b-axis-rotating table).
10.3.10 Block 69. Enter by name each axis that is controlled under positioning mode of operation (e.g., X, Y, Z, B).
10.3.11 Block 70. Enter by name each axis or combination of axes that are unde contouring control simultaneously (e.g., (1) XYZ, (2) XY, XZ, or YZ (switchable).
10.3.12 Block 71. Enter maximum travel in inches or millimeters, and rotary motions in degrees of each axis whether under NC or not.
10.3.13 Blocks 72 thru 74. Enter the positioning rate, feed range, and spindle data.
10.3.14 Block 75. Enter the preparatory "G" function codes that are furnished in accordance with Appendix B.1 of the EIA Standard checked in Block 77A. All codes for preparatory functions using EIA unassigned codes shall be listed and described in Block 98.
10.3.15 Block 76. Enter the miscellaneous function in accordance with Appendix B.2 of the EIA Standard checked in Block 77A. All codes for auxiliary functions using unassigned codes shall be listed and described in Block 98.
10.3.16 Blocks 77 thru 85. Enter the input data; tool change data; rotary table data; reader data (reader speed shall be in characters per second); type of interpolation; buffer storage (yes or no); and thread cutting lead.
10.3.17 Block 86. Enter the cutter diameter compensations and the maximum amount of offset that may be entered for each.
10.3.18 Block 87. Enter the number of pairs of tool offsets and the maximum amount of offset that may be entered for each.
10.3.19 Blocks 88 and 89. Check appropriate boxes to indicate the data that may be read out on displays; and the type of feedback device provided.
10.3.20 Block 90. Enter the smallest increment of measure that the control unit and feedback system will accept and act on.
10.3.21 Block 91. Check the appropriate box to indicate the type of drive motors provided for the feed drives.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:34Z
Check the source to verify that this is the current version before use.

10. PREPARATION INSTRUCTIONS (Cont'd)

10.3.22 Block 92. Enter the postprocessors name.
10.3.23 Block 93. Enter name of machine rebuilder or control manufacturer that prepared the postprocessor.
10.3.24 Blocks 94 thru 96. Enter the computer language used; part program language and version used; and the applicable computer.
10.3.25 Block 97. Enter the title and edition of all required manuals, control diagnostic tapes, and machine test tapes.
10.3.26 Block 98. Enter all special features of the machine or control; control features provided and identified by codes other than assigned EIA Standard codes; control features that are not in accordance with applicable EIA Standards; and special accessory items provided with equipment.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:34Z
Check the source to verify that this is the current version before use.