MIL-I-46607A(MU)
5 June 1963
SUPERSEDING
MIL-I-46607 (CmlC)
29 November 1961

MILITARY SPECIFICATION

IGNITER, BOMB, MK 260, MOD 0

1. SCOPE

1.1 This specification covers an igniter (without fuze) filled with white phosphorus (WP) for use in igniting a fire bomb.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of the specification to the extent specified herein:

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.

DRAWINGS

DEPARTMENT OF THE NAVY - BUREAU OF NAVAL WEAPONS

LD 479815 - Igniter, Bomb, MK 260, Mod 0 - List of Drawings, Assemblies, Parts, Specifications. (All drawings referenced in this specification are listed on Dwg LD 479815.)

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Materials and components.

3.1.1 Materials. All materials cited on Drawing LD 479815 or on the

FSC 1325

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:26Z
Check the source to verify that this is the current version before use.

subsidiary drawings shall conform to the specifications listed thereon, or to the specific characteristics set forth on the drawings.

3.1.2 Components. All components of the igniter shall conform to the specifications and drawings listed on Drawing LD 479815 and subsidiary drawings.

3.2 Assembly. The igniter shall be assembled, coated, and marked as specified on Drawing 1634812.

3.3 Filling.

3.3.1 Procedure. The igniter thoroughly clean, shall be filled with molten WP specified on Drawing 1634812 (see 6.2). When the igniter is filled under water, the depth of water remaining on the surface of the WP in the filled and closed igniter shall not exceed 1/8 inch (see 6.3). The molten WP shall be allowed to solidify in the igniter while in a vertical position with the top end (closure or filling end) up.

3.3.2 Quantity. The surface of the WP in the filled and closed igniter shall be 1/4 to 1/2 inch below the inside surface of the top end when the igniter is inspected in a vertical position and when tested as specified in 4.6.1.

3.4 WP contamination. The exterior surface of the filled and closed igniter and the interior surface of the sleeve shall be thoroughly cleaned to remove any grease, oil or WP (see 6.5).

3.5 Leakage. The igniter shall not leak when maintained at a temperature of 135° ± 5°F for a minimum period of 16 hours and tested as specified in 4.6.3. After igniters have been accepted for leakage the WP shall be allowed to solidify with the igniter in the top end (closure or filling end) up.

3.6 Workmanship. The igniter shall be free from foreign matter (oil or grease) and damage such as dents, cracks, or deformations which would impair its use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified, the supplier may utilize his own facilities or any commercial laboratories acceptable to the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:26Z
Check the source to verify that this is the current version before use.

4.2 Special provisions.

4.2.1 Alternative inspection (including testing) procedures. The supplier may utilize any alternative inspection procedures which will insure equal or better quality by submitting a written proposal with justification and obtaining written approval from the Government prior to instituting the procedure. In case of dispute, the procedures of this specification shall govern.

4.2.2 Objective evidence. The supplier shall provide evidence acceptable to the contracting officer that the requirements of 3.1 and section 5 have been satisfied.

4.3 Lotting. A lot shall consist of the igniters filled by one filling installation, using the same materials, under essentially the same filling and assembling conditions.

4.4 Sampling for examination and nondestructive tests. Sampling shall be conducted in accordance with Standard MIL-STD-105.

4.5 Examination. Sample igniters and the level A preparation for delivery requirements shall be examined and tested in accordance with the classification of defects and Standard MIL-STD-105.

4.5.1 For critical characteristics. Each item in the lot shall be inspected for the critical characteristics listed in the classification of defects.

4.5.2 Classification of defects.

4.5.2.1 Igniter, bomb, MK 260, mod 0, assembly (Dwg 1634812).

Categories	Defects	Acceptance stancards
Critical:		
1	Leakage	4.6.3
2	WP contamination (see 3.4)	4.6.2
Major:	AQL 1.0 percent defective	
101	Damage (see 3.6)	
102	Excessive water on fill	4.6.1
103	Marking incorrect	
104	Filling screw torque incorrect	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:26Z
Check the source to verify that this is the current version before use.

4.5.2.1 Igniter, bomb, MK 260, mod 0, assembly (Dwg 1634812). (Continued).

Categories	Defects	Acceptance standards
Minor:	AQL 2.5 percent defective	
201	Marking missing or illegible	
202	Filling insufficient	4.6.1
203	Protective finish missing, or incorrect	
204	Paint on threads	
205	Foreign matter (see 3.6)	
Major A:	AQL 0.65 percent defective	
301	Filling excessive	4.6.1

4.5.2.2 Preparation for delivery (section 5).

Categories	Defects
Critical:	None defined
Major:	AQL 4.0 percent defective
101	Containers incorrect
102	Internal blocking missing or incorrect
103	Container closure incorrect
104	Quantity per container incorrect
105	Container damage (punctured)
106	Marking missing, illegible or incorrect

4.6 Tests.

4.6.1 Quantity of filling. With the WP in a molten state (at 130° ± 10°F) and the igniter in a vertical position, filling-end up, the height of the WP shall be located radiographically in conformance with Chemical Corps Inspection Standard R9-1 (see 6.1).

4.6.2 WP contamination. Cleaning shall be determined by a method approved by the Government inspector.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:26Z
Check the source to verify that this is the current version before use.

4.6.3 Igniter leakage. Following the final cleaning operation and while the WP is still molten, the igniter shall be placed in a vertical position (filling-end down) or rolled in a horizontal position for a minimum period of 1 minute. The igniter shall be observed for the emission of smoke, which shall constitute leakage.

5: PREPARATION FOR DELIVERY

5.1 Packing, level A. The filled igniters shall be packed as shown on Drawing DL 2185238.

5.2 Marking. In addition to any special marking required by the contract or order, shipping containers shall be marked in accordance with the document referenced on Drawing DL 2185238.

6. NOTES

6.1 Ordering data. Procurement documents should specify the following:

(a) Title, number and date of this specification.
(b) The Government will furnish the Inspection Standard.
(c) The supplier will not be required to furnish radiographic equipment.

6.2 Precautions. Beacuse of the hazardous nature of filling munitions with chemical agents, filling installations are advised to take all necessary precautions to protect personnel from injury while filling in accordance with this specification.

6.3 Alkalinity. When igniters are filled under water, the water should be buffered by a suitable alkaline salt to maintain a pH value between 6.5 and 8.0 as a protection to stop equipment from corrosion.

6.4 Weight. Igniters filled in accordance with this specification will contain approximately 2 pounds, 14 ounces of WP. This information is furnished as an aid for procurement and not as a criterion for filling.

6.5 Decontamination. Igniters may be decontaminated by passing through a hot water and detergent spray washer or by flushing with hot water while vigorously scrubbing with steel wool. Additional cleaning of the burster well may be effected with a steam lance and a power driven wire brush.

6.6 Safety classification. This item carries the following safety classification: chemical group C, explosive hazard class 2 (Chemical Corps Safety Directive No. 385-10).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:26Z
Check the source to verify that this is the current version before use.

Notice. When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

Custodian:

Army - MU

Preparing activity:

Army - MU

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:26Z
Check the source to verify that this is the current version before use.