INCH-POUND
MIL-P-70507 (AR)
AMENDMENT 5
16 February 1995
SUPERSEDING
AMENDMENT 4
02 August 1993

MILITARY SPECIFICATION

PROJECTILE, 155MM, HE, XM864
LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-P-70507 (AR), dated 28 December 1984, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense

PAGE 1

Change "XM864" to "M864" wherever it appears in the specification.

* 1.1: Add the following new paragraph:

"1.2 The Appendix herein covers the requirements and quality assurance provisions for loading of M864 projectiles with M42/M46 grenade cargoes downloaded from surplus M483A1 projectiles."

2.1: Add the following specification:

"MIL-S-71174 - Spheroidal Propellant, M38 for Use in the M864 Expulsion Charge"

Add the following Government Drawing:

"12914619 - Packing and Marking for 155mm Projectile Pallet"

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202640-23T03:35Z
Check the source to verify that this is the current version before use.

3.3 Delete in its entirety and add the following new paragraph:

"3.3 Strength of heat seal. The charge bag shall withstand application of a static load, at the seam, of 2.5 pounds per linear inch, minimum without peel-back of the heat seal and without tensile failure of the area adjacent to the heat seal."

PAGE 4

3.5: Delete 3.5.g "separated igniter components" and add the following new 3.5.g: "Examine the base burner assembly for:

1. Missing components
2. Misassembled components
3. Igniter cup loading assemblies facing the wrong way (inverted orientation)
4. Foreign matter present

Add "3.5.h Presence of gap between base and body"

PAGE 5

4.3.1: Delete the table in its entirety and add the following:

"Part Description	Drawing	Quantity
Projectile	9381131	12
Steel Shim	9215397	25
Expulsion Charge Assembly (if applicable)	12944315	50
Obturator	1054290	5
Cup, Expulsion	9391057	25
Charge Loading Assembly (if applicable)	12934963	25
Bag, Charge Assembly (if applicable)	12934962	25
Forward Plate	9381111	10
Container Assembly, Expulsion Charge (if applicable)	9391003	50
Cup and Lid Sub-Assembly (if applicable)	12630560	25
Lid, Container Expulsion Charge (if applicable)	9362552	Note 1
Cup Container, Expulsion Charge (if applicable)	9391001	Note 1

Note 1. Five samples from each mold cavity."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

PAGES 6 AND 7

Table I.: Delete in its entirety and add new Table I included as pages 6A and 7A.

PAGE 8

4.3.3d-e, Delete and add the following:

"d. The total number of grenades failing to function satisfactorily equals or exceeds twenty-five (25). Applicable to the service pressure phase of the initial sample only (major defect).

e. One or more projectiles fail to function satisfactorily (major defect)."

Note 2, lines 3-4, Delete and add the following:

"number of air detonations from the entire seven rounds tested in the initial sample service pressure phase exceeds eleven"

Note 3, lines 7-8, Delete and add the following:

"Such grenades from the entire seven (7) rounds tested in the initial sample service pressure phase exceeds fourteen (14), the data"

PAGE 9

4.4.1.: Delete item d and add the following new item d:

"d. Base burner assemblies from one finally accepted lot interfix number from one manufacturer."

Delete the following from items 4.4.1.g and 4.4.1.h:

"from one lot interfix number"

Delete items 4.4.1.j and 4.4.1.k, and add the following:

"j. Charge assembly propellant from one lot.
k. Expulsion charge assemblies from one lot interfix number from one manufacturer."

Add the following:

"o. Expulsion cups from one lot interfix number from one manufacturer."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE Projectile and components	SHEET 1 OF 2	DRAWING NUMBER See below
			NEXT HIGHER ASSEMBLY
CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
	Projectile (Dwg. 9381131) Examination for defects Ballistic functioning	 12 12	 3.1 3.4	 4.4.2.14 4.4.3.1
	Expulsion Charge Assembly (Dwg. 12944315) Examination for defects	 50	 3.2	 4.4.2.4
	Steel Shim (Dwg. 9215397) Examination for defects	 25	 3.2	 4.4.2.7
	Bag Charge Assembly (Dwg. 12934962) Examination for defects	 25	 3.2	 4.4.2.1
	Cover, Expulsion Charge (Dwg 9272022) Examination for defects	 25	 3.2	 4.4.2.2
	Charge Loading Assembly (Dwg. 12934963) Examination for defects	 25	 3.2	 4.4.2.3

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE Projectile and Components	SHEET 2 OF 2	DRAWING NUMBER See below
			NEXT HIGHER ASSEMBLY
CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
	Obturator (Dwg. 10542907) Examination for defects	Note 1	3.2	4.4.2.16
	Forward Plate (Dwg. 9381111) Examination for defects	10	3.2	4.4.2.24

NOTES:
1. Five (5) samples from each mold cavity.

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

PAGE 10

4.4.2.1: Delete in its entirety and add new 4.4.2.1 included as page 10A.

PAGE 11

4.4.2.2: Delete in its entirety and add new 4.4.2.2 included as page 11A.

PAGE 12

4.4.2.3: Delete in its entirety and add new 4.4.2.3 included as page 12A.

PAGE 13

* 4.4.2.4: Delete in its entirety and add new 4.4.2.4 included as page 13A.

PAGE 20

4.4.2.11: Major 104, change "sealant" to "adhesive", change AQL "0.40%" to "100%".

PAGE 21

4.4.2.12: Special Defect a., change "Gage" to "Gage/4.5.14".

Add Special Defect b:

"b.	Sealant around weather seal-base closure interface missing or not 360 degrees	100%	3.1	Visual"

Delete Major Defect 101 and add the following:

"101	Disassembly torque test of base burner assembly	100%	3.2	4.5.6"

Delete Major Defect 103 in its entirety.

Add the following minor defect:

"Minor				
202	Sealing compound not present between projectile body and base (360 degrees)	.65%	3.2	Visual"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
AMENDMENT 5

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.1	Bag, Charge	1 OF 1	12934962
			NEXT HIGHER ASSEMBLY: 12934963

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Length of bag	0.40%	3.2	Gage
102	Distance to end heat seal, max.	0.40%	3.2	Gage
103	Distance to side heat seal (See Dwg. 10542907)	0.40%	3.2	Gage
104	Minimum width of both heat seals over entire length	0.40%	3.2	Gage
105	Heat seal incomplete (2 places)	0.40%	3.2	Visual
106	Strength of heat seal	Note a	3.2	4.5.3
107	Location of eyelet	0.40%	3.2	Gage
108	Location of end stitching	0.40%	3.2	Gage
109	Distance to side stitching	0.40%	3.2	Gage
Minor				
201	Stitching incomplete (2 places)	0.65%	3.2	Visual
202	Fold width eyelet end	0.65%	3.2	Gage
203	Fold misalignment max.	0.65%	3.2	Gage
204	Thickness of assembled eyelet	0.65%	3.2	Gage
205	Evidence of poor workmanship	0.65%	3.8	Visual

NOTES:
a. Sample 20 per lot, reject on one (1) or more defectives.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
AMENDMENT 5

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.2	Cover, Expulsion Charge	1 OF 1	9272022

NEXT HIGHER ASSEMBLY: 129349263

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Diameter of rim	0.40%	3.2	Gage
102	Thickness of rim, minimum	0.40%	3.2	Gage
103	Total height	0.40%	3.2	Gage
104	Angle between rim and angled portion	0.40%	3.2	Gage
105	Thickness of angled portion, minimum	0.40%	3.2	Gage
106	Height of rim	0.40%	3.2	Gage
107	Location of tabs	0.40%	3.2	Gage
108	Distance between tab and angled portion (2 places)	0.40%	3.2	Gage
109	Radius missing	0.40%	3.2	Visual
110	Crack or puncture	0.40%	3.2	Visual
111	Burr	0.40%	3.2	Visual
112	Hole diameter under minimum	0.40%	3.2	Gage
Minor				
201	Hole diameter over maximum	0.65%	3.2	Gage
202	Hole true position	0.65%	3.2	Gage
203	Evidence of poor workmanship	0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
AMENDMENT 5

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.3	Charge Loading Assembly	1 OF 1	12934963
			NEXT HIGHER ASSEMBLY: 12944315

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None Defined			
Major				
101	Pull wire of bag loose with respect to cover	0.40%	3.2	Visual/Manual
102	Cover damaged	0.40%	3.2	Visual
103	Clinch of stud improper	0.40%	3.2	Visual
104	Bag diameter	0.40%	3.2	Visual
Minor				
201	Evidence of poor workmanship	0.65%	3.8	Visual

NOTES:

AMSMC Form 1570b-E, 1 Jul 89 Replaces AMSMC Form 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil - 9 (1.2A) Created: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
AMENDMENT 5

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.4	Expulsion Charge Assembly	1 OF 1	12944315
			NEXT HIGHER ASSEMBLY: 9381131

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Leak test	Note a	3.2	4.5.2
102	Weight of propellant charge incorrect	0.40%	3.2	Gage
103	Bag seal incomplete (3 places)	0.40%	3.2	Visual
104	Moisture and total volatiles content of propellant	Note a	3.2	4.5.1
105	Bag damaged	0.40%	3.2	Visual
Minor				
201	Evidence of poor workmanship	0.65%	3.8	Visual

NOTES:
a. Sample in accordance with applicable test method paragraph.

Source: https://assist.dla.mil-- (DPAA) Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

PAGE 23

4.4.2.14, Add the following Major Defect:

"107 Ballistic test (d) 3.4 4.4.3.1"

Add the following note:

"(d) Sample in accordance with applicable test method paragraph"

PAGE 24

4.4.2.14, Delete minor 203 in its entirety and add:

"203 Bare spots on protective coating 0.65% 3.2 Visual"

PAGE 25

* 4.4.2.15, Delete special (a.) in its entirety.

Add the following new table 4.4.2.25 included as page 34A.

PAGE 27

4.4.2.17: Change next higher assembly drawing number to "9391003". Change Major 113 to "Pull test, min. and max. (See dwg. 12630560)"

PAGE 28

4.4.2.18: Change drawing number to "9391001". Change next assembly drawing number to "9391003". Change major 109 to "Pull test, min. and max. (See dwg. 12630560)". Add Major Defect 110 "Flatness of seal area, 0.40%, 3.2, Gage". Add Major Defect 111 "Wall thickness, 0.40%, 3.2, Gage".

PAGE 29

4.4.2.19: Change next higher assembly drawing to "9391003".

PAGE 30

4.4.2.20: Change drawing number to "9391003". Change next higher assembly drawing number to "9381131". Add new Major Defect 105 "Cup or lid damaged, 0.40%, 3.2, Visual". Add new Major Defect 106 "Gap between cup and lid 360 degrees, max., 0.40%, 3.2, Gage". Add new Major Defect 107 "Total length, max., 0.40%, 3.2, Gage".

Source: https://assist.dla.mil -- Downloaded: 202610-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
AMENDMENT 5

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.25	Packaging and Marking for 155MM Projectile Pallet	1 OF 1	12914619

NEXT HIGHER ASSEMBLY

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Improperly assembled or parts missing	0.40%	3.2	Visual
102	Spacers loose or damaged	0.40%	3.2	Visual
103	Rods not properly engaged in cover or base	0.40%	3.2	Visual
104	Lifting plug of projectile missing or damaged	0.40%	3.2	Visual
105	Improper torque on nut at top of rod	0.40%	3.2	Gage
106	Cotter pin not properly engaged	0.40%	3.2	Visual/Manual
Minor				
201	Any marking missing incorrect or unidentifiable	0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil-2 (20240) Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

PAGE 32

4.4.2.22: Delete in its entirety and add the new 4.4.2.22 included as page 32A.

PAGE 34

4.4.2.24: Major 104: Change "Concentricity" to "True Position".

PAGE 35

4.4.3.1: Delete and add the following:

"4.4.3.1 Ballistic Functioning (see 3.4). For first article and each lot produced, the projectiles shall be "tested per 4.5.10 as follows:

Buttress thread projectiles. For metal parts produced with buttress threads (body drawing 9381123 Revision C and ogive drawing 9381121 Revision B) seven samples shall be tested at service pressure and three shall be tested at the safety phase."

PAGE 36

4.4.3.1.3d. Delete and add the following:

"d. The total number of grenades failing to function satisfactorily equals or exceeds twenty-five (25). Applicable to the service pressure phase of the initial sample only (major defect)."

4.4.3.1.3e. Delete and add the following:

"e. One or more projectiles fail to function satisfactorily (major defect)."

Note 2. Delete lines 3 and 4 and add:

"air detonations from the entire seven (7) rounds tested in the initial sample service pressure phase exceeds eleven (11).

Note 3. Delete lines 7 through 9 and add:

"such grenades from the entire seven (7) rounds tested in the initial sample service pressure phase exceeds fourteen (14), the data"

Source: https://assist.dla.mil -- Downloaded: 202610-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
AMENDMENT 5

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.22	Cup, Expulsion	1 OF 1	9391057
			NEXT HIGHER ASSEMBLY: 9381131

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Pitch diameter of thread	0.40%	3.2	Gage
102	Major diameter of thread	0.40%	3.2	Gage
103	True position of largest inside diameter with pitch diameter of threads	0.40%	3.2	Gage
104	True position of smallest inside diameter with pitch diameter of thread	0.40%	3.2	Gage
105	Minimum inside diameter	0.40%	3.2	Gage
106	True position of largest outside diameter with pitch diameter of thread	0.40%	3.2	Gage
107	Length of threaded area	0.40%	3.2	Gage
108	Thickness of bottom	0.40%	3.2	Gage
109	Thickness of sidewall	0.40%	3.2	Gage
110	Overall length	0.40%	3.2	Gage
111	Depth to start of angle	0.40%	3.2	Gage
112	Presence of two slots	0.40%	3.2	Visual
113	Largest outside diameter	0.40%	3.2	Gage
114	Perpendicularity of largest outside diameter	0.40%	3.2	Gage
115	Presence of angle between large and small inside diameters	0.40%	3.2	Gage
Minor				
201	Evidence of poor workmanship	0.65%	3.4	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

PAGE 38

4.5.2, Note 1, Delete and add:

"Note 1: For the purpose of this test, a reject shall be defined as an assembly that leaks to the extent that the propellant becomes wet. To determine the condition of the propellant, those assemblies that exhibit darkening (an indication of wet propellant) of the propellant shall be cut open and the propellant shall be visually and manually inspected for moisture. Only those assemblies containing moisture shall be considered defective. Assemblies that do not contain moisture, for lots that have passed leakage testing, shall have the propellant salvaged. There shall be no mixing of lots of salvaged propellant. Salvaged propellant shall be tested in accordance with 4.5.1."

PAGE 39

4.5.2.1: Change dwg. "936255" to "9391003".

4.5.3: Delete paragraph in its entirety.

PAGE 40

4.5.9: Delete in its entirety and add the following:

"4.5.9 Radiographic inspection of projectile. The projectile assemblies shall be radiographically examined prior to forwarding to the proving ground. Prior to assembly of the base burner assembly, the Government inspector shall indicate the location of the spline by marking the outside of the projectile. In all exposures the radiographic beam shall be focused along the center axis of the projectile and parallel to the face of the forward plate, with the spline ninety degrees (90) to the right in the direction from the source to the projectile. Radiographic exposure shall as a minimum, include all of the base burner assembly, to and including the entire forward plate. If necessary more than one radiograph shall be taken in this view as required to avoid detrimental parallax effects and to observe the conditions specified in 3.5. In the event that the radiograph(s) taken in this view prevent a suitable examination, the projectile shall again be radiographed at a location rotated 90 degrees from the original view, with the spline nearest to the source. Projectiles and radiographs shall be suitably identified to permit cross reference. Radiographs shall be maintained by the contractor until final acceptance of the projectile. If any defect, per paragraph 3.5 is found, it shall be reported to SMCAR-QAR-R. The lot represented by this sample shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

4.5.9.1 Radiographic qualifications. Radiographic equipment, operations and procedures shall be qualified in accordance with MIL-STD-453. The personnel performing this examination shall be qualified and certified, Level 2, per MIL-STD-410. In addition, the radiographic examination shall be performed with the technique capable of producing 2 percent sensitivity (radiographic quality level 2-2T) and the photographic density of the film used shall be of a quality which will produce a sharp definition of internal structure."

PAGE 41

4.5.10.2: Delete the first sentence and replace with:

"The sample projectiles to be subjected to this test shall be fired at 145+/-5 degrees F in the M199 Cannon with a M203A1 propelling charge conditioned to 145+/-5 degrees F."

PAGE 42

4.5.12: Delete the first part of the first sentence and add the following:

"After each sample of lid (dwg. 12630546) and empty cup (dwg. 9391001) have been assembled together for this inspection (dwg. 12630560), the assembly shall..."

Change drawing "(9362556)" to "(12630560)".

4.5.13: Add new paragraph as follows:

"4.5.13 Hardness test of cup. The cups selected shall be subjected to the hardness test in accordance with the methods and procedures of ASTM E 18-67. The load and penetrator shall be in accordance with the hardness scale specified on the applicable drawing. Three readings shall be taken on each cup on the outside surfaces of the closed end and approximately 1/4" from the edge and approximately 120 degrees apart. A suitable fixture shall be utilized to provide support under the surface being tested. Such fixtures shall be approved in accordance with 4.4.4. If the average value of the three readings for any cup is less than the value specified in the applicable drawing, that cup shall have failed the requirement. Equipment used for performing this test shall be approved in accordance with paragraph 4.4.4."

Source: https://assist.dla.mil -- Downloaded: 202610-23T03:35Z
Check the source to verify that this is the current version before use.

PAGE 42

4.5.14: Add the following new paragraph:

"4.5.14 Inspection of gap between projectile body and base. Gap shall be inspected using an approved feeler gage as specified on drawing 9381131. The feeler gage shall be cleaned with a clean dry rag immediately after each inspection such that the gage is free of any base/body gap sealant. No solvent or other substance other than a clean dry rag shall be used to clean the gage. The gap between the projectile body and base shall be inspected within fifteen (15) minutes after the sealant is applied to the shoulder of the base."

5.1.1: Delete in its entirety and add the following:

"5.1.1 Packing-Level A. The projectiles shall be palletized in accordance with Dwg. 12914619."

Add the following:

"5.1.2 Alternative Packing-Level A. Only with the specific approval of the contracting officer, the projectiles shall be palletized in accordance with Dwg. 8837839.

5.1.3 Markings. Markings shall be in accordance with Dwg. 12914619 or 8837839."

PAGE 43

Add new paragraph 6.7 as follows:

"6.7 Heat-treatment batch. A heat-treatment batch is herein defined as cups, of the same type, that have been produced from one lot of material, and heat treated at the same time in the furnace, quench medium and aging process for each of all phases of the entire heat treatment process. When a continuous-type heat treatment process is used, the quantity of cups processed through the furnace for each four (4) hours production, or portion thereof, shall be considered as a heat treatment batch."

PAGE 44

Add attached Appendix A to the end of the Specification.

Source: https://assist.dla.mil -- Downloaded: 202640-23T03:35Z
Check the source to verify that this is the currentversion before use.

MIL-P-70507

APPENDIX A

REQUIREMENTS AND QUALITY ASSURANCE PROVISIONS FOR M864 PROJECTILES LOADED WITH REUTILIZED M42/M46 GRENADE CARGOES

10. SCOPE

10.1 Scope. This appendix covers the requirements and quality conformance provisions for loading of M864 projectiles withM42/M46 grenade cargoes downloaded from surplus M483A1 projectiles. In addition, this appendix covers the qualification testing of sampled M42/M46 grenades downloaded from surplus M483A1 projectile lots.

The download/reload method shall serve to replace the typical grenade layer by layer loading operation in the M864 LAP sequence. Elimination of the latter operation will reduce the amount of inspection (See para. 40.1); however, inspections that pertain to the projectile subassembly, base burner assembly, and complete round still remain.

20. APPLICABLE DOCUMENTS

20.1 MILITARY SPECIFICATIONS

MIL-G-48062 - Grenade, HE, G.P., M46, Loading and Assembling

MIL-G-50975 - Grenade, HE, G.P., M42, Loading and Assembling

30. REQUIREMENTS

30.1 Method of cargo transfer. The download/reload of the reutilized M42/M46 grenade cargoes shall be by means of a system that constrains the cargo (both diametrically and axially) as a complete unit during its transfer from the M483A1 projectile to the M864 projectile. The system must be capable of accommodating the grenade quantities needed to support the M864 production safely and reliably. Grenade cargo configuration and quantity shall conform to drawing 9381131.

30.1.1 System demonstration. A demonstration test of the transfer system shall be conducted for feasibility and compatibility purposes. Test parameters shall be approved by the Government.

30.2 Inspection, M864. In addition to the inspections cited in the basic specification, inspection of M864 projectiles loaded

Source: https://assist.dla.mil -- Downloaded: 202610-23T03:35Z
Check the source to verify that this is the current version before use.

with reutilized M42/M46 grenade cargoes shall be in accordance with para. 40.1.1 and drawing 9381131, Note 30.

30.3 Qualification testing, M483A1. Testing of M42/M46 grenades (with M223 fuzes), downloaded from surplus M483 projectile lots, shall be in accordance with paragraphs 40.1.2 and 40.1.3. The contractor shall maintain records of all test results.

30.3.1 Projectile/grenade sampling. From each M483A1 projectile lot that is selected for downloading, the responsible Government agency shall randomly sample four projectiles. From each projectile, the ninth and first layer of grenades (8-M42, 8-M46 grenades respectively) shall be removed for testing. Total grenade sample per lot is sixty-four (64).

30.3.2 Sample traceability. All separated components (i.e. fuze, loaded grenade body) shall be identified by projectile lot number, projectile sample number, and layer position.

40. QUALITY ASSURANCE PROVISIONS

40.1 Examinations and tests. The following inspections in this appendix pertain to the test and load of M42/M46 grenade cargoes in accordance with the documents and requirements cited in this appendix. It shall be noted that paragraph 40.1.1 herein has been substituted for paragraphs 4.4.2.5, 4.4.2.9, 4.4.2.10, and 4.4.2.11 of the basic specification.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
APPENDIX

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
40.1.1	Projectile after transfer of grenades prior to assembly of base burner assembly and seal ring	1 OF 1	9381131
			NEXT HIGHER ASSEMBLY: None

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Special				
a.	Adapter missing or improperly assembled	100%	30.2	Visual
b.	Any sleeve, spacer or spline missing, impoperly positioned or incorrect length	100%	30.2	Visual
Major				
101	Ribbon unwound (Exposed grenade layer)	100%	30.2	Visual
102	Stiffener or tape improperly positioned (Exposed grenade layer)	100%	30.2	Visual
103	Depth between projectile face and adapters (or shims) at specified load	100%	30.2	4.5.11
104	Seal ring missing or wrong type	0.40%	30.2	Visual
105	Seal ring not lubricated	0.40%	30.2	Visual
106	Adhesive missing on threads of base burner assembly	100%	30.2	Visual
107	Threads damaged on base burner assembly or projectile body	0.40%	30.2	Visual
108	Foreign material on threads	0.40%	30.2	Visual
Minor				
201	Evidence of poor workmanship	0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-02-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
APPENDIX

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
40.1.2	Qualification of M42 Grenades from downloaded M483A1 Projectile lot.	1 OF 1	9215340
			NEXT HIGHER ASSEMBLY: None

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined.			
Major				
101	Unthreading torque, test of clinched arming screw, M223 fuze	Sample 32	30.3	note a.
102	Arming test of M223 fuze slide	Sample 32	30.3	note b.
103	Static penetration	note c	30.3	note c
Minor	None defined			

NOTES:

a. Test IAW 4.5.4.2 of MIL-G-50975. Accept lot on 0 defects, reject on one.
b. Test IAW 4.5.4.3 of MIL-G-50975. Accept lot on 0 defects, reject on one.
c. 30 defuzed, loaded grenade bodies shall be tested IAW the requirements and methods of MIL-G-50975.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF CHARACTERISTICS

MIL-P-70507 (AR)
APPENDIX

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
40.1.3	Qualification of M46 Grenades from downloaded M483A1 Projectile lot.	1 OF 1	9215370
			NEXT HIGHER ASSEMBLY: None

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined.			
Major				
101	Unthreading torque, test of clinched arming screw, M223 fuze	Sample 32	30.3	note a.
102	Arming test of M223 fuze slide	Sample 32	30.3	note b.
103	Static penetration	note c	30.3	note c
Minor	None defined			

NOTES:

a. Test IAW 4.5.4.2 of MIL-G-48062. Accept lot on 0 defects, reject on one.
b. Test IAW 4.5.4.3 of MIL-G-48062. Accept lot on 0 defects, reject on one.
c. 30 defuzed, loaded grenade bodies shall be tested IAW the requirements and methods of MIL-G-48062.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:35Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1320-0006)

Source: https://assist.dla.mil -- Downloaded: 202610-23T03:35Z
Check the source to verify that this is the current version before use.