MILITARY SPECIFICATION

FIN, ASSEMBLY, BOMB: 750-LB CLUSTER, M14E3

1. SCOPE

1.1 This specification covers one type of fin.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein:

SPECIFICATIONS

FEDERAL

PPP-B-636 - Box, Fiberboard.

MILITARY

MIL-C-11133 - Crate, Wood, Open, Wirebound.

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-1168 - Lot Numbering of Ammunition.

DRAWINGS

US ARMY MUNITIONS COMMAND

EDGEWOOD ARSENAL

DL14-23-4082 - Fin Assembly, Bomb: 750-Lb Cluster, M14E3.

FSC 1325

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Materials and components.

3.1.1 Materials. All materials cited on Drawing DL14-23-4082 or on the subsidiary drawings shall conform to the specifications listed thereon, or to the specific characteristics set forth on the drawings.

3.1.2 Components. All components of the fin shall conform to the specifications and drawings listed on Drawing DL14-23-4082 and subsidiary drawings.

3.2 Assembly. The fin shall be assembled as shown on Drawing E14-23-4082.

3.3 Tie-rod (Drawing E14-23-4087). The tie-rod brazed joints shall have an effective braze area of not less than 85 percent of the joint area when tested as specified in 4.4.4.

3.4 Preproduction. Prior to the start of regular production, a preproduction sample of fins and tie-rods shall be produced in accordance with this specification for examination and tests (see 4.3).

3.5 Workmanship. The fin shall be free from foreign matter (oil, grease or dirt) and damage such as dents, cracks or deformation which could affect its intended use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection.

4.1.1 Supplier's responsibility. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to specified requirements.

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the currentversion before use.

4.1.2 Objective evidence. The supplier shall provide objective evidence acceptable to the contracting officer that the requirements of 3.1 and section 5 for which specific inspection has not been provided in this specification have been satisfied.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

(a) Preproduction inspection (see 4.3).
(b) Quality conformance inspection (see 4.4).

4.3 Preproduction inspection.

4.3.1 Sample. A preproduction sample of 10 fins and 12 tie-rods shall be produced using the same methods, materials, equipment and processes as will be used during regular production.

4.3.2 Inspection procedure.

4.3.2.1 For examination. The sample fins shall be examined in accordance with the classification of defects. The AQL's do not apply.

4.3.2.2 For destructive test. Two tie-rods shall be taken at random for testing in accordance with 4.4.4.

4.3.3 Acceptance/rejection criteria. The preproduction sample shall comply with the examinations and test specified in 4.3.2 to be acceptable. The acceptance number is zero. The supplier shall obtain written approval from the contracting officer prior to proceeding with regular production.

4.4 Quality conformance inspection.

4.4.1 Lotting. Each lot shall be identified and controlled in accordance with MIL-STD-1168 and consist of one week's production.

4.4.2 Sampling.

4.4.2.1 For examination. Sampling shall be conducted in accordance with MIL-STD-105.

4.4.2.2 For destructive test. Two tie-rods shall be taken at random from each day's production.

4.4.3 Inspection procedure.

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

4.4.3.1 For examination. The sample fins shall be examined in accordance with the classification of defects and MIL-STD-105.

4.4.3.2 For destructive test. The sample tie-rods shall be tested in accordance with 4.4.4.

4.4.3.3 Classification of defects.

(a) Fin, 750-pound cluster, M14E3 (Drawing E14-23-4082).

Categories	Defects
Critical:	None defined
Major:	AQL 1.0 percent defective
101	Component missing
102	Component incorrectly assembled
103	Fin orientation incorrect
104	Perpendicularity incorrect
105	Spotwelding incorrect
106	Dimension (24.47) incorrect
107	Fuze adapter threads incorrect (Drawing C14-23-1844)
108	Cone diameter (15-31/32) incorrect (Drawing C14-23-1352)
109	Brazing incorrect (Drawing D14-23-1831)
110	Frame configuration incorrect (Drawing E14-23-1836)
111	Marking incorrect
112	Workmanship (3.5)
Minor:	AQL 2.5 percent defective
201	Fuze fairing location incorrect
202	Protective finish missing
203	Marking illegible
204	Tube guide obstructed (Drawing B14-23-1535)

(b) Tie-rod, body assembly (Drawing D14-23-2020).

Categories	Defects
Critical:	None defined

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

4.4.3.3 Classification of defects (continued).

(b) Tie-rod, body assembly (Drawing D14-23-2020)(continued).

Categories		Defects
Major:		AQL 1.0 percent defective
	101	Length incorrect
	102	Threads incorrect
	103	Brazing incorrect
	104	Workmanship (3.5)
Minor:		AQL 2.5 percent defective
	201	Slot location incorrect

(c) Yoke, tie-rod (Drawing E14-23-4085).

Categories		Defects
Critical:		None defined
Major:		AQL 1.0 percent defective
	101	Rivets or bolts missing
	102	Dimension (11.519) incorrect
	103	Material incorrect
	104	Countersink missing
	105	Tack weld missing or inadequate
	106	Welding incorrect
	107	Workmanship (3.5)
Minor:		AQL 2.5 percent defective
	201	Pin length incorrect
	202	Burrs not removed
	203	Dimension (4.00) incorrect
	204	Pin diameter incorrect
	205	Dimension (5.12) incorrect

(d) Tie-rod assembly (Drawing E14-23-4087).

Categories		Defects
Critical:		None defined

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

4.4.3.3 Classification of defects (continued).

(d) Tie-rod assembly (Drawing E14-23-4087)(continued).

Categories	Defects
Major:	AQL 1.0 percent defective
101	Length incorrect
102	Rivets loose or missing
103	Perpendicularity incorrect
104	Leg connector to tie-rod braze incorrect
105	Workmanship (3.5)
Minor:	AQL 2.5 percent defective
201	Protective finish incorrect

(e) Ring, locking (Drawing B14-23-4084).

Categories	Defects
Critical:	None defined
Major:	AQL 1.0 percent defective
101	Hole location incorrect
102	Thread 10-32-NF-2 incorrect
103	Thread 3-3/4-12UN-2B incorrect
104	Workmanship (3.5)
Minor:	AQL 2.5 percent defective
201	Holes not countersunk
202	Protective finish missing

(f) Crate, wood, wirebound (Drawing E14-17-1503).

Categories	Defects
Critical:	None defined
Major:	AQL 2.5 percent defective
101	Center block members length incorrect or incorrectly assembled

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

4.4.3.3 Classification of defects (continued).

(f) Crate, wood, wirebound (Drawing E14-17-1503)(continued).

Categories		Defects
Major(continued):		
	102	Positioning pins location incorrect
	103	Top assembly overall dimension incorrect
	104	Battens incorrectly located
	105	Center block assembly incorrectly located
	106	Base assembly overall dimensions incorrect
	107	Disc incorrect or incorrectly located
	108	Base assembly or top assembly stock size incorrect
	109	Blank section spacing or overall dimensions incorrect
	110	Blank reinforcing strip location or level incorrect
	111	Component missing
Minor:	AQL 4.0 percent defective	
	201	Strapping incorrect
	202	Component loose or damaged
	203	Binding wire location incorrect

(g) Packing, 750-pound cluster fin (Drawing E14-17-923).

Categories		Defects
Critical:		None defined
Major:	AQL 1.0 percent defective	
	101	Tie-rod not securely wired to frame
	102	Fin not located on pins
	103	Cap plug missing or incorrectly assembled
	104	Blank incorrectly secured
	105	Marking incorrect
	106	Workmanship (3.5)
Minor:	AQL 2.5 percent defective	
	201	Marking illegible

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

4.4.4 Test for tie-rod. Test shall be conducted as follows: Using a suitable fixture the tie-rod brazed joint shall be peeled and an evaluation made of the joint. Joints with less than required braze contact constitute poor quality and shall be rejected.

4.5 Acceptance/rejection criteria. If any brazed joint fails the test in 4.4.4, the items made since the last successful peel test shall be rejected.

5. PREPARATION FOR DELIVERY

5.1 Packing Level A. The fin shall be packed in accordance with Drawing E14-17-923. Each crate or wood parts thereof shall be preservative-treated in accordance with MIL-C-11133.

5.2 Marking. In conjunction with information furnished in the contract or order, shipping containers shall be marked in accordance with Drawing E14-17-923, as applicable.

6. NOTES

6.1 Intended use. This item is a conponent of the M36E2 cluster.

6.2 Ordering data. Procurement documents should specify the following:

(a) Title, number and date of this specification.
(b) Preproduction.

(1) Time allowed for supplier submission of samples for Government test and evaluation after award of contract.
(2) Name and address of test facility and shipping instructions when testing is performed by the Government.
(3) Time required for the Government to notify the supplier whether or not to proceed with production.

6.3 Supersession data. This specification supersedes Edgewood Arsenal Purchase Description EA-F-1078, 5 June 1970.

Custodian:

Army - MU

Preparing activity:

Army - MU (EA)

Project No. 1325-A451

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

SPECIFICATION ANALYSIS SHEET

Form Approved
Budget Bureau No. 22-R255

INSTRUCTIONS: This sheet is to be filled out by personnel, either Government or contractor, involved in the use of the specification in procurement of products for ultimate use by the Department of Defense. This sheet is provided for obtaining information on the use of this specification which will insure that suitable products can be procured with a minimum amount of delay and at the least cost. Comments and the return of this form will be appreciated. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments and suggestions submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or serve to amend contractual requirements.

SPECIFICATION

ORGANIZATION

CITY AND STATE

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE SPECIFICATION CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?

A. GIVE PARAGRAPH NUMBER AND WORDING.

B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY SPECIFICATION REQUIREMENT CONSIDERED TOO RIGID

3. IS THE SPECIFICATION RESTRICTIVE?

☐ YES ☐ NO *(If "yes", in what way?)*

4. REMARKS *(Attach any pertinent data which may be of use in improving this specification. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity)*

SUBMITTED BY *(Printed or typed name and activity - Optional)*

DATE

DD FORM 1 JAN 66 1426

REPLACES EDITION OF 1 OCT 64 WHICH MAY BE USED.

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:58Z
Check the source to verify that this is the current version before use.

FOLD

POSTAGE AND FEES PAID

OFFICIAL BUSINESS

Commanding Officer
Edgewood Arsenal
ATTN: SMUEA-TS-S
Edgewood Arsenal, MD 21010

FOLD

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:58Z
Check the source to verify that this is the current version before use.