INCH-POUND

MIL-C-48697 (AR)
AMENDMENT 3
8 December 1992
SUPERSEDING
AMENDMENT 2
19 January 1990

MILITARY SPECIFICATION

CARTRIDGE 60MM, TP, M50A3
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of MIL-C-48697 (AR), dated 11 August 1987 and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 10

4.4.2.4, Add Major 105 and 106 which read as follows:

"105 Sealing compound bead improperly located, missing or not full 360 degrees in base of cartridge housing cavity (prior to insertion of ignition cartridge) ... Visual.

106 Sealing compound bead improperly located, missing or not full 360 degrees on red end of ignition cartridge (Prior to seating of primer into fin cavity) ... Visual."

Major 101: Delete in its entirety.

Majors 107 and 108: Add as follows:

"107 Fuze not fully seated ... 0.40% ... 3.2 ... Visual
108 Fin and fin extension not fully seated ... 0.40% ... 3.2 ... Visual"

Minor 203: Delete in its entirety.

PAGE 11

* 4.4.2.5, Change Major 101 to read as follows:

"101 Propellant sheets damaged ... 100% ... 3.2 ... Visual."

AMSC N/A FSC 1310

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202640-22T19:37Z
Check the source to verify that this is the current version before use.

MIL-C-48697 (AR)
Amendment 3

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1310-A526)

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:37Z
Check the source to verify that this is the current version before use.