MIL-Q-46315C (AR)
AMENDMENT 2
15 October 1987
SUPERSEDING
AMENDMENT 1
25 September 1973

MILITARY SPECIFICATION

QUADRANT, FIRE CONTROL: M15

This Amendment forms a part of Military Specification MIL-Q-46315C (MU), dated 15 August 1972, and is approved for use within the U.S. Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.5.3: Delete paragraph and substitute:

"3.5.3 Vibration. The quadrant shall show no evidence of physical failure or damage and shall meet the requirements of 3.5.5 to 3.9 inclusive after being vibrated under conditions specified in 3.5.3.1 and 3.5.3.2."

* 3.5.3.1: Delete paragraph and substitute:

"3.5.3.1 Vibration A. Vibration shall be in accordance with MIL-F-13926, Procedure VI, Condition B, which involves a displacement of 1/32 inch (total) at frequencies which vary logarithmically from 10 to 55 to 10 cycles per second."

3.5.3.2: Delete paragraph and substitute:

"3.5.3.2 Vibration B. Vibration shall be in accordance with MIL-STD-810, Procedure VIII, using frequencies which vary logarithmically from 5 to 500 to 5 cycles per second with a maximum displacement of 0.5 inch."

PAGE 4

* 3.6.4: Delete paragraph and substitute:

"3.6.4 Backlash. Backlash in the elevation and cant worm mechanisms shall not exceed 0.3 mil."

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:32Z
Check the source to verify that this is the current version before use.

* 3.6.5.1: Delete paragraph and substitute:

"3.6.5.1 Cant mechanism. The cant worm mechanism shall provide a minimum travel of 34° (604.44 mils) in a clockwise and counterclockwise direction from the position specified in 3.4(b) and the cross level vial centered within a graduation line."

PAGE 6

4.3.2.1: Delete all after second sentence.

4.3.2.2: Renumber to 4.3.2.4.

PAGE 7

4.3.2.2: Add the following paragraph:

"4.3.2.2 First article test. The mount shall successfully comply with the requirements outlined in Tables II and III and Vibration "B" and shock tests of 3.5. Additional first article testing will be required when the processes, material or changes in design occur subsequent to the original first article approval. All first articles so produced shall be submitted to the Government in accordance with 4.2 for approval."

4.3.2.3: Add the following paragraph:

"4.3.2.3 Final acceptance inspection. Subsequent to first article approval, examination and tests related to Section 3 shall be performed on a single defect (individual characteristic) basis in accordance with MIL-STD-105 and the sampling plans specified in Tables II and III. Examination and tests for Packaging, Packing, and Marking shall be in accordance with MIL-P-14232 and Section 5 herein. The tabulated classification of defects in Tables II and III shal constitute the minimum inspection to be performed by the supplier after first article approval and prior to Government acceptance or rejection by item or lot."

4.3.4, Table III: Delete characteristics 305 and 306.

PAGE 9

4.6.1.2: Change first sentence to read: "This test shall be performed as specified in MIL-F-13926, Procedure VI, Condition B, with the vibration input swept logarithmically from 10 to 55 to 10 cycles per second."

Source: https://assist.dla.mil -- Downloaded: 202610-22T05:32Z
Check the source to verify that this is the currentversion before use.

4.6.1.3: First sentence: Change Procedure I to Procedure VIII. Delete all after exceptions and substitute: "No resonance search or dwell shall be performed. Vibration input shall be at 0.5 inch DA from 5 cycles per second to the 1.5g curve, to 0.033 inch DA then to the 4g curve continuing to 500 cycles per second. Vibration input shall be sept logarithmically with the complete frequency exposure from 5 to 500 and return to 5 cycles per second completed in 15 minutes."

PAGE 10

* 4.6.2.5:

8th sentence: Delete and substitute:

"Backlash in the cant mechanism will be measured by setting any selected cant angle into Inspection Aid (8658940) placed on Adapter Backlash (11739342) and rotating the cant knob to make the Inspection Aid level. Scribe a line on the casting and align an index mark on the cant knob in coincidence with the casting line after Inspection Aid level vial has been set to indicate level."

Line 22: After "vial" add "of the Inspection Aid".

The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1290-A414)

Source: https://assist.dla.mil -- Downloaded: 202640-22T05:32Z
Check the source to verify that this is the currentversion before use.