INCH-POUND
MIL-F-70435 *(AR)*
AMENDMENT 7
29 November 1994
SUPERSEDING
AMENDMENT 6
18 September 1989

MILITARY SPECIFICATION

FUZE, POINT DETONATING, M759

This amendment forms a part of Military Specification MIL-F-70435 (AR), dated 15 July 1983, and is approved for use by the US Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

* 3.2.1.4: Delete in its entirety and substitute the following:

3.2.1.4 Arming. The fuze, assembled to a M789 HEDP cartridge (fuze carrier), shall upon impact with a 0.063 inch nominal thickness) 2024-TB aluminum alloy plate at a range of 150 meters ± 1 meter, cause the projectile to produce an average hole of not less than seven (7) inches in diameter, exclusive of petals, and show evidence of shrapnel on the forward face or remnants of the aluminum plate with a reliability of 90 percent. (See 4.6.2)"

* 3.2.1.5: Delete in its entirety and substitute the following:

3.2.1.5 Target reliability The fuze, assembled to a M789 HEDP cartridge (fuze carrier), shall upon impact with a 0.060 inch (nominal thickness) mild steel plate at a range of 200 meters + 2 meters, cause the projectile to produce an average hole of not less than seven (7) inches in diameter, exclusive of petals, and show evidence of shrapnel on the forward face or remnants of the steel plate with a reliability of 95 percent. (See 4.6. 3)

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:26Z
Check the source to verify that this is the current version before use.

PAGE 3 (continued)

3.2.2.4: Delete in its entirety and substitute the following:

"3.2.2.4 Transportation vibration/temperature. After undergoing vibration at temperatures from -54 degrees to 71 degrees C, in accordance with MIL-STD-331, Test 119, the fuze shall be safe to handle and meet the arming, non-arming and target reliability requirements (see 4.5.2.4)."

PAGE 5

Table I, Jumble: Delete '4.2.2" and substitute "4.5.2.2"

* Table I, under Next higher assembly: Delete "11825925/ll825948" and substitute "11825955/11825948".

Table I, under Reference/inspection method: Delete "3.3.1, 4.2.2.1, 4.2.2.2.. .4.2.2.9" and substitute "4.3.1/4.4.2 .1, 4.4.2.2..., 4.4.2.9

* Table I: Delete "Base (Dwg 12551751) examination for Defects 32 4.3.1 4.2.2.1"

and substitute "Base (Dwg 12551751) Examination for Defects 32 I 4.4.2.1 9A"

PAGE 8

Table 1: Add Plug, base closure 32 (Dwg. 12551752) examination for defects

"Base 32 4.3.1 4.2.2.1" (Dwg 12551751) examination for defects

"Spitback lead assembly (Dwg. 11834335) Examination for

PACE 9

4.3.1 4.2.2.1 "32 4.3.1 \7visual defects”

Holder and Body Assembly: Delete " (Dwg. 11834315)" and substitute "(Dwg. 11834318)

Table I: Delete “3.3.1” and substitute “4.3.1”

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:26Z
Check the source to verify that this is the current version before use.

PAGE 11

4.4.2.1, Major 102, 103 and 104: Delete "3.3.1" and substitute "3.1.1"

Minor 201: Delete "3.3.1" and substitute "3.1.1"

* 4.4.2.1: Delete in its entirety and substitute the following:

4.4.2.1 (Plug, Base, Closing)

Major	101	Diameter, large inside, max.	.40%	3.1.1	Gage
Major	102	Diameter, thread	.40%	3.1.1	Gage
Major	103	Depth, large inside dia, max	.40%	3.1.1	Gage
Major	104	Thickness, overall, mm.	.40%	3.1.1	Gage
Minor	201	Complete thread	.65%	3.1.1	Gage
Minor	202	Diameter, small Inside, mm.	.65%	3.1.1	Gage
Minor	203	Width, across flats	.65%	3.1.1	Gage
Minor	204	Presence of chamfers	1.00%	3.1.1	Visual"

PACE 12

4.4.2.2, Major 101 and 102: Delete "3.3.1" and substitute 3.1.1"

PACE 13

4.4.2.3, Drawing number: Delete "11820627" and substitute 93580l6"

Major 101 and 102: Delete "3.3.1" and substitute "3.1.1". Minor 201:

Delete "3.3.1" and substitute "3.1.1".

PAGE 14 and 15

4.4.2.4, Major 102: Delete "hold and body" and substitute "holder and body"
Major 101 thru 112: Delete "3.3.1" and substitute "3.1.1".
Minor 201 thru 205: Delete "3.3.1" and substitute "3.1.1"

PACE 16

4.4.2.5, Major 101 Delete "3.3.1" and substitute "3.1.1".

Source: https://assist.dla.mil -- Downloaded: 2026l0-23T03:26Z
Check the source to verify that this is the current version before use.

PAGE 17

4.4.2.6, Major 101 thru 106: Delete "3.3.1" and substitute "3.1.1"

Minor 201 thru 202: Delete "3.3.1" and substitute "3.1.1"

PAGE 18

4.4.2.7, Major 101 thru 107: Delete “3.3.1” and substitute "3.1.1"

Minor 201 thru 202: Delete "3.3.1" and substitute "3.1.1"

Table I: Delete "3.3.1" and substitute "4.3.1"

PAGE 19

4.4.2.8, Minor 201: Delete "presence or roller weight" and substitute “presence of ball weight".

Major 101: Delete "3.3.1' and substitute "3.1.1".

Minor 201: Delete "3.3.1" and substitute "3.1.1"

PAGE 20

4.4.2.9 Major 101 thru 103” De;ete “3.3.1” and substitute “3.1.1”
Minor 201: Delete "3.3.1" and substitute ~

* 4.4.2.9A: Should read as follows:
“4.4.2.9A Base 1 of 1 Dwg No. 12551751
Next higher No. 12551750

CRITICAL:	None defined			
Major:				
101	Diameter, front flange, max.	.40%	3.1.1	Gage
102	Thickness, overall minus flange, max	.40%	3.1.1	Gage
103	Pitch diameter, outside thread	.40%	3.1.1	Gage
104	Depth, large inside diameter	.40%	3.1.1	Gage
105	Diameter, large inside, mm	.40%	3.1.1	Gage
106	Minor diameter, inside thread	.40%	3.1.1	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:26Z
Check the source to verify that this is the current version before use.

PACE 20 (continued)

* 4.4.2.9A (continued)

Minor:				
201	Width, across hex, max	.65%	3.1.1	Gage
202	Complete outside thread	.65%	3.1.1	Gage
203	Complete Inside thread	.65%	3.1.1	Gage
204	Presence of chamfers	1.00%	3.1.1	Visual"

PAGE 21 and 22

4.4.2.l0: Delete "3.3.1" and substitute "3.1.1".

Delete critical 1.

Delete major 101 in its entirety and substitute:

"Height from rear face of base to rear face of closing plug (max)	.40%	3.1.1	Gage"

Delete Major 102 in its entirety and substitute:

"Presence of **or improperly** assembled probe, confinement cup or setback cup.	40%	3.1.1	Visual/ x-ray/ Gage

Minor 201: Delete "3.3.3" and substitute "3.4.5"

Sheet 2 of 3: Note 1 change to Note 3.

PAGE 23

* 4.4.2.10, Sheet 3 of 3: Delete Note 1 in its entirety and substitute the following:

If assemblies are assembled on a qualified assembly machine, this check is performed 100% by the machine and the defects are automatically removed. If the machine fails **veri**fication, the assemblies are 100% x-ray checked with the critical defects manually removed and the lot then submitted or inspection verification of the x-ray sort. If assemblies are hand built, the assemblies are 100% x-ray checked with the critical defects manually removed or are 100% inspected by an approved blast proof gage that will destroy the rotor assembly it is in the unsafe position. The lot is then submitted for x-ray verification of the Inspection. Sample size determination by .25 AQL (minimum sample size Is 315) zero defects allowed. If the lot is rejected the assemblies will be 100% x-ray cracked with the critical defects manually removed and the lot submitted for inspection verification of the x-ray sort.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:26Z
Check the source to verify that this is the current version before use.

PAGE 24

Table II:

Delete all **"Vi** and Vt" and substitute "RI an Rt" wherever it appears.

Add footnote '6' to Target Reliability.

Add footnote "7" to Extended Range and Armor Plate.

Note 2: Delete “(NiNi)“ and substitute "divided"

Delete "devided" and substitute "divIded".

In second sentence: Delete "A" and substitute "at"

PACE 27

4.6: Delete "constant twist” and substitute "gain or progressive twist"

Change the second statement from: Delete "Drawing 282000380" and substitute "28201629 or government 11825969"; to: Delete "Drawing 282000380" and substitute "20201629 or Government 9390748"

* 4.6.2: Delete In Its entirety and substitute the following:

“4.6.2 Arming. The fuze, assembled to a M789 HEDP cartridge (fuze carrier), shall within two (2) minutes after removal from the temperature conditioning chamber be tested at range of 150 meters + 1 meter with an angle or impact of zero (0 degrees, 10 degrees on 0.063 inch 2024-T3 aluminum plate. Failure of the fuze to effect projectile high order function and produce a hole as defined in paragraph 3.2.1.4 shall be considered a defect (See Table 2)."

* 4.6.3: Delete in its entirety and substitute the following:

"4.6.3 Target Reliability. The fuze, assembled to a M789 ..~DP cartridge (fuze carrier), shall within two (2) minutes after removal from the temperature conditioning chamber be tested at a range of 200 meters ±2 meters with an angle of impact: zero (0) degrees ± 10 degrees on 0.060 mild steel late. Failure of the fuze to effect projectile high order function and produce a hole as defined in paragraph 3.2.1.5 shall be considered a defect (See Table 2).

4.6.5: Delete "HEPD" and substitute "HEDP"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:26Z
Check the source to verify that this is the current version before use.

PAGE 28

E.2: Delete "Profidions" and substitute "Provisions".

PACE 29

E.3.7: Delete "firinf" and substitute "firing" Add new paragraph as follows:

"6.3.8 Defective test ammunition If any fuze firing defect is found to have been caused by a defective cartridge and verified by the Government, the firing defect shall be considered a no-test. In such cases the test shall be repeated in whole or in part, as indicated."

* 6.4.: Delete “DRSMC-QAF-S (D) " and substitute "AMSTA-AR-QAC-C".

The margins of this amendment are marked with asterisks to Indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the previous amendment.

Custodian:
Army-AR

Preparing activity:
Army -AR

(Project 1305-AE9l)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:26Z
Check the source to verify that this is the current version before use.