INCH-POUND

MIL-C-48162B (AR)
AMENDMENT 1
4 November 1992

MILITARY SPECIFICATION

CARTRIDGE, IGNITION, M702
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of MIL-C-48162B (AR), dated 14 August 1987, and is approved for use by the U.S. Army Armament, Munitions, and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1, Add new military specification as follows:

"MIL-P-60312 - Parts, Molded, Plastic Foam, Polystyrene (For use with ammunition)"

PAGE 2

2.1.2, Product and Packaging Drawings, 9287826, delete "Fiberboard" and substitute "Wirebound."

PAGE 13

4.4.2.6, Critical 3, add note (a) after sample size and in notes section which reads:

"(a) This Five Foot Drop Test on 25 samples will only be performed on each new lot of primers when they are initially introduced into M702 production."

* Major 104, change as follows and add note (b):

"104 Leak test...60(b)...3.5...4.5.3"

"(b) Test shall be performed on material selected from each days production. If more than 3 failures occur, that days production shall be 100% screened.

AMSC N/A FSC 1310

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:15Z
Check the source to verify that this is the current version before use.

PAGE 15

4.4.2.7, Add new major and note (a) and (b) as follows:

"102 Moisture content excessive (a)(b) 5.1 (a)(b)

"(a) Requirement and inspection procedure shall be per MIL-P-60312. Two (2) samples shall be randomly selected from a quantity of trays for scheduled production for five (5) consecutive shifts. If one or more samples are defective, the quantity of production represented by the sample shall be rejected. Inspection shall be accomplished within 24 hours of scheduled use of the trays."

"(b) Moisture content determination not required when this packing material is stored in an environmentally controlled area maintained at 40 percent maximum relative humidity (RH) @ 72 degrees F for at least 24 hours prior to using."

PAGE 16

4.4.2.8, Add new major and note (a) as follows:

"103 Moisture content excessive for any packaging component (4 items) (a) 5.1 Gage"

"(a) Components shall be inspected prior to use every hour during the production shift. If any sample exceeds the requirement, the inspection lot shall be rejected from further processing."

PAGE 17

4.4.2.9, Add new major and note (a) as follows:

"104 Environmental conditions inadequate (a) 5.1 Gage"

"(a) Temperature and humidity shall be checked at the beginning and end of each shift. If conditions are not proper at either time, the quantity of product represented by the conditioning shall be rejected for further processing."

PAGE 18

4.4.2.11, 4.4.2.12, 4.4.2.13, add new paragraphs (attached).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:15Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48162B (AR)
AMEMDMENT 1

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.11	Box, Wirebound, Before Packing	1 OF 1	9294951
			NEXT HIGHER ASSEMBLY 9287826

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside dimensions incorrect		0.40%	5.1	Gage
102	Broken, split or missing components		0.40%	5.1	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.10	Visual

REMARKS

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-02-27 10:45:52
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48162B (AR)
AMENDMENT 1

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.12	Packed Wirebound Box, Before Closing				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
Major					
101	Improperly packed		0.40%	5.1	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

47(18E)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:15Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48162B (AR)
AMENDMENT 1

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.13	Packed Wirebound Box, After Closing		NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
Major					
101	Wire closing improper		0.40%	5.1	Visual
Minor					
201	Conteuts loose		0.65%	5.1	Manual
202	Marking incomplete, incorrect or illegible		0.65%	5.1	Visual
203	Evidence of poor workmanship		0.65%	3.10	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-02-22 19:15Z
Check the source to verify that this is the current version before use.

PAGE 20

4.4.3.2.3, add to last sentence as follows:

"(Test shall be performed on new primer lots prior to use in M702 production. Acceptable results shall qualify the primer lot for use in M702 production)."

PAGE 22

4.5.2.3, delete paragraph in its entirety and substitute as follows:

"4.5.2.3 Safety drop test. Each of the test assemblies will consist of an inert filled M720 body, and inert M935 Fuze and a M27 Tailfin assembly. After inserting the sample M702 to be tested, the cartridge total drop weight will be 3.75 pounds +/- 0.05 pounds. The cartridge will be dropped five foot onto a steel plate first in the fin down orientation and then dropped fuze end down. Each cartridge will have the inert M935 fuze and M27 Tailfin assembly replaced after each double drop. the drop height shall be measured from the lowest point of the cartridge orientation to the top of the anvil surface. Any test assembly which functions as a result of the drop shall be classed defective. All questionable test assemblies shall be downloaded to verify primer/black powder pellet functioning or nonfunctioning. All components used for this test shall not be returned to their respective lots."

PAGE 23

4.5.3, change first sentence to read as follows

"After the ignition cartridges have been assembled and the RTV is applied, the ignition cartridges will be kept in the controlled environmental storage for two (2) hours minimum prior to performing the leak test."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1310-A522)

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:15Z
Check the source to verify that this is the current version before use.