INCH-POUND

MIL-C-70544A (AR)
AMENDMENT 3
15 March 1991
SUPERSEDING
AMENDMENT 2
26 March 1990

MILITARY SPECIFICATION

CARTRIDGE, 81MM, ILLUMINATING, M853A1,
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-C-70544A (AR), dated 28 January 1988, and is approved for use by the U.S. Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

* 2.2 Change this paragraph to "2.1.2".

Under Inspection Equipment Drawings, add the following:

"6518071 - Alignment Gage
6518072 - Alignment Check Gage"

PAGE 3

* 3.4 Change "60" to "65" and change "550,000" to "525,000".

* 3.4.1 Delete in its entirety and substitute the following:

"3.4.1 Pull test for oval sleeve crimp to suspension wire. The oval sleeve crimp to the suspension wire shall withstand a pull force of 1800 pounds minimum."

PAGE 7

* 4.4.1.d Delete in its entirety and substitute the following:

"4.4.1.d Propelling charges, of one lot interfix number, from one manufacturer."

PAGE 11

* 4.4.2.4, Under Major 105, delete in its entirety and substitute the following:

"Taped shroud loops not attached to suspension wire loop... 0.40%...3.2...Visual".

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.
Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.

PAGE 11

Under major category, add the new following:

* "106 Tape missing from the sleeve and cable ...0.40%...3.2 ...Visual."

PAGE 16

4.4.2.8, Under Major category add the following:

"104 Increment tape missing...0.40%...3.2...Visual
105 Propelling charge support missing or damaged ...0.40%... 3.2...Visual.
106 Tab at the end of increment tape inadequate ...0.40%... 3.2...Visual.
107 Tab at the end of increment tape covered by propellant charge support label...0.40%...3.2...Visual."

PAGE 18

4.4.2.10, Change existing "Minor 202" to "Minor 204".

Add new following Minor 202, 203, 205 and 206 as follows:

"202 Plastic sheet not present in every sixth box ...0.65%... 3.2...Visual
203 Box containing plastic sheet not appropriately marked... 0.65%...3.2...Visual
* 205 Circular firing scale not present in every third box... 0.65%...3.2...Visual
* 206 Box containing circular firing scale not appropriately marked...0.65%...3.2...Visual"

PAGE 20

* 4.4.3.2, Change "60" to "65" and change "550,000" to "525,000".

PAGE 22

* 4.4.3.3, Change "Major: Illuminant fails to ignite or provide effective illumination for 50 seconds or less (See Note 2)." to "Major: Illuminant fails to ignite or provide effective illumination for less than 50 seconds (See Note 2)."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.

PAGE 23

* 4.4.3.5, Change "8865018" to "9209555-8".

4.4.3.5, Delete "4.4.3.5.1 and 4.4.3.5.2" and substitute "4.4.5.10."

* 4.4.3.5.1, Change "1050" to "1800".

4.4.3.5.1, At the last sentence, delete "until it is requalified in accordance with paragraph 4.4.3.5.2."

4.4.3.5.2, Delete in its entirety.

PAGE 26

* 4.4.5.6, Delete the word "primers" from the fifth line. Add "and chamber pressure" after muzzle velocity in the last sentence before Table III.

NOTE: The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian
Army-AR

Preparing activity:
Army-AR

(Project 1315-AC88)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:39Z
Check the source to verify that this is the current version before use.