MILITARY SPECIFICATION

COMPUTER LOGIC UNIT: 8623272

This amendment forms a part of Military Specification MIL-C-60215(MU), dated 5 March 1965.

Paragraph 1.1: Delete "FLAT" and substitute "FALT".

Paragraph 2.1, under DRAWINGS: Add the following:

"C8213506	Power Cable
C8623423	Cable Assembly
F8623471	Wiring Harness Jumper"

Paragraph 3.4.1, first sentence: Delete and substitute: "The FALT with Power Cable C8213506, Wiring Harness Jumper F8623471, and Cable Assemblies C8623423-1 through C8623423-5, enhoused within the FALT transit case, shall be capable of withstanding a circular motion of 1 ± 0.1 inch diameter at a frequency of 271 ± 2 cycles per minute for a total of 3 hours."

Paragraph 3.6.1: Delete in its entirety and substitute:

"3.6.1 Vibration.- The FALT, including the cables and wiring harness specified in 3.4.1 shall be capable of withstanding a simple harmonic motion with a single amplitude of 0.015 inch (0.03 inch total excursion) and a frequency varying uniformly between the limits of 10 and 55 cycles per second and return to 10 cycles per second in approximately one minute. The FALT shall be capable of withstanding this motion for a period of 10 minutes in each of the 3 mutually perpendicular axes (total 30 minutes)."

Paragraph 4.2.4, Table A, Characteristic Column: Add to Characteristic "125. FALT run-in", the following: "(except items selected for tests specified in 4.3.2)".

Paragraph 4.5, first sentence: Delete and substitute: "The FALT with Power Cable C8213506, Wiring Harness Jumper F8623471, and Cable Assemblies C8623423-1 through C8623423-5, enhoused within the FALT transit case, shall be placed on a test table, but not fastened to it".

FSC 1220

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:18Z
Check the source to verify that this is the current version before use.

Paragraph 4.9.2(e), Table II, Columns A, B and C, line 7: Delete "-1.5R 1.25, 12 watt 6.8, 1 watt" and substitute "-1.5R 13.75, 25 watt* 75, 5 watt*",; Add the following notation at bottom of Table II: "*Return -1.5R loads to -18R not to Gnd".

Paragraph 4.9.5(f)(2): Delete "-6.2 ± 0.2 volts" and substitute "-6.0 ± 1 volts".

Paragraph 4.9.6.2, Table VII, under Nominal Voltage, line 4: Delete "+6" and substitute "+6(z)"; line 14: Delete "+6(z)" and substitute "+6".

Paragraph 4.9.9: Delete Step 18(c) and (d) in their entirety and substitute the following:

"Step 18(c) Manual Control Lamp 7 shall go out. Release hand sprocket switch.

Step 18(d) Operate clock key two times."

Table XI, CTO Voltage on Pin J10-GG Column: Delete "+5.58" and "+6.1" and substitute "+5.0" and "+7.0". Make the same changes in Tables XII through XIX.

Paragraph 4.9.10, Step 4: Delete "Table VIII" and substitute "Table XIII".

Paragraph 4.9.10, Step 10(h): Delete "E5, E5" and substitute "E5".

Paragraph 4.9.12, Step 3(d): Delete: "#123" and substitute "123".

Table XXII: Delete the values in the last two columns and substitute the following values:

"Max.	Min.
15.0	12.5
34.4	28.6
18.2	15.2
17.6	14.8
49.2	40.9
12.4	10.4
24.2	20.3
196.9	167.4
196.9	167.4
27.3	22.8
23.3	19.3
17.5	14.5"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:18Z
Check the source to verify that this is the current version before use.

After paragraph 4.9.28 add new paragraph:

"4.9.29 Falt to Falt test.- F tape, Part No. 8213330-25 may be substituted for paragraphs 4.9.5 and 4.9.9 through 4.9.27 except 4.9.25. This test shall be performed using F tape, Signal Data Reproducer and Control Box, Computer Logic Unit Test Set C-4020/GSM-70, in accordance with instructions in TM-9-4931-204-34/5. This test and the self-test (4.9.28) shall be performed with the Falt front and rear covers removed."

Paragraph 4.10.1: Delete in its entirety and substitute:

"4.10.1 Vibration test.- The Falt shall be tested as outlined in MIL-F-13926, Procedure II, Condition B except the frequency, amplitude, direction and duration shall be as specified in 3.6.1. Subsequent to this test, the unit shall be visually inspected for physical damage then tested as outlined in 4.10.2."

Figure 3: Delete "D1520 or equivalent" and substitute "D152 or equivalent".

Custodian:

Army - MU

Preparing activity:

Army - MU

Project No. 1220-A037

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:18Z
Check the source to verify that this is the current version before use.