MILITARY SPECIFICATION

JETTISON PLATE (WITH ACCESSORIES) FOR DISPENSER, XM19 PARTS FOR AND ASSEMBLY

1. SCOPE

1.1 This specification covers the assembly and parts for one type of jettison plate for use with the XM19 Dispenser.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-2550 - Ammunition and Special Weapons; General Specification For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105)
MIL-STD-109 - Quality Assurance Terms and Definitions
MIL-STD-1168 - Lot Numbering of Ammunition
MIL-STD-1235 - Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes

FSC: 1370

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY MUNITIONS COMMAND

9241092 - Crate, Wirebound, Packing, Ammunition, For Dispenser, XM19
9242543 - Carton, Packing, Ammunition, for Tiedown Hardware for XM19 Dispenser
9243965 - Box, Packing, Ammunition, for Tiedown Hardware for XM19 Dispenser
9251396 - Jettison Assembly
9255504 - Box, Packing, Ammunition for Firing Device Panel Assembly, Cable Assembly and XM19 Test Set Assembly
9255505 - Carton, Packing, Ammunition, for Firing Device Panel Assembly, Cable Assembly and XM19 Test Set Assembly

PUBLICATIONS

U.S. ARMY MUNITIONS COMMAND

ET 9251396 - Equipment Tabulation

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Materials.-Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 Assembly.-The jettison plate assembly shall comply with all requirements specified on Drawing (dwg.) 9251396, and with all requirements specified in applicable specifications.

3.3 Leakage

3.3.1 Safety valve.-The safety valve leakage rate shall not exceed 10 cubic centimeters (cc) per minute of free air (measured at atmospheric pressure) when tested as specified in 4.4.1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

3.3.2 Interlock assembly.-The interlock assembly leakage rate shall not exceed 120cc per minute of free air (measured at atmospheric pressure) when tested as specified in 4.4.2.

3.3.3 Pressure system.-The pressure system leakage rate shall not exceed 420cc per minute of free air (measured at atmospheric pressure) when tested as specified in 4.4.3.

3.4 Soundness of welds.-The following welded areas shall be free from cracks, voids, non-metallic inclusions, scattered slag, and defects which indicate welds were made with a dirty electrode or on improperly prepared surfaces:

Rails to plate.
Plug in piston cylinder.
Piston cylinder to support angle.

Examination shall be made as specified in 4.4.4.

3.5 Functioning.-The XM19 Dispenser shall eject from its mooring on the jettison plate at a velocity of 11 feet per second (fps) minimum to 15 fps maximum, when tested as specified in 4.4.5.

3.6 Five-foot drop (test set only).-The test set shall show no evidence of separated parts and shall function **satisfactorily** when tested as specified in 4.4.9.

3.7 Functioning of test set.-The test set shall function satisfactorily as evidenced by a flash of the lamp with the output terminals connected to a dummy load, and by no flash of the lamp with the output terminals open when tested as specified in 4.4.10.

3.8 Workmanship

3.8.1 Welding.-The outer surface of all welds shall be smooth and free of cracks, pits, craters, tip pick-up, porosity undercutting and defects which indicate welds were made with a dirty electrode.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

3.8.2 General.-All components and assemblies shall be fabricated in a thorough workmanlike manner. They shall be free of burrs, chips, sharp edges, cracks, unblended radii, surface defects, dirt, grease, corrosion products and other defects and foreign matter which would affect appearance or serviceability. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agents. All required markings shall be neat, legible and sharply defined. All packing components shall be dry.

3.9 First article inspection.-This specification makes provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Reference shall be made to MIL-STD-109 to define terms used herein. The provisions of MIL-A-2550 shall apply.

4.1.1 Submission of product.-At the time each completed lot of items deliverable under the contract is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

a. A statement that the lot complies with all of the quality assurance provisions specified in this specification.
b. Drawing and specification number and date, together with identification and date of changes thereto.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

c. A statement that all material purchased by the contractor meets requirements, when such material is controlled by Government or commercial specifications referenced in any of the contractual documents, and that certificates of conformance are on file and available for review.

d. Number of items in the lot.

e. Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.2 First article inspection

4.2.1 Submission.-The contractor shall submit a first article sample as designated by the contracting officer for evaluation in accordance with the provisions of 4.2.2. The first article sample shall consist of one (1) complete jettison plate with accessories (Dwg. 9251396) which has been manufactured using the same production processes, procedures and equipment which will be used in fulfilling the contract. All parts and materials, including packaging and packing, shall be obtained from the same source of supply as will be used in regular production. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract and submit a record of this inspection with the sample, including a certificate of conformance for materials. A sample containing known defects will not be submitted unless specifically authorized by the contracting officer. A first article sample as directed by the contracting officer, shall also be submitted whenever there is a lapse in production for a period in excess of 90 days or whenever a change occurs in manufacturing process, material used, drawing or specification such as to significantly affect product uniformity as determined by the Government.

4.2.2 Inspections to be performed.-The jettison plate assembly shall be subjected by the Government to any or all of the examinations and tests specified in 4.3 of this specification any any or all requirements of the applicable drawings. In addition the following tests will be performed:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

a. Pressure system leakage (see 3.3.3).
b. Soundness of welds (see 3.4)
c. Functioning (see 3.5).
d. Five-foot drop (see 3.6).
e. Test set functioning (see 3.7).

4.2.3 Rejection.-If any jettison plate assembly or accessory fails to comply with any of the applicable requirements, the first article sample shall be rejected. The Government reserves the right to terminate its inspection upon any failure to comply with any of the stated requirements.

4.3 Inspection provisions

4.3.1 Lot formation.-The term "inspection lot" as used in this specification is defined as an essentially homogeneous collection of units of product from which a representative sample is drawn and inspected to determine conformance with applicable requirements. The sample selected shall represent only that quantity of units from which the sample was drawn and shall not be construed to represent any prior or subsequent quantities presented for inspection. Homogeneity shall be considered to exist provided the inspection lot has been produced by one manufacturer in one unchanged process, using the same material and methods, in accordance with the same drawings, same drawing revisions, same specifications and same specification revisions and complies with the provisions for submission of product as specified in MIL-STD-105. Changes to the process, specification or drawing not affecting safety, performance, interchangeability, or storage, as determined by the Government, shall not be deemed to alter the homogeneity of an inspection lot. All material submitted for inspection in accordance with this specification shall comply with the homogeneity criteria specified herein regardless of the type of sampling procedure which is being applied to determine conformance with requirements. Lot numbering, as required, shall be in accordance with MIL-STD-1168.

4.3.2 Examination.-The examinations listed in the following subparagraphs shall be performed on inspection lots (see 4.3.1) of the components or assemblies designated in the applicable paragraph headings. Inspection for critical defects (and major defects, when so specified) shall be 100 percent. Sampling plans for major and minor defects shall be in accordance with MIL-STD-105 except that continuous sampling plans in accordance with

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

MIL-STD-1235 may be used if approved by the Government. Instead of applying the AQL's designated herein to the groups of major and minor defects listed, the Contractor may elect to apply the AQL's to individual defects using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. When this method is elected, it shall be applied to all of the major and minor defects listed in the applicable subparagraph of this section, except where 100 percent inspection is specified, and be documented as part of the contractor's inspection system. Equipment necessary for the performance of the inspections listed shall be in accordance with 4.3.4.

4.3.2.1 Case, modified (see Dwg. 9247447 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No. (see 6.2)
Critical:	None defined		
Major:	None defined		
Minor:	AQL 4.00 percent		
201.	True position of small holes	Gage	01001
202.	Diameter of small holes, minimum (min.)	Gage	01002
203.	True position of intermediate hole	Gage	01003
204.	Diameter of intermediate hole, min	Gage	01004
205.	True position of large holes	Gage	01005
206.	Diameter of large holes, min	Gage	01006
207.	Location of cutout	Gage	01007
208.	Length of cutout, maximum (max.)	Gage	01008
209.	Width of cutout, max	Gage	01009
210.	Any hole missing	Visual	01010
211.	Evidence of poor workmanship (see 3.8)	Visual	01011

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.2 Plate, mounting (see Dwg. 9247452 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		
Minor:	AQL 4.00 percent		
201.	Length, min	Gage	02001
202.	Width, min	Gage	02002
203.	Thickness, min	Gage	02003
204.	Diameter of large hole(s)	Gage	02004
205.	Diameter of small hole(s)	Gage	02005
206.	Location of large holes	Gage	02006
207.	Location of small holes	Gage	02007
208.	Countersink missing	Visual	02008
209.	Evidence of poor workmanship (see 3.8)	Visual	02009

4.3.2.3 Case assembly, prior to potting (see Dwg. 9249361 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Connections incomplete or incorrect	Visual	03001
102.	Wire broken	Visual	03002
103.	Improperly soldered connections	Visual	03003
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.8)	Visual	03004

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.4 Case assembly (see Dwg. 9249361 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Any component missing, improperly assembled or damaged to the extent that functioning may be impaired	Visual	04001
Minor:	AQL 1.00 percent		
201.	Evidence of poor workmanship (see 3.8)	Visual	04002
202.	Potting above flush	Visual	04003

4.3.2.5 Firing device panel assembly (see Dwg. 9249360 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Any component missing, improperly assembled or damaged to extent that functioning may be impaired	Visual	05001
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.8)	Visual	05002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.6 Adapter, modified (see Dwg. 9251393 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Pin missing	Visual	06001
Minor:	AQL 1.00 percent		
201.	Length of pin from shoulder, min	Gage	06002
202.	Evidence of poor workmanship (see 3.8)	Visual	06003

4.3.2.7 Valve, ball (modified) (see Dwg. 9247446 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Modification incorrect or incomplete	Visual	07001
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.8)	Visual	07002

4.3.2.8 Brace, rear (see Dwg. 9247459 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

Minor:	AQL 2.50 percent		
201.	True position of small diameter holes	Gage	08001
202.	Location of large diameter hole	Gage	08002
203.	Diameter of large hole	Gage	08003
204.	Diameter of small hole(s)	Gage	08004
205.	Evidence of poor workmanship (see 3.8)	Visual	08005

4.3.2.9 Bracket, valve (see Dwg. 9251637, covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		
Minor:	AQL 2.50 percent		
201.	True position of small diameter holes	Gage	09001
202.	Location of large diameter hole	Gage	09002
203.	Diameter of large hole	Gage	09003
204.	Diameter of small hole(s)	Gage	09004
205.	Evidence of poor workmanship (see 3.8)	Visual	09005

4.3.2.10 Block, bearing (see Dwg. 9247466, covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Pitch diameter of thread, max	Gage	10001
102.	Minor diameter of thread, max	Gage	10002
103.	True position of threaded hole	Gage	10003
104.	True position of through hole	Gage	10004
105.	Width of bearing cutout	Gage	10005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

Minor:	AQL 1.50 percent		
201.	Diameter of through hole.....	Gage	10006
202.	Overall length.....	Gage	10007
203.	Overall height.....	Gage	10008
204.	Evidence of poor workmanship (see 3.8).....	Visual	10009

4.3.2.11 Plate, identification (see Dwg. 9251738 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		
Minor:	AQL 1.00 percent		
201.	Marking misleading or unidentifiable.....	Visual	11001
202.	Evidence of poor workmanship (3.8).....	Visual	11002

4.3.2.12 Decal, safe (see Dwg. 9247444 covering a detail of 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		
Minor:	AQL 1 00 percent		
201.	Marking misleading or unidentifiable.....	Visual	12001
202.	Evidence of poor workmanship (see 3.8).....	Visual	12002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.13 Decal, arm (see Dwg. 9247456 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major: None defined			
Minor:	AQL 1.00 percent		
201.	Marking misleading or unidentifiable	Visual	13001
202.	Evidence of poor workmanship (see 3.8)	Visual	13002

4.3.2.14 Brace, forward (see Dwg. 9247458 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major: None defined			
Minor:	AQL 4.00 percent		
201.	Diameter of large hole, max	Gage	14001
202.	Diameter of small hole(s), max	Gage	14002
203.	Location of large hole	Gage	14003
204.	True position of small holes	Gage	14004
205.	Length, min	Gage	14005
206.	Height, min	Gage	14006
207.	Width, min	Gage	14007
208.	Evidence of poor workmanship (see 3.8)	Visual	14008

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.15 Tube, piston (see Dwg. 9247451 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Outside diameter, min.	Gage	15001
102.	Wall thickness	Gage	15002
Minor:	AQL 1.50 percent		
201.	Location of hole	Gage	15003
202.	Length, min	Gage	15004
203.	Evidence of poor workmanship (see 3.8)	Visual	15005

4.3.2.16 Plug, piston tube (see Dwg. 9247460 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Diameter of center hole	Gage	16001
102.	Pitch diameter of center hole thread, max	Gage	16002
103.	Minor diameter of center hole thread, max	Gage	16003
104.	Pitch diameter of tapered hole thread	Gage	16004
105.	True position of tapered hole with center hole	Gage	16005
106.	Small diameter, min	Gage	16006
Minor:	AQL 2.50 percent		
201.	Total length, min	Gage	16007
202.	Length of shoulder, min	Gage	16008
203.	Depth of center hole thread, min	Gage	16009
204.	Large diameter, min	Gage	16010
205.	Chamfer missing	Visual	16011
206.	Evidence of poor workmanship (see 3.8)	Visual	16012

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.17 Piston tube assembly (see Dwg. 9247439 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Weld missing where required	Visual	17001
102.	Inner surface damage due to welding	Visual	17002
Minor:	AQL 1.50 percent		
201.	Parallelism of brace with tube	Gage	17003
202.	Parallelism of hole with brace	Gage	17004
203.	Protective finish missing, inadequate or on indicated areas	Visual	17005
204.	Evidence of poor workmanship (see 3.8)	Visual	17006

4.3.2.18 Piston (see Dwg. 9247453 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		
Minor:	AQL 1.50 percent		
201.	Length of piston	Gage	18001
202.	Outside diameter, max	Gage	18002
203.	Evidence of poor workmanship (see 3.8)	Visual	18003

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.19 Plug, piston (see Dwg. 9247461 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Large outside diameter.....	Gage	19001
102.	Seal groove diameter.....	Gage	19002
Minor:	AQL 1.00 percent		
201.	Total length.....	Gage	19003
202.	Evidence of poor workmanship (see 3.8).....	Visual	19004

4.3.2.20 Piston assembly (see Dwg. 9247465 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Paint missing or applied incorrectly.....	Visual	20001
102.	Any component missing or improperly assembled.....	Visual	20002
103.	Piston plug loose.....	Visual-Manual	20003
Minor:	AQL 1.00 percent		
201.	Overall length, max.....	Gage	20004
202.	Evidence of poor workmanship (see 3.8).....	Visual	20005

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.21 Bracket, interlock (see Dwg. 9247468 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Location of large diameter hole in short leg	Gage	21001
102.	True position of countersunk holes with large hole	Gage	21002
103.	True position of holes in long leg with large hole	Gage	21003
Minor:	AQL 1.00 percent		
201.	Overall length of bracket	Gage	21004
202.	Evidence of poor workmanship (see 3.8)	Visual	21005

4.3.2.22 Lever assembly (see Dwg. 9251596 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Stop block assembled improperly	Visual	22001
Minor:	None defined		

4.3.2.23 Block, stop (see Dwg. 9251593 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	True position of hole	Gage	23001

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

Minor:	AQL 2.50 percent		
201.	Diameter of hole	Gage	23002
202.	Length of shoulder from end	Gage	23003
203.	Width of shoulder	Gage	23004
204.	Radius at shoulder incorrect	Gage	23005
205.	Thickness	Gage	23006
206.	Overall length	Gage	23007
207.	Evidence of poor workmanship (see 3.8)	Visual	23008

4.3.2.24 Piston (see Dwg. 9247464 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Large outside diameter	Gage	24001
102.	Seal groove diameter	Gage	24002
103.	True position of seal groove diameter with large outside diameter	Gage	24003
104.	Outside diameter of spherical end	Gage	24004
105.	True position of spherical diameter with large outside diameter	Gage	24005
106.	Length of shoulder on spherical end	Gage	24006
107.	Outside diameter of shank on groove end	Gage	24007
108.	True position of shank with outside diameter	Gage	24008
109.	Presence of spherical radius	Visual	24009
Minor:	AQL 1.50 percent		
201.	Outside diameter of lever fork groove	Gage	24010
202.	Length from chamber to shoulder at spherical end	Gage	24011
203.	Overall length	Gage	24012
204.	Evidence of poor workmanship (see 3.8)	Visual	24013

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.25 Cap (see Dwg. 9247448 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Pitch diameter of threads, max	Gage	25001
102.	Minor diameter of threads, max	Gage	25002
103.	Diameter of hole	Gage	25003
104.	True position of hole with thread	Gage	25004
Minor:	AQL 1.50 percent		
201.	Depth of thread cavity	Gage	25005
202.	Length of cap	Gage	25006
203.	Evidence of poor workmanship (see 3.8)	Visual	25007

4.3.2.26 Pin, lever (see Dwg. 9247450 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Small outside diameter	Gage	26001
102.	True position of intermediate outside diameter with small outside diameter	Gage	26002
103.	Width of groove	Gage	26003
104.	Groove outside diameter	Gage	26004
Minor:	AQL 1.50 percent		
201.	Length of large outside diameter	Gage	26005
202.	Length of small outside diameter to groove	Gage	26006
203.	Overall length	Gage	26007
204.	Evidence of poor workmanship (see 3.8)	Visual	26008

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.27 Lever (see Dwg. 9247462 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Length from offset end to large hole	Gage	27001
102.	Offset distance	Gage	27002
103.	Offset angle	Gage	27003
104.	Diameter of large hole	Gage	27004
105.	Location of small hole	Gage	27005
106.	Diameter of small hole	Gage	27006
Minor:	AQL 2.50 percent		
201.	Overall length	Gage	27007
202.	True position of slot in offset with width	Gage	27008
203.	Length of slot in offset	Gage	27009
204.	Paint in hole	Visual	27010
205.	Evidence of poor workmanship (see 3.8)	Visual	27011

4.3.2.28 Cylinder (see Dwg. 9247463 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Large inside diameter	Gage	28001
102.	Small inside diameter	Gage	28002
103.	Seal groove diameter	Gage	28003
104.	True position of small inside diameter with large inside diameter	Gage	28004
105.	True position of seal groove diameter with large inside diameter	Gage	28005
106.	Pitch diameter of external thread, min	Gage	28006

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

107.	Major diameter of external thread, min	Gage	28007
108.	Surface finish of inside diameter incorrect	Gage	28008
109.	Pitch diameter of pipe threads	Gage	28009

Minor: AQL 2.50 percent

201.	Depth of large inside diameter	Gage	28010
202.	Pitch diameter of threaded holes on end, max	Gage	28011
203.	Minor diameter of threaded holes on end, max	Gage	28012
204.	Location of threaded holes on end	Gage	28013
205.	Location of pipe threads on outside diameter	Gage	28014
206.	Evidence of poor workmanship (see 3.8)	Gage	28015

4.3.2.29 Interlock assembly (see Dwg. 9247442 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
	101. Any component missing or improperly assembled	Visual	29001
	102. Piston binds in cylinder when lever is rotated	Visual-Manual	29002
Minor:	None defined		

4.3.2.30 Track (see Dwg. 9247457 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

Major:	AQL 0.40 percent		
101.	Inside height, min.....	Gage	30001
102.	Length of leg to shoulder, min.....	Gage	30002
Minor:	AQL 4.00 percent		
201.	Length of track relief, max...	Gage	30003
202.	Thickness of open end of leg, min.....	Gage	30004
203.	Thickness of base of leg, min.....	Gage	30005
204.	Thickness of base of track, min.....	Gage	30006
205.	Width, min.....	Gage	30007
206.	Length, min.....	Gage	30008
207.	Radius missing.....	Visual	30009
208.	Evidence of poor workmanship (see 3.8).....	Visual	30010

4.3.2.31 Snug, block (see Dwg. 9249355 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		
Minor:	AQL 2.50 percent		
201.	Width, min.....	Gage	31001
202.	Length, min.....	Gage	31002
203.	Height, min.....	Gage	31003
204.	Thickness, min.....	Gage	31004
205.	Evidence of poor workmanship (see 3.8).....	Visual	31005

4.3.2.32 Plate, jettison (see Dwg. 9247469 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Location of mounting holes "A".....	Gage	32001
102.	Keyhole slot missing on hole(s) "A".....	Visual	32002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

Minor:	AQL 4.00 percent		
201.	Location of mounting holes "B"	Gage	32003
202.	Location of mounting holes "C"	Gage	32004
203.	True position of mounting holes "C"	Gage	32005
204.	Location of mounting holes "D"	Gage	32006
205.	Diameter of mounting holes "A"	Gage	32007
206.	Diameter of mounting holes "B"	Gage	32008
207.	Diameter of mounting holes "C"	Gage	32009
208.	Diameter of mounting holes "D"	Gage	32010
209.	Length from end to side max (4 places)	Gage	32011
210.	Length, min	Gage	32012
211.	Width, min	Gage	32013
212.	Hole(s) missing	Gage	32014
213.	Evidence of poor workmanship (see 3.8)	Visual	32015

4.3.2.33 Track and plate weldment (see Dwg. 9247443 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Distance across track shoulders	Gage	33001
102.	True position of track	Gage	33002
103.	Any component missing or improperly assembled	Visual	33003
Minor:	AQL 2.50 percent		
201.	Location of tubes	Gage	33004
202.	Diameter of tube hole(s)	Gage	33005
203.	True position of mounting holes "A"	Gage	33006
204.	Diameter of tube hole(s)	Gage	33007
205.	Location of snug block	Gage	33008
206.	Evidence of poor workmanship (see 3.8)	Visual	33009

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.34 Jettison assembly, prior to joining pipe threads (see Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Sealing compound missing.....	Visual	34001
Minor:	None defined		

4.3.2.35 Jettison assembly (see Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:			
1.	Valve in armed position.....	Visual	35001
2.	Decals missing or incorrectly applied.....	Visual	35002
Major:	AQL 0.40 percent		
101.	Distance between interlocks.....	Gage	35003
102.	Any component missing, improperly assembled or damaged to extent that functioning may be impaired.....	Visual	35004
Minor:	AQL 1.50 percent		
201.	Protective finish missing or incomplete.....	Visual	35005
202.	Paint on surface where not required.....	Visual	35006
203.	Tape missing or improperly applied.....	Visual	35007
204.	Evidence of poor workmanship (see 3.8).....	Visual	35008

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.36 Case, modified (see Dwg. 9255552 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major: None defined			
Minor:	AQL 2.50 percent		
201.	True position of small holes	Gage	36001
202.	Diameter of small hole(s)	Gage	36002
203.	Location of large hole	Gage	36003
204.	Diameter of large hole	Gage	36004
205.	Location of intermediate hole	Gage	36005
206.	Diameter of intermediate hole	Gage	36006
207.	Evidence of poor workmanship (see 3.8)	Visual	36007

4.3.2.37 Cover, modified (see Dwg. 9255553 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major: None defined			
Minor:	AQL 1.50 percent		
201.	Location of hole	Gage	37001
202.	Diameter of hole	Gage	37002
203.	Height of cover	Gage	37003
204.	Evidence of poor workmanship (see 3.8)	Visual	37004

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.38 Bulb and vial assembly (see Dwg. 9212139 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Any component missing, damaged or improperly assembled	Visual	38001
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.8)	Visual	38002

4.3.2.39 Case and connector assembly (see Dwg. 9255551 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Any component missing, damaged or improperly assembled	Visual	39001
102.	Soldering improper or incomplete	Visual	39002
103.	Wiring incorrect	Visual	39003
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.8)	Visual	39004

4.3.2.40 Plate, identification (see Dwg. 9255554 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	None defined		
Minor:	AQL 0.65 percent		
201.	Marking misleading or unidentifiable	Visual	40001

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.41 Test set (see Dwg. 9255382 covering a detail of Dwg. 9251396).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Any component missing or improperly assembled	Visual	41001
102.	Potting below flush with cover	Visual	41002
103.	Soldering improper	Visual	41003
Minor:	AQL 0.65 percent		
201.	Evidence of poor workmanship (see 3.8)	Visual	41004

4.3.2.42 Carton, packing, prior to sealing (see Dwgs. 9242543 and 9255505).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Incorrect number of components or envelopes (as applicable)	Visual	42001
Minor:	AQL 0.65 percent		
201.	Marking misleading or unidentifiable (as applicable)	Visual	42002

4.3.2.43 Carton, packing (see Dwgs. 9242543 and 9255505).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Carton flap not secured	Visual	43001
102.	Carton damaged to extent that the contents are exposed or likely to be exposed during subsequent handling	Visual	43002

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

Minor:	AQL 1.00 percent		
201.	Contents move when shaken	Manual	43003
202.	Marking misleading or unidentifiable	Visual	43004

4.3.2.44 Bag, sealed (see Dwgs. 9242543 and 9255505).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Seal incomplete or incorrectly located	Visual	44001
102.	Bag cut, torn or punctured	Visual	44002
Minor:	AQL 0.65 percent		
201.	Marking misleading or unidentifiable	Visual	44003

4.3.2.45 Box, packing (see Dwgs. 9243965 and 9255504).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.65 percent		
101.	Top improperly assembled	Visual-Manual	45001
102.	Board broken or split	Visual-Manual	45002
103.	Strapping missing, broken or loose	Visual-Manual	45003
104.	Box damaged to the extent that contents are exposed or likely to become exposed in subsequent handling	Visual	45004
Minor:	AQL 1.50 percent		
201.	Strapping improperly assembled	Visual-Manual	45005
202.	Contents loose when shaken	Manual	45006
203.	Marking misleading or unidentifiable	Visual	45007

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.2.46 Crate, wirebound, packing (see Dwg. 9241092).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 1.00 percent		
101.	Box(s) missing, improperly positioned or improperly secured	Visual-Manual	46001
102.	Dispenser improperly packed	Visual	46002
103.	Jettison plate improperly positioned	Visual	46003
104.	Components improperly secured (where required)	Visual-Manual	46004
105.	Cushion pads missing	Visual	46005
106.	Board broken or loose	Visual	46006
107.	Strapping missing, broken or loose	Visual-Manual	46007
108.	Loop(s) improperly closed	Visual	46008
Minor:	AQL 1.50 percent		
201.	Strapping mislocated	Visual-Manual	46009
202.	Contents loose when shaken	Manual	46010
203.	Marking misleading, missing or unidentifiable	Visual	46011
204.	Seal missing or mislocated	Visual	46012

4.3.3 Testing

4.3.3.1 Leakage of safety valve (see 3.3.1) - Major defect - Code No. 07003.-This test shall be performed 100 percent in accordance with the procedure specified in 4.4.1 using test equipment specified in 4.3.4. Any valve that fails to comply with the specified requirement shall be classed defective and removed from the lot.

4.3.3.2 Leakage of interlock assembly (see 3.3.2) - Major defect - Code No. 29003.-This test shall be performed 100 percent in accordance with the procedure specified in 4.4.2 using test equipment specified in 4.3.4. Any assembly that fails to comply with the specified requirement shall be classed defective and removed from the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.3.3 Leakage of pressure system (see 3.3.3) - Major defect - Code No. 35009.-This test shall be performed 100 percent in accordance with the procedure specified in 4.4.3 using test equipment specified in 4.3.4. Any jettison plate exhibiting leakage shall be classed defective and removed from the lot.

4.3.3.4 Soundness of welds of rails to plate, plug in piston cylinder and piston cylinder to support angle (see 3.4) - Major defect - Code No. 35010.-Each jettison plate assembly shall be subjected to inspection to determine the soundness of these welds using the procedure specified in 4.4.4. Test equipment shall be as specified in 4.3.4. Any assembly that fails to comply with the specified requirement shall be classed defective and removed from the lot.

4.3.3.5 Functioning (see 3.5) - Major defect - Code No. 35011.-This test shall be performed 100 percent in accordance with the procedure specified in 4.4.5 using test equipment specified in 4.3.4. Any jettison plate assembly that fails to comply with the specified requirement shall be classed defective and removed from the lot.

4.3.3.6 Continuity and short circuit test of case assembly (see Dwg. 9249361) - Code No. 04004, firing device panel assembly (see Dwg. 9249360) - Code No. 05003 and cable assembly (see Dwg. 9251397) - Code No. 47001 - Major defects.-These tests shall be performed 100 percent in accordance with the procedure specified in 4.4.6 using test equipment specified in 4.3.4. Any firing device panel assembly, case assembly or cable assembly that fails to comply with the specified requirement shall be classed defective and removed from the lot.

4.3.3.7 Resistance of resistor (see Dwg. 925556) - Major defect - Code No. 48001.-Fifty (50) resistors shall be selected from each lot for this test. The lot shall be rejected if any resistor fails to comply with requirement. The test shall be performed as specified in 4.4.7 using test equipment in accordance with 4.3.4.

4.3.3.8 Resistance of bulb (see Dwg. 9212139) - Major defect - Code No. 38003.-One hundred and twenty five (125) bulbs shall be selected from each lot for this test. The lot shall be rejected if two or more bulbs fail to comply with the requirement. The test shall be performed as specified in 4.4.8 using test equipment in accordance with 4.3.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.3.3.9 Five-foot drop (test set) (see 3.6) - Major defect - Code No. 41005.-Fifty (50) test sets shall be selected from each lot for this test. The lot shall be rejected if any test set fails to comply with the requirement. The test shall be performed as specified in 4.4.9 using test equipment in accordance with 4.3.4.

4.3.3.10 Functioning of test set (see 3.7) - Major defect - Code No. 41006.-This test shall be performed 100 percent. Any test set which fails to comply with the specified requirement shall be classed defective and removed from the lot. The test shall be performed as specified in 4.4.10, using test equipment in accordance with 4.3.4.

4.3.4 Inspection equipment.-Equipment Tabulation Number ET 9251396 identifies the inspection equipment required to perform the examinations and tests prescribed in this section. The contractor shall design inspection equipment in accordance with the instructions in paragraph 6.3.

4.3.4.1 Government rights to documentation.-Inspection equipment drawings and lists provided and revised in accordance with the requirements of the ET may be used by DOD activities for design, procurement, manufacture, testing, evaluation, production and receiving inspection, overhaul, shipping, storage, identification of stock, ordering and storage of replacement parts, inspection of items at overhaul, general maintenance of equipment, construction, survey and whenever inspection equipment drawings are needed.

4.4 Test methods and procedures.

4.4.1 Leakage of safety valve.-The safety valve shall be assembled to the test equipment specified and the required input pressure shall be applied. Observation shall be made for compliance with the requirement specified.

4.4.2 Leakage of interlock assembly.-The interlock assembly shall be assembled to the test equipment specified and the required input pressure shall be applied. Observation shall be made for compliance with the requirement specified.

4.4.3 Leakage of pressure system.-The jettison plate shall be assembled to the test equipment specified and the required input pressure shall be applied. Observation shall be made for compliance with the requirement specified.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

4.4.4 Soundness of welds.-The specified welds shall be examined utilizing a dye penetrant method of inspection. Observation shall be made for compliance with the requirement specified.

4.4.5 Functioning.-The jettison plate assembly shall be assembled to the test stand specified. A mock dispenser weighing 835 pounds shall be used for this test. With the safety valve in the safe position and the interlocks open, the test dispenser shall be placed in position on the jettison plate assembly. The interlocks shall be closed. The jettison plate assembly shall be functioned and the velocity of the test dispenser shall be photographically measured over last one (1) foot of travel to determine compliance with the requirement specified.

4.4.6 Continuity and short circuit test (case assembly, firing device panel assembly, cable assembly).-The applicable assembly shall be assembled to the test equipment specified. The test shall be conducted in accordance with the instructions specified. Observation shall be made for compliance with the requirement specified.

4.4.7 Resistance of resistor.-The resistance of the resistor shall be measured using an ohmeter. Observation shall be made for compliance with the requirement specified.

4.4.8 Resistance of bulb.-The resistance of the bulb shall be measured using an ohmeter. Observation shall be made for compliance with the requirement specified.

4.4.9 Five-foot drop (test set only).-The test set shall be dropped from a height of five (5) feet plus or minus 3 inches. The test set shall be examined for any evidence of separation of parts. The test set shall then be functioned as specified in 4.4.10.

4.4.10 Functioning of test set.-The test set shall be functioned using a pulse generator. Observation shall be made for compliance with the requirement specified.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

5.1.1 Level A.-The tiedown hardware, firing device panel assembly, cable assembly and XM19 test set assembly shall be preserved and packaged in accordance with Dwgs. 9242543 and 9255505.

5.2 Packing

5.2.1 Level A

5.2.1.1 Cartons.-The cartons shall be packed in accordance with Dwgs. 9243965 and 9255504.

5.2.1.2 Jettison plate and boxes.-The jettison plate and boxes shall be packed in accordance with Dwg. 9241092.

5.3 Marking

5.3.1 Cartons.-Packing cartons shall be marked in accordance with Dwgs. 9242543 and 9255505.

5.3.2 Boxes.-Packing boxes shall be marked in accordance with Dwgs. 9243965 and 9255504.

5.3.3 Crate.-The crate shall be marked in accordance with Dwg. 9241092.

6. NOTES

6.1 Ordering data.-Procurement documents shall specify the following:

a. Title, number and date of this specification.
b. Data cards.-Data cards shall be prepared for each lot in accordance with the information specified in MIL-STD-1167.
c. Provisions for submission of first article samples.

6.2 Inspection code numbers.-The five digit code numbers assigned to the inspections herein are to facilitate future data collection and analysis by the Government. These code numbers are also used to correlate the characteristics cited on Equipment Lists with the inspections listed in this specification. In addition, they should be cited as references on drawings of equipment designs submitted by the contractor to the Government for approval (see 6.3.5).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

6.3 Inspection equipment.-The contractor shall design inspection equipment as required by the inspection Equipment Lists (EL) referenced on the applicable ET in accordance with the instructions of paragraphs 6.3.1 through 6.3.5.

6.3.1 Inspection equipment lists (EL).-Inspection equipment lists indicate the availability of inspection equipment designs by showing in the "number" column of the list of inspection equipment (Form SMUPA 1010) the numbers of drawings or Federal Stock numbers of existing equipment designs, or codes as indicated in paragraph 6.3.2. Design action required of the contractor is described in paragraphs 6.3.3 and 6.3.4. The contractor will be required to prepare detailed drawings in accordance with 6.3.4 for all the equipment coded as "Contractor Design" in the number column. These contractor designs must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.5.

6.3.2 Inspection equipment list codes.-The inspection equipment as defined in 6.3.3 and 6.3.4 will be designated in the EL by the following codes:

CD - Contractor design on controlled contractor format and/or commercial equipment
MU - Army design, mandatory for use

6.3.3 Army designs.-Army designs are reflected on detailed drawings which completely depict all the information necessary for the fabrication of the item of inspection equipment. The contractor need provide no design when an Army design is listed for an item of inspection equipment. Army designs fall into two basic classifications; mandatory (designated "MU") and non-mandatory (indicated by drawing or Federal Stock Number). When an inspection equipment list references mandatory Army designs, the contractor shall comply with, and use these designs accordingly. The contractor may, however, in connection with non-mandatory designs, design alternate inspection equipment or use comparable commercial equipment to facilitate his operations. Such contractor prepared designs or commercial equipment selections must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.5.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.

6.3.4 Contractor designs.-Contractor designs are designs of inspection equipment for which the Government has assigned design responsibility to the contractor. Contractor designs shall be supported by detailed drawings which depict all information necessary to completely fabricate, calibrate and operate an item of inspection equipment. This requires that the necessary views, dimensions, materials, finish, notes, operating and calibration instructions be properly depicted in accordance with approved practices to the extent that further calculation or clarification will not be required. Unless otherwise specified, contractor designs may be developed on the format the contractor normally employs in his equipment design procedure provided such format reflects the detail and information specified above, subject to the following controls: All submitted contractor designs shall conform to MIL-D-1000, Category A, Form 2. Legibility and reproducibility shall permit conventional making of clearly understandable, high contrast reproductions. Contractors shall submit three copies of final designs as a flat set. Designs shall be submitted for approval as specified in 6.3.5.

6.3.5 Submission of contractor designs.-All submitted designs shall contain a reference to the applicable five digit Code Number contained in Section 4 of this specification and the appropriate component or assembly drawing number and revision letter to which the specific design applies. Unless otherwise specified on the EL, all designs of equipment for inspection of defects classified as critical and major shall be submitted for approval to the Commanding Officer, Picatinny Arsenal, ATTN: SMUPA-ND15. All other designs of inspection equipment shall be approved by the inspection element of the agency administering the contract; submission shall be as directed by the contracting officer. Partial submission of inspection equipment designs is permissible and encouraged. However, the Arsenal completion date for design review will be based on the date of the final submission of designs. Picatinny Arsenal design review will be accomplished normally within one month after receipt.

Custodian:
Army-MU

Preparing Activity:
Army-MU

Project Number: 1370-A-282

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:27Z
Check the source to verify that this is the current version before use.