BY ORDER OF THE COMMANDER
WARNER ROBINS AIR LOGISTICS COMPLEX

WARNER ROBINS AIR LOGISTICS COMPLEX INSTRUCTION 91-202

8 OCTOBER 2026

Safety

SLINGS AND BELOW THE HOOK LIFTING DEVICES

COMPLIANCE WITH THIS PUBLICATION IS MANDATORY

ACCESSIBILITY: Publications and forms are available for downloading or ordering on the e-publishing web site at www.e-Publishing.af.mil

RELEASABILITY: There are no releasability restrictions on this publication

---

OPR: 402MXSS/MXDXA

Certified by: 402MXSG/CL (William Broach)

Supersedes: WR-ALCI91-202, 13 August 2024

Pages: 9

This instruction implements Department of the Air Force Manual (DAFMAN) 91-203, *Department of the Air Force Occupational Safety, Fire, and Health Standards*, 29 Code of Federal Regulations (CFR) 1910.184, *Slings*, and American Society of Mechanical Engineers (ASME) B30 standards. It applies to all Warner Robins Air Logistics (WR-ALC) personnel. This publication addresses maintenance, periodic inspection and tagging of slings and below the hook lifting devices. A sling is defined as an assembly which connects a load to material handling equipment and/or a holding device. Improper use of slings can cause injury, death, and property damage. Mishaps often occur when loads are dropped or slip because the sling or its attachments break. Most sling mishaps can be attributed to inadequate design, improper selection, poor inspection, failure to make sure loads are properly attached and secured, or improper storage and care. This publication establishes policies and procedures to implement the WR-ALC Sling Program and to mitigate these factors. In addition, this publication assigns responsibilities to individuals and organizations (users) to implement. Squadron commanders are ultimately responsible for ensuring compliance where organizations or users are referenced. Refer recommended changes and questions about this publication to the office of primary responsibility (OPR) using the Department of the Air Force (DAF) Form 847, *Recommendation for Change of Product*. This instruction may be supplemented at any level, but all direct supplements must be routed to the OPR of this instruction for coordination prior to certification and approval. Requests for waivers must come through the chain of command from the commander or civilian director of the maintenance group or staff office seeking relief from compliance. Ensure that all records created because of processes prescribed in this instruction are maintained in accordance with

(IAW) Air Force Instruction (AFI) 33-322, *Records Management and Information Governance Program*, and disposed of IAW the Air Force Records Information Management System Records Disposition Schedule. See **Attachment 1** for a glossary of references and supporting information.

SUMMARY OF CHANGES

This publication has been revised and must be completely reviewed. The revision includes updates from DAFMAN 91-203 that affect sling load testing requirements, removes duplicate statements, and updates verbiage, references, forms, and abbreviations.

1. Responsibilities.

1.1. The 402d Maintenance Support Group (402 MXSG) director appoints, in writing, a WR-ALC (Complex) Sling Program Manager (SLPM) to manage the WR-ALC Sling Program.

1.2. WR-ALC group commanders/directors will appoint, in writing to Complex SLPM (402 MXSG), a primary and alternate sling monitor.

1.3. Complex SLPM (402 MXSG):

1.3.1. Assigns sling identification (ID) numbers and inputs information into FEM.

1.3.2. Builds asset record for all new items submitted by owning organization into FEM.

1.3.3. Inputs new sling information into FEM from a WR-ALC Form 38, *FEM Database Action Form & Certification of Proof Test,* provided by the owning organization.

1.3.4. Attaches proof test certification from manufacturer if provided by the owning organization or a completed WR-ALC Form 38 with proof testing documentation for slings in FEM as needed.

1.3.5. Attaches manufacturer's sling certification in FEM when provided by the owning organization.

1.3.6. Completes any sling status changes (hold, decommission, etc.) in FEM with a completed WR-ALC Form 38 provided by the owning organization.

1.3.7. Prepares preventative maintenance instructions for slings IAW applicable manufacturer's instructions, drawings, ASME B30 standards, technical orders (TO) and DAFMAN 91-203.

1.3.8. Reports any discrepancies to the owning organization.

1.3.9. Assists owning organizations sling monitors with questions and discrepancies concerning slings and facilities and equipment maintenance (FEM).

1.3.10. Files most recent appointment letters received from the owning organizations.

1.4. Inspection and Testing Organization: 402 Maintenance Support Group/Maintenance Support Squadron Services A (Maintenance) (402 MXSG/MXDVA):

1.4.1. All 402 MXSG/MXDVA mechanics performing inspections and testing on slings shall first successfully complete the 78 Air Base Wing (78 ABW) MRXMAS0000900SU Sling Training Course.

1.4.2. Reviews drawings, tech data, and verify sling assemblies are complete.

1.4.3. Reviews statement of work provided by the owning organization to verify it is accurate and rejects incomplete statements of work.

1.4.4. Completes sling inventory transfer sheet with owning organization at drop off.

1.4.5. Performs proof/load tests (if required) and then performs periodic inspections on slings and attachments IAW all applicable manufacturer's instructions, TOs, drawings, DAFMAN 91-203, and ASME B30 standards.

1.4.6. Determines if slings require non-destructive inspection (NDI), depaint and/or paint IAW all applicable manufacturer's instructions, TOs, drawings, DAFMAN 91-203, and ASME B30 standards.

1.4.7. Shall disassemble and reassemble slings requiring disassembly for testing.

1.4.8. Routes slings to 571st Commodities Maintenance Group (571 CMXG) for required blasting, NDI, and painting.

1.4.9. Updates next due date tags when inspection is complete.

1.4.10. Documents 402 MXSG's work performed in FEM work order log before closing the work order.

1.4.11. Attaches completed Lean Depot Management System (LDMS) Air Force Sustainment Center (AFSC) Form 959, *Work Control Document* (WCD) from 571 CMXG to the sling work order in FEM.

1.4.12. Contact customers to pick up slings when preventative maintenance work order is complete.

1.4.13. Will perform proof/load tests (if required) at flight line pull station if slings are too large for pull testing at the 402 MXSG Bldg. 321 pull station.

1.4.14. Shall destroy and discard all slings that have conditions present (see 29 CFR 1910.184 and ASME B30 standards for criteria) that require removal from service that cannot be repaired IAW 29 CFR 1910.184 and ASME B30 standards once received from the owning organization.

1.4.15. Prior to being placed into service, proof tests all locally manufactured slings. A record of the most recent proof test will be retained in FEM.

1.4.16. Ensure all slings are tagged IAW ASME B30 standards and include the asset ID (SL0#), a brief description, working load limit, owning Resource Control Center (RCC) (MNP#), drawing number if available and the serial number if available.

1.5. Owning Organization:

1.5.1. Tracks sling work schedule in FEM.

1.5.2. Delivers slings to drop off/pick up point in 402 MXSG Bldg. 321 no earlier than 5 days before due date, Monday through Friday between 7:00 a.m. and 10:00 a.m.

1.5.3. Will deliver slings that are too large to be pull tested at 402 MXSG Bldg. 321 pull station to the flight line pull station after coordinating with 402 MXSG.

1.5.4. Provides all applicable TOs, drawings, and a completed AFSC Form 137, *Routed Order (PROJ DIR)*, with statement of work along with slings for periodic inspection and proof/load testing (if required).

1.5.5. Completes statement of work on AFSC Form 137 in box 30. The AFSC Form 137 shall include the asset number, part number (if available), nomenclature, stock number (if available), serial number (if available), owning RCC (MNP#), point of contact (POC) with phone number and the FEM work order number.

1.5.6. Shall pick up the completed sling from drop off/pick up point from 402 MXSG Bldg. 321 within 3 business days of being notified.

1.5.7. Shall submit a WR-ALC Form 38 requesting any sling to be decommissioned that have conditions present (see 29 CFR 1910.184 and AMSE B30 standards for criteria) that require removal from service that cannot be repaired IAW 29 CFR 1910.184 and ASME B30 standards and deliver the sling to 402 MXSG to be destroyed and discarded.

1.5.8. Provides past due reports to group commanders/directors when requested.

1.5.9. Reports discrepancies to SLPM for corrections.

1.5.10. Coordinates the acquisition process for purchasing and outsourcing new slings (locally manufactured and/or commercially purchased).

1.5.11. Maintains FEM access.

1.5.12. Maintains sling inventory IAW AFI 23-101 *Materials Management Policy _Air Force Materiel Command Supplement*, (AFMCSUP).

1.5.13. Requests out-of-cycle inspections, and proof/load testing (if required) through the Complex SLPM (402 MXSG).

1.5.14. Provides completed WR-ALC Form 38 to the Complex SLPM for new items to be entered into FEM.

1.5.15. Requests to Complex SLPM any sling status changes (hold, decommission, etc.) in FEM with a completed WR-ALC Form 38.

1.5.16. If provided by the sling manufacturer, it will provide manufacturer's sling certifications to the SLPM for documentation.

1.5.17. Maintains appointment letters from group commander/director. Provides Complex SLPM with updated sling appointment letters when there are updates.

1.5.18. Performs visual inspection on slings from the production support center (PSC), tool crib, or shop storage location prior to signing out IAW DAFMAN 91-203, Chapter 12, manufacturer's instructions, technical data, and ASME B30 standards.

1.5.19. Remove all dirt, grease, or oil from all web slings prior to returning to the PSC, tool crib, or shop storage location. Use only soap or water-soluble detergent to clean web slings.

1.5.20. Lubricates metal slings and restraining devices every 30 days or prior to each use. **NOTE:** IAW TO 35D6-1-106, *Aircraft and Engine Slings (General) and Restraining Devices*, Chapter 4, Monthly Lubrication, including type of lubricant.

1.6. User:

1.6.1. Prior-to-use inspections.

1.6.1.1. The user must perform prior to use inspection IAW ASME B30 standard series and applicable TOs and if a defect is discovered, the user will record the defect in Part V of the Air Force Technical Order (AFTO) Form 244, *Industrial/Support Equipment Record*, IAW TO 00-20-1, *Aerospace Equipment Maintenance Inspection, Documentation, Policies, and Procedures*.

1.6.1.2. Uses slings and below the hook lifting devices only for the purpose they are intended, and in a manner consistent with DAFMAN 91-203, ASME B30 standards and applicable TOs.

1.6.1.3. Return damaged slings to PSCs. PSCs will initiate repair or decommission process.

1.7. 571st Commodities Maintenance Squadron (571 CMMXS):

1.7.1. Planner reviews slings/parts and updates sling inventory transfer sheet.

1.7.2. Reviews AFSC Form 137 with statement of work, including the asset number (SL0), part number (if applicable), the nomenclature, national stock number (NSN) (if available), serial number (if available), owning RCC (MNP#), POC with phone number, and the FEM work order number.

1.7.3. Reviews drawings, TOs, and verify sling assemblies are complete.

1.7.4. Reviews statement of work provided by 402 MXSG to verify accuracy and rejects incomplete statements of work.

1.7.5. Creates LDMS WCD AFSC Form 959.

1.7.6. Remove paint from slings/parts if required.

1.7.7. Performs NDI on slings/parts if required.

1.7.8. Paints slings/parts as required IAW drawings and/or TOs.

1.7.9. Scheduler updates the sling inventory transfer sheet.

1.7.10. Routes slings with sling inventory transfer sheet to 402 MXSG.

1.7.11. Email LDMS WCD AFSC Form 959 to 402 MXSG/MXVDA to attach to the FEM work order.

1.7.12. Shall perform all required blasting, depainting, NDI, and painting.

1.8. 573d CMXG:

1.8.1. Performs weld repairs on slings as required per LDMS WCD AFSC Form 959.

1.8.2. Routes repaired slings backed to 571 CMXG.

2. Acquisition (Owning Organization):

2.1. Commercially procured material handling and lifting equipment or parts shall comply with design manufacturing requirements and specifications in Occupational Safety and Health Administration (OSHA) standards and as applicable, ASME requirements and specifications.

2.2. Slings procured for DAF use shall comply with design and manufacturing requirements in 29 CFR 1910.184, *Slings*, and ASME B30 standards, *Slings*. Locally manufactured slings that do not meet the engineering requirements of ASME B30 standards are prohibited and shall be disassembled and removed from service. **Note:** Design and manufacturing requirements are specified in OSHA's Tables and Figures: Guidance on Safe Sling Use: **https://www.osha.gov/dsg/guidance/slings/tables-** figures.html IAW DAFMAN 91-203.

2.3. The purchaser will obtain a certified document of proof test performed by the manufacturer if available or an initial proof test will need to be accomplished by qualified personnel before the asset can be put into service.

2.4. Locally manufactured slings, the owning group engineering authority will specify on the blueprint the maximum working load capacity and how to perform the load test. Also, they will need to specify on the blueprint that the manufacturer will etch or stamp this information permanently in a conspicuous place on the sling. Slings shall be marked or identified with a durable and legible tag or stencil.

2.5. Local manufacturer: Whole slings or components may be manufactured locally. Component parts manufactured locally will be made IAW engineer's or manufacturer's drawing for that part. 572d Commodities Maintenance Group (572 CMXG) accomplishes local manufacture for metal slings, and/or synthetic web slings and their component parts. Locally manufactured slings will comply with DAFMAN 91- 203, ASME B30 standard and 29 CFR 1910.184.

2.6. For locally manufactured slings, the owning organizations planning and engineering will work with local contractors or 572 CMXG.

2.7. Locally manufactured slings will be identified by the local manufacturer IAW ASME B30.9.

DAVID S. MILLER
Brigadier General
Commander

Attachment 1

GLOSSARY OF REFERENCES AND SUPPORTING INFORMATION

References

29 CFR 1910.184, *Slings*

AFI 23-101_AFMCSUP, *Materiel Management Policy*, 10 December 2021

AFI 33-322, *Records Management and Information Governance Program*, 23 March 2020

DAFMAN 91-203, *Department of the Air Force Occupational Safety, Fire, and Health Standards*, 24 February 2026

TO 00-20-1, *Aerospace Equipment Maintenance Inspection, Documentation, Policies, and Procedures*, 23 February 2026

TO 35D6-1-106, *Aircraft and Engine Slings (General) and Restraining Devices,* 29 May 2025

ASME B30.9, *Slings,* 26 September 2025

Prescribed Form

WR-ALC Form 38, *FEM Database Action Form & Certification of Proof-Test*

Adopted Forms

AFSC Form 137, *Routed Order (Proj Dir)*

AFSC Form 959, *Work Control Document*

AFTO Form 244, *Industrial/Support Equipment Record*

DAF Form 847, *Recommendation for Change of Product*

Abbreviations and Acronyms

AFI—Air Force Instruction

AFMC—Air Force Materiel Command

AFSC—Air Force Sustainment Center

AFTO—Air Force Technical Order

ASME—American Society of Mechanical Engineers

CFR—Code of Federal Regulations

CMXG—Commodities Maintenance Group

DAF—Department of the Air Force

DAFMAN—Department of the Air Force Manual

FEM—Facilities and Equipment Maintenance

IAW—In Accordance With

ID—Identification

LDMS—Lean Depot Management System

MXSG—Maintenance Support Group

NDI—Nondestructive Inspection

OPR—Office of Primary Responsibility

PSC—Production Support Center

SLPM—Sling Program Manager

TO—Technical Order

WCD—Work Control Document

WR-ALC—Warner Robins Air Logistics Complex

Terms

Chain—A series of links pivotally joined together for conveying or transmitting motion or power. General classes of chain are detachable, pintle, combination, roller, rivetless, coil, inverted tooth, and bar link chains.

Prior—to-Use Inspection—A visual inspection of equipment performed once each day prior to initial use. If the equipment is not used daily, this inspection is performed prior to each use and is not required on those days when the equipment is not used. The use of additional items such as ladders, personnel lifts, or special tools or disassembly of lifting equipment is not required by this standard for this inspection. **Note:** The daily or prior-to-use inspection is not an operational test.

Load Test—Also called rated-load test. A test of the rated capacity (working load limit), as determined by type of equipment and designated by the manufacturer and DAFMAN 91-203. See individual chapters for applicable equipment-specific test procedures.

Load (Working)—The external load, in pounds, applied to the crane, including the weight of load-attaching equipment such as load blocks, shackles, slings, and ropes.

Must—Indicates a mandatory requirement.

Prior—to-Use Inspection—A visual inspection of equipment performed once each day prior to initial use. If the equipment is not used on a daily basis, this inspection is performed prior to each use and is not required on those days the equipment is not used. The use of additional items such as ladders, personnel lifts, or special tools or disassembly of lifting equipment is not required by this standard for this inspection. **Note:** The daily or prior-to-use inspection is not an operational test.

Proof Test—A nondestructive tension test performed by the manufacturer or qualified person to verify construction and workmanship of a lifting device. See individual chapters for applicable equipment-specific test procedures.

Shall—Also, used to indicate a mandatory requirement.

Sling—An assembly which connects a load to the material handling equipment and/or holding device.

Will—Is also used to indicate a mandatory requirement; in addition is used to express a declaration of intent, probability, or determination.