PREVENT FOREIGN OBJECT DAMAGE
PREVENT DROPPED OBJECTS

REPORT TO:

100 ARW FOD/DOP PROGRAM MONITOR Primary	**TSgt Drake Morvant** X-6885 Bldg. 809 Rm. 2.33
100 ARW FOD/DOP PROGRAM MONITOR Alternate	**TSgt Tristan Williams** X-6889 Bldg. 809 Rm. 2.33

WAYS YOU CAN PREVENT FOD & DROPPED OBJECTS:

1. BY EXERCISING **"CAUTION"** NEAR OPERATING JET ENGINES.
2. BY USING GOOD HOUSEKEEPING I.E. PICKING UP TOOLS AND CLEANING AS YOU GO.
3. BY INSPECTING VEHICLES AND TIRES PRIOR TO USE ON THE FLIGHTLINE.
4. BY ENSURING ALL FASTNERS ARE SECURE.
5. BY REQUESTING VACUUM OR MECHANICAL SWEEPERS FOR NOTICEABLE DEBRIS ON AIRFIELD THROUGH WING MAINTENANCE OPERATIONS CENTER (MOC) OR BASE OPERATIONS.
6. BY ENSURING ALL DOORS AND PANELS ARE SECURE PRIOR TO AIRCRAFT FLIGHT.

RAFMILDENHALLVA21-101, Dated 12 SEPTEMBER 2024
Supersedes RAFMILDENHALLVA 21-101, Dated 22 February 2024
Prescribed by DAFI 21-101

OPR: 100 MXG/MXQ
Releasability: Unrestricted