PG&E now requires all line-side taps to go through variance testing before the engineering review of the interconnection process. This requires us to submit the following photos:

ures, If you are performing a line side tap the following pictures are required. Please
ch pictures clearly showing;
Customer's side open section
Picture showing routing identified by arrows/circles
Picture showing connection points identified by arrows/circles
Picture showing the entire meter panel