

RALINK TECHNOLOGY, CORP.

Ralink APSoC SDK Important Change Log

Copyright © 2011 Ralink Technology, Corp.

All Rights Reserved.

This document is property of Ralink Technology Corporation Transmittal, receipt, or possession of this document does not express, license, or imply any rights to use, sell, design, or manufacture from this information or the software documented herein. No reproduction, publication, or disclosure of this information, in whole or in part, shall be allowed, unless the prior written consent of Ralink Technology Corporation is obtained.

Note: THIS DOCUMENT CONTAINS SENSITIVE INFORMATION AND HAS RESTRICTED DISTRIBUTION.

intingliand syllaging of the control of the control



Proprietary Notice and Liability Disclaimer

The confidential Information, technology or any Intellectual Property embodied therein, including without limitation, specifications, product features, data, source code, object code, computer programs, drawings, schematics, know-how, notes, models, reports, contracts, schedules and samples, constitute the Proprietary Information of Ralink (hereinafter "Proprietary Information")

All the Proprietary Information is provided "AS IS". No Warranty of any kind, whether express or implied, is given hereunder with regards to any Proprietary Information or the use, performance or function thereof. Ralink hereby disclaims any warranties, including but not limited warranties of non-infringement, merchantability, completeness, accuracy, fitness for any particular purpose, functionality and any warranty related to course of performance or dealing of Proprietary Information. In no event shall Ralink be liable for any special, indirect or consequential damages associated with or arising from use of the Proprietary Information in any way, including any loss of use, data or profits.

Ralink retains all right, title or interest in any Proprietary Information or any Intellectual Property embodied therein. The Proprietary Information shall not in whole or in part be reversed, decompiled or disassembled, nor reproduced or sublicensed or disclosed to any third party without Ralink's prior written consent.

Ralink reserves the right, at its own discretion, to update or revise the Proprietary Information from time to time, of which Ralink is not obligated to inform or send notice. Please check back if you have any question. Information or items marked as "not yet supported" shall not be relied on, nor taken as any warranty or permission of use.

Ralink Technology Corporation (Taiwan)

5F, No.5, Tai-Yuen 1st Street,

ChuPei City

HsinChu Hsien 302, Taiwan, ROC

Tel +886-3-560-0868

Fax +886-3-560-0818

Sales Taiwan: Sales@ralinktech.com.tw

Technical Support Taiwan: FAE@ralinktech.com.tw

http://www.ralinktech.com/

intingiland syntaktion



Content

1. Introduction...... 4





Ralink APSoC SDK Important Change Log

1. Introduction

Due to increase SDK's quality, we fix bugs and improve functions constantly. The following shows you updated history of this version:

Ralink AP SDK - History

Version 3.6.0.0

==========

New functions:

- [IPv6] Support IPv6 Ready logo
- [IPv6] Support IPv6 MLD multicast proxy/snooping (ECMH)
- [Raeth] Support skb recycling mechanism
- [Raeth] Support switch packet count debug (/proc/rtxxxx/esw_cnt)
- [Raeth] Support phy register dump
- [Raeth] Re-initialize frame engine if TX timeout occurred
- [WDG] Supprot user and kernel mode watchdog module
- [NVRAM] Support kernel mode nvram
- [Utility] Support iPerf
- [Utility] Support ebtables

WiFi update:

- [RT2860APD] 802.1X daemon update
- [WSCD] WSC daemon update
- [GUI] Support WSC 2.0

Bug fixed:

- [Raeth] Fix ifconfig eth2 down/up crash issue

intigation synthetically and control of the control