

Working TCX1007 replacement using logic IC's - PCB designed for the HX-10P

