

PCB引脚及接线图(PCB Pins and Wiring Diagram)

1.主板引脚图(注: NC代表此处无引脚贴片)


Mainboard Pinout Diagram (Note: NC means no pin patch here)






2.喷头转接板引脚图


Nozzle Adapter Board Pinout Diagram






3.屏幕主板引脚图

Screen Mainboard Pinout Diagram





4.机器接线图

Machine wiring diagram

