Date: 15 07 2025

RRM KAWR

Sub: Clarification regarding Road Learning of HPCT siding.

It has been observed that on certain occasions in recent past, some of the crews assigned duties to HPCT siding refused duty on the plea that having road learning lapsed.

It is clarified herewith that HPCT siding is a part of Thokur station only. Movement to HPCT siding does not involve any block section and no signals in HPCT siding. Moreover, the trains are being piloted in / piloted out from/ to Thokur station by a competent railway servant i.e. on duty Points man. The speed of trains is also restricted to 15 KMPH since non-interlocked points in HPCT siding.

(Rajendra Kumar Sharma) Chief Operations Manager

Copy To: D (O&C) for kind information ED (B&O) for information and n.a. please.