Figuras Artísticas en G-code para CNC

Límite de trabajo:

Eje X: de -175 a 175Eje Y: de -200 a 200

Contenido:

• 13 figuras variadas en G-code

1. Palabra UCE

Letra U
G0 X-150 Y-190 Z50
G0 Y-220
G1 X-150 Y-220 Z-50
G1 X-110 Y-220 Z-50
G1 X-110 Y-220 Z50
; Separación a la letra C corregida
G0 Y-190
G0 X-70 Z50
G0 Y-220

; Letra C simplificada (apertura derecha)

G1 X-30 Y-220 Z50

G1 X-70 Y-220 Z50

G1 X-70 Y-220 Z-50

G1 X-30 Y-220 Z-50

; Separación a la letra E

G0 Y-190

G0 X10 Z50

G0 Y-220

; Letra E

G1 X10 Y-220 Z-50

G1 X50 Y-220 Z-50

G1 X10 Y-220 Z-50

G1 X10 Y-220 Z0

G1 X40 Y-220 Z0

G1 X10 Y-220 Z0

G1 X10 Y-220 Z50

G1 X50 Y-220 Z50

2. Casa

- G0 X-100 Y-190 Z0
- G0 X-50 Y-190 Z-50
- G0 Y-220
- G1 X50 Y-220 Z-50
- G1 X50 Y-220 Z50
- G1 X-50 Y-220 Z50
- G1 X-50 Y-220 Z-50
- G0 Y-190
- G0 X0 Z100
- G0 Y-220
- G1 X-50 Y-220 Z50
- G1 X50 Y-220 Z50
- G1 X0 Y-220 Z100
- G0 Y-190

3. Estrella 5 puntas

- G0 X0 Y-190 Z100
- G0 Y-220
- G1 X38 Y-220 Z31
- G1 X95 Y-220 Z31
- G1 X59 Y-220 Z-12
- G1 X71 Y-220 Z-77
- G1 X0 Y-220 Z-38
- G1 X-71 Y-220 Z-77
- G1 X-59 Y-220 Z-12
- G1 X-95 Y-220 Z31
- G1 X-38 Y-220 Z31
- G1 X0 Y-220 Z100
- G0 Y-190

4. Corazón

- G0 X0 Y-190 Z100
- G0 Y-220
- G1 X0 Y-220 Z100
- G1 X-40 Y-220 Z130
- G1 X-60 Y-220 Z110
- G1 X-65 Y-220 Z60
- G1 X-55 Y-220 Z20
- G1 X-20 Y-220 Z-40
- G1 X0 Y-220 Z-90
- G1 X20 Y-220 Z-40

- G1 X55 Y-220 Z20
- G1 X65 Y-220 Z60
- G1 X60 Y-220 Z110
- G1 X40 Y-220 Z130
- G1 X0 Y-220 Z100
- G0 Y-190

5. Letra C

- G0 X50 Y-190 Z75
- G0 Y-220
- G1 X-50 Y-220 Z75
- G1 X-50 Y-220 Z-75
- G1 X50 Y-220 Z-75
- G1 X50 Y-220 Z-65
- G1 X-40 Y-220 Z-65
- G1 X-40 Y-220 Z65
- G1 X50 Y-220 Z65
- G1 X50 Y-220 Z75
- G0 Y-190
- G0 X0 Z0

6. Cuadrado

- G0 X-50 Y-190 Z-50
- G1 X50 Y-190 Z-50
- G1 X50 Y-190 Z50
- G1 X-50 Y-190 Z50
- G1 X-50 Y-190 Z-50

7. Flecha

- G0 X0 Y-190 Z-60
- G1 X0 Y-190 Z60
- G1 X20 Y-190 Z40
- G1 X0 Y-190 Z60
- G1 X-20 Y-190 Z40

8. Espiral cuadrada

- G0 X-100 Y-190 Z-100
- G1 X100 Y-190 Z-100
- G1 X100 Y-190 Z100
- G1 X-90 Y-190 Z100
- G1 X-90 Y-190 Z-90
- G1 X90 Y-190 Z-90
- G1 X90 Y-190 Z90
- G1 X-80 Y-190 Z90

- G1 X-80 Y-190 Z-80
- G1 X80 Y-190 Z-80
- G1 X80 Y-190 Z80
- G1 X-70 Y-190 Z80
- G1 X-70 Y-190 Z-70
- G1 X70 Y-190 Z-70
- G1 X70 Y-190 Z70
- G1 X-60 Y-190 Z70
- G1 X-60 Y-190 Z-60
- G1 X60 Y-190 Z-60
- G1 X60 Y-190 Z60
- G1 X-50 Y-190 Z60
- G1 X-50 Y-190 Z-50
- G1 X50 Y-190 Z-50
- G1 X50 Y-190 Z50
- G1 X-40 Y-190 Z50
- G1 X-40 Y-190 Z-40
- G1 X40 Y-190 Z-40
- G1 X40 Y-190 Z40
- G1 X-30 Y-190 Z40
- G1 X-30 Y-190 Z-30
- G1 X30 Y-190 Z-30
- G1 X30 Y-190 Z30
- G1 X-20 Y-190 Z30
- G1 X-20 Y-190 Z-20
- G1 X20 Y-190 Z-20
- G1 X20 Y-190 Z20
- G1 X-10 Y-190 Z20
- G1 X-10 Y-190 Z-10
- G1 X10 Y-190 Z-10
- G1 X10 Y-190 Z10

9. Cruz

- G0 X0 Y-190 Z-100
- G1 X0 Y-190 Z100
- G0 X-100 Y-190 Z0
- G1 X100 Y-190 Z0

10. Grafico de barras (3 barras)

- G0 X-120 Y-190 Z-200
- G1 X-120 Y-220 Z-200
- G1 X-100 Y-220 Z-200
- G1 X-100 Y-220 Z-100
- G1 X-120 Y-220 Z-100

- G1 X-120 Y-220 Z-200
- G0 X-50 Y-190 Z-200
- G1 X-50 Y-220 Z-200
- G1 X-30 Y-220 Z-200
- G1 X-30 Y-220 Z0
- G1 X-50 Y-220 Z0
- G1 X-50 Y-220 Z-200
- G0 X30 Y-190 Z-200
- G1 X30 Y-220 Z-200
- G1 X50 Y-220 Z-200
- G1 X50 Y-220 Z75
- G1 X30 Y-220 Z75
- G1 X30 Y-220 Z-200

11. Ventana

- Marco exterior
- G0 X-75 Y-190 Z-75
- G1 X-75 Y-220 Z-75
- G1 X75 Y-220 Z-75
- G1 X75 Y-220 Z75
- G1 X-75 Y-220 Z75
- G1 X-75 Y-220 Z-75
- ; Línea vertical central
- G0 X0 Y-190 Z75
- G1 X0 Y-220 Z75
- G1 X0 Y-220 Z-75
- ; Línea horizontal central
- G0 X-75 Y-190 Z0
- G1 X-75 Y-220 Z0
- G1 X75 Y-220 Z0

12. Letra T

- G0 X-75 Y-190 Z150
- G1 X-75 Y-220 Z150
- G1 X75 Y-220 Z150
- G1 X75 Y-220 Z100
- G1 X25 Y-220 Z100
- G1 X25 Y-220 Z-150
- G1 X-25 Y-220 Z-150
- G1 X-25 Y-220 Z100
- G1 X-75 Y-220 Z100

G1 X-75 Y-220 Z150

13. Letra L

G0 X-100 Y-190 Z-150

G1 X-100 Y-220 Z-150

G1 X-100 Y-220 Z50

G1 X0 Y-220 Z50

G1 X0 Y-220 Z0

G1 X-50 Y-220 Z0

G1 X-50 Y-220 Z-150

G1 X-100 Y-220 Z-150