## **Problem Statement Worksheet - Nordic Sensing**

What could be the cause for the sudden spike in sensor failures from 1-2 % to 15%?



## 1 Context

The cause of the increase in sensor failures is currently unknown, could be because of faulty parts, poor manufacturing, or specific to a particular factory. It is important that we address this issue because we've received 3 large orders from our clients.

## 2 Criteria for success

Employ data science methods such as A, B, and C in order to identify the root cause of the increase in sensor failure rates.

3 Scope of solution space

Results of the data analysis.

## 4 Constraints within solution space

- Chi-squares were not able to provide any insight as to what could be causing the problem
- No leads at all
- Limited data to work with
- 5 Stakeholders to provide key insight
- VP Tony Abraham
- Supervisor Vince
- Manufacturing Gary Neumont
- 6 Key data sources
- Data from Cert