FIJI AIRPORTS	Working Document # OHS 2/2023					
		Non-Compliance		Compliance		Safety Concern
	✓	Non-Conformance		Conformance	(Ti	ick the relevant ox)
Audit Name:	Nadi Airport OHS Annual Audit					
Auditor:	Epeli Leiyamo		F	Risk Level		

♦ Audit Objective #1:

Determine whether Fiji Airports Department buildings meets Emergency Facilities & Procedures requirements.

♦ Test Step #1:

Verify whether FA Building complies with the Emergency Exits, Procedures and Training requirements.

Source Data

- Nadi Aerodrome Manual
- FA OHS Manual
- Site Inspection

Finding

◆ Condition (What is in place?)

Absent of Building Fire Wardens.

There is nil appointed Fire Wardens at following department buildings:

- 1. ASOPS
- 2. Security ground floor
- 3. Arrival Buildings
- 4. FAA Academy
- 5. Nadi Tower
- 6. ATMC building.
- 7. ATM AIS
- 8. ANES building.
- 9. BCW Office building
- 10. HQ/Finance building
- 11. Office 366 building.
- 12. Mechanical Fleet Garage.

◆ Criteria (What should be?)

Appointed persons on Evacuation plan with evacuation procedures during an emergency. Fire warden details on display in appropriate place as stated in the OHS Manual & HASAW(GWC)2003 reg 34 .3a, b, c

- ♦ Effect (So what? /consequences/result)
- Non-Conformance to the requirement
- ◆ Cause (Why the condition exists? /Source?)
- Lack of urgency in highlighting the inadequate equipment with the responsible manager.

Recommendation (How to make it better?)

Create and test 6 monthly with NFA or ARFFS Emergency Evacuation Plan with details of arrangements for evacuation kept on display at the appropriate place

[Department Manager]:

Agree/Disagree: Agree

(If not, why?):

Action Plan: As per recommendation

Target Dates: 30/09/23

72 | Page

Responsible Officer: MARFFS						
Rev No. 2.0	Issue Date: March 2016	Form No: COS001-05				