HOBOware

From labwiki

Uploading data

- 1. Open HOBOware Pro Trial
- 2. Connect the HOBO via it's USB port. When the device is successfully connected "1 device connected will appear in the bottom right hand corner of the window.
- 3. Click on the 'Readout device' icon, found in the top left hand corner (second icon).
- 4. Change the temperature settings from Fahrenheit to Celsius.
- 5. Click 'plot'.
- 6. Save the data.
- 7. Export data as an excel file by clicking the 'Export Table Data' icon on the tool bar. Save the csv. file generated.

Retrieved from "http://ecotheory.uwaterloo.ca/labwiki/index.php?title=HOBOware&oldid=22"

- This page was last modified on 30 April 2014, at 10:55.
- This page has been accessed 33 times.

1 of 1 2021-08-25, 12:18 p.m.