Project Name EXISTING CONDITION PHOTOGRAPHS

Daily Sales Report for 22-Oct-2022

1.							

Top Performing Items

1.

Revenue Bar Chart

S.No.	Item Name	Cost Per Unit	Units Sold	Revenue
1.		image one		





tc for item in processedImages





item.images

tc endfor







ORIGINAL Move sink over 8 inches



Improper office signage



Corridor door should be removed (18 inches minimum pull front approach)







Broken cabinets, no legroom under sink, load center too high




Aisle into kitchen is 28.5 inches



Light switch at 46








18 inches required front pull approach



Damaged pool deck







Protruding stairwell



